



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2100299

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/01/2021
Reference CC6/CTI20004357/Kga3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMJ 3766Y
Insured Veh. SJV 2986H
Claim No. SNM20D201408/C02
Policy No. DMPCSNW00013812000
Accident Date 17/03/2020
Inspection Date 20/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20004357/Kga3q2	
			Date: 14/01/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJV 2986H	Veh. Inspected	SMJ 3766Y	
Policy No.	DMPCSNW00013812000	Coverage (\$)	0.00	
Claim No.	SNM20D201408/C02	Excess (\$)	0.00	
Assign From		Assign Date	20/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GP51338554	Colour	METALLIC PEARL WHITE	
Odometer	103430 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	WANLI	8 mm	
L/H Front Tyre	185/60 R15	WANLI	8 mm	
R/H Rear Tyre	185/60 R15	WANLI	8 mm	
L/H Rear Tyre	185/60 R15	WANLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/03/2020	Inspection Date	20/03/2020	
Survey held at	160 SIN MING IND #05-01			
Repairer	CITY AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 3766Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	517.70	517.70
1	FRONT BUMPER RETAINER -RH	SERVICEABLE	10.40	-
1	RH HEADLAMP	SERVICEABLE	850.10	-
1	RH FOGLAMP COVER	SERVICEABLE	29.00	-
	LESS 20% DISCOUNT		-281.44	-103.54
			1,125.76	414.16
	<u>LABOUR</u>			
	TO CHECK WIRING AND LIGHTING .		60.00	10.00
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.		300.00	200.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		250.00	220.00
			610.00	430.00
	GRAND TOTAL		1,735.76	844.16
	RECOMMENDED COST OF REPAIRS			844.16

Report Ref No. CC6/CTI20004357/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 3766Y

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 3766Y

RE-INSPECTION

