

Date: 23.03.2020
Vehicle No: SLW5547T
Model: MAZDA 3 SEDAN 1.5
Chassis: JM6BN22A8H0166313-2017
Reg.Year: 2018

Third Party Insurer: AIG
Third Party Veh No: SCN3388C
Date of Accident: 19.03.2020

*Not authorized
Resurvey B4 paint 3 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT NOSE PANEL	1		482.60 \$482.60	✗ NN
2	FRONT GRILLE	1		296.40 \$296.40	✓
3	FRONT GRILLE CHROME MOULDING	1		242.60 \$242.60	✓
4	FRONT GRILLE BASE	1		227.60 \$227.60	✗ NN
5	FRONT GRILLE CLIPS	6	\$5.50	33.00 \$33.00	✓
6	FRONT BUMPER LOWER GRILLE SIDE COVER LH	1		74.20 \$74.20	✓
7	FRONT BUMPER	1		1,241.60 \$1,241.60	✓ \$1130
8	FRONT BUMPER CLIPS	10	\$5.80	58.00 \$58.00	✓
SUB TOTAL				\$2,656.00	\$2316.80
LESS 20%				-\$531.20	\$463.36
PARTS TOTAL				\$2,124.80	\$1853.44

*Finalise: Parts: \$1853.44
Labour: \$720
Part by Part: \$2573.44 & 3 days*

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST & REFIX FRONT ACCIDENT AREAS & ETC.	\$500.00	<i>300</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT NOSE PANEL, FRONT BUMPER, FRONT BONNET & ETC.	\$600.00	<i>400</i>
LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$60.00	<i>20</i>
LABOUR TOTAL	\$1,160.00	<i>\$720</i>

TingAn TOTAL \$3,284.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*Finalise:
Parts: \$1945.75
Labour: \$720.00
Part by Part: \$2665.75 . 3 days*

*OC
11/4/2020*