

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004385/UDA3Q2

Date: 03/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900129969

Claimant
Vehicle No : SKL8487H **Insured Vehicle No :** SMN4065J

Date of Loss: 21/03/2020 Nature of Claim: TP Claim No: 7527075453SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL8487H		
Make & Model:	VOLVO S60, 2.0 T (A)	Engine No:	B4204T6212888
Reg. Date:	31/03/2011 (Man. Year: 2010)	Chassis No:	YV1FS445BB2019624
Colour:	White	Odometer:	150684 km
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45Z R17	Rear Tyre Size:	235/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,819.20	5,089.52	9,729.68	65.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	1,170.00	2,880.00	71.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,869.20	6,259.52	12,609.68	66.83
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	18,869.20	5,000.00	13,869.20	73.50
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,636.45		
Global Sum Settlement (S\$)		5,600.00		

INSPECTION

Date of Assignment: 23/03/2020

Date Inspected: 23/03/2020 Inspected At:

Zoom Autowerks Pte Ltd (HQ)
130 Bedok Reservoir Road, Eunos
Spring, #08-1339
Singapore 470130

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Torn	1,665.00 FL	*1,440.62 FL
2	1		*REAR BUMPER CENTRE LOWER GARNISH	Deformed	587.00 FL	*486.40 FL
3	1		*REAR BUMPER CENTRE INNER BRACKET	No such part	275.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	276.00 FL	*- FL
5	1		*REAR BUMPER BRACKET	Not Necessary	176.00 FL	*- FL
6	1		*REAR BUMPER TOW GARNISH	Not Necessary	68.00 FL	*- FL
7	4		*REAR BUMPER SENSOR (ORI)	Shorted (1 PCS ONLY)	1,840.00 FL	*252.00 FL
8	4		*REAR BUMPER SENSOR RING INNER BRACKET	Not Necessary	272.00 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT	Dented	1,495.00 FL	*915.00 FL
10	1		*REAR BUMPER CLIPS	Necessary	80.00 FL	*60.00 FL
11	1		*REAR BOOTLID PANEL	Dented / Bent	2,577.00 FL	*2,251.00 FL
12	1		*REAR BOOTLID LOCK	Not Necessary	590.00 FL	*- FL
13	1		*REAR BOOTLID WEATHERSTRIP	Not Necessary	372.00 FL	*- FL
14	1		*REAR BOOTLID EMBLEM (VOLVO)	Necessary	195.00 FL	*105.00 FL
15	1		*REAR BOOTLID EMBLEM (2.0T)	Necessary	108.00 FL	*80.00 FL
16	1		*REAR BOOTLID EMBLEM (S 60)	Necessary	98.00 FL	*65.00 FL
17	2		*REAR BOOTLID REFLECTOR LAMP	Not Necessary	978.00 FL	*- FL
18	2		*REAR TAILLAMPS	Not Necessary	1,680.00 FL	*- FL
19	1		*REAR TAILLAMPS CLIPS	Not Necessary	20.00 FL	*- FL
20	2		*REAR TAILLAMP LOWER BRACKET	Not Necessary	184.00 FL	*- FL
21	1		*REAR END PANEL	Repair	1,280.00 FL	*- FL
22	1		*REAR END PANEL TOP GARNISH	Not Necessary	495.00 FL	*- FL
23	1		*REAR END PANEL LOCK SENSOR	Not Necessary	457.00 FL	*- FL
24	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	520.00 FL	*- FL
25	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*REAR NUMBER PLATE W/GARNISH	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,448.00	5,655.02
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,628.80	565.50
Total Parts (\$\$)	14,819.20	5,089.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & RENEW AFFECTED ACCIDENT AREAS	New	1,600.00	400.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	600.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL ,REAR INTERIOR TRIMS ,SEAT ,CARPETS TO FACILITATE REPAIRS	New	250.00	60.00
5	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TO FACILITATE REPAIRS	New	250.00	60.00
6	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
7	TO RE-PROGRAMME & RESET DIAGNOSTIC	New	250.00	0.00
8	TO RUST PROOF AFFECTED AREAS	New	100.00	30.00
Gross Labour Cost (\$\$)			4,050.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >