

Estimate

EQ

Your Ref Vehicle No:
(GBG626J-TP)

Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

Date: 23/3/2020
Vehicle No: GBD7642G
Model: TOYOTA DYNA
Date of loss: 20/3/2020
Our ref: LSA317TJS
Year: 2015

Qty	Description	List Price	Remarks
1.00	FRONT BUMPER <i>bt</i>	\$ 485.00	
1.00	FRONT LHS HEADLAMP <i>bro</i>	\$ 1,200.00	
1.00	FRONT HEADLAMP BRACKET <i>? X SVC</i>	\$ 128.00	
1.00	FRONT HEADLAMP LOWER RUBBER <i>cut</i>	\$ 30.00	
1.00	FRONT GRILL <i>cm</i>	\$ 550.00	
1.00	FRONT DYNA ENBLEM <i>ne</i>	\$ 65.00	
1.00	FRONT LHS DOOR <i>bt</i>	\$ 1,600.00	
2.00	FRONT LHS DOOR HINGE <i>X SVC</i>	\$ 190.00	
1.00	FRONT LHS DOOR WHEATHER STRIP <i>ne</i>	\$ 195.00	
1.00	FRONT LHS STEP PANEL <i>sch</i>	\$ 300.00	
1.00	AIR CON CONDENSOR <i>bt</i>	\$ 745.03	
1.00	AIR CON FAN MOTOR <i>X SVC</i>	\$ 320.60	
1.00	AIR COND CONDENSOR METAL BRACKET <i>? X SVC</i>	\$ 480.50	
1.00	REAR LHS TAIL LAMP <i>bro</i>	\$ 220.00	
1.00	REAR LHS TAIL LAMP BRACKET <i>bt</i>	\$ 81.01	
	4855.04	TOTAL: \$ 6,590.14	\$5471.04
	252	LESS 25%: \$ 1,647.53	\$ 1367.76
	3641.28	\$ 4,942.61	\$ 4103.28

SPECIAL NETT ITEMS

Qty	Description	Unit Price	Remarks
1.00	REVERSE SENSOR SET <i>cm</i>	\$ 300.00	
1.00	REAR LHS STAINLESS STEEL DOOR FRAME <i>bt</i>	\$ 2,800.00	
1.00	REAR LHS DOOR PANEL WITH ALL ROUND GASKET <i>cut</i>	\$ 1,500.00	
1pc 2.00	REAR LHS DOOR HINGE <i>cut</i>	\$ 320.00	
1.00	REAR LHS DOOR LOCKING BAR <i>? X SVC</i>	\$ 340.00	
1pc 2.00	REAR RUBBER STOPPER <i>cm</i>	\$ 160.00	
1.00	70KM/H STICKER <i>ne</i>	\$ 15.00	
1.00	COMPANY DETAIL STICKER <i>ne</i>	\$ 30.00	
1.00	REAR LOWER SAFETY BAR <i>bt</i>	\$ 500.00	
1.00	A/C GAS <i>nec</i>	\$ 50.00	
	Total	\$6,045.00	\$5560

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 1,800.00	
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 1,600.00	
1.00	CHECK WIRING	\$ 180.00	
1.00	LABOUR TO REMOVE AND REFIX FRONT LHS DOOR PANEL	\$ 180.00	
1.00	LABOUR TO REMOVE AND REFIX PART OF A/C AND BLEEDING	\$ 150.00	
1.00	LABOUR CHARGE : TO REMOVE AND REFIX FOR REAR BOX DOOR	\$ 2,300.00	
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 200.00	
			1900

Estimate

EQ

Your Ref Vehicle No:
(GBG626J-TP)

Li Sheng Automobile Trading

Please arrange to survey at

Blk K, Pandan Loop #01-16/18 S(128236)

Date: 23/3/2020

Vehicle No: GBD7642G

Model: TOYOTA DYNA

Date of loss: 20/3/2020

Our ref: LSA317TJS

Year: 2015

TOTAL: \$ 6,410.00 \$3900

SUBTOTAL: \$ 17,397.61 \$13563.28

Estimate prepared by: TOH KHAR KIAN

Telephone: 83987469

tohkk_90@hotmail.com

3641.28
2930.00
1900.00
8471.28
208
6777.02
L/S - \$6750

9 days

-28/0 L/S
Resur \$10850.00
Hp 900/10068
9 days
L/S
24/03/2020 @ 1550
Resur after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: