



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2005335
INV Date 30/07/2020
Reference CC4/LPC20004396/R1da3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SDZ 1518H
Insured Veh. SJV 1436K
Claim No. 20/20/20/VP05/023232
Policy No. Z20VP05025764
Accident Date 23/03/2020
Inspection Date 22/06/2020

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20004396/R1da3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 30-07-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------------|----------------|------------|
| Insured Veh. | SJV 1436K | Veh. Inspected | SDZ 1518H |
| Policy No. | Z20VP05025764 | Coverage (\$) | 0.00 |
| Claim No. | 20/20/20/VP05/023232 | Excess (\$) | 0.00 |
| Assign From | ONG LI LI | Assign Date | 23/03/2020 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|---------------------------|--------------|------------|
| Make & Model | INFINITI Q50 2.0T SENSORY | c.c | 1991 |
| Engine No. | HIDDEN | Year of Reg. | 2018 |
| Chassis No. | JN1BCAV37Z0570092 | Colour | BLUE |
| Odometer | 33255 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|-------------|-------------|---------|
| R/H Front Tyre | 225/50 RF18 | BRIDGESTONE | 6 mm |
| L/H Front Tyre | 225/50 RF18 | BRIDGESTONE | 6 mm |
| R/H Rear Tyre | 225/50 RF18 | BRIDGESTONE | 6 mm |
| L/H Rear Tyre | 225/50 RF18 | BRIDGESTONE | 6 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 23/03/2020 | Inspection Date | 22/06/2020 |
| Survey held at | WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103. | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDZ 1518H

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|-------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FACE-RR BUMPER (SN) | DEFORMED | 839.80 | 778.50 |
| 1 | REAR TOW COVER (SN) | CUT | 20.90 | 19.44 |
| 1 | BRACKET-BUMPER RR LH (SN) | SERVICEABLE | 32.30 | - |
| 1 | BRACKET-BUMPER RR RH (SN) | SERVICEABLE | 32.30 | - |
| 1 | BUMPER REAR LH BRACK (SN) | SERVICEABLE | 32.30 | - |
| 1 | BUMPER REAR RH BRACK (SN) | SERVICEABLE | 32.30 | - |
| | | | 989.90 | 797.94 |
| | <u>LABOUR</u> | | | |
| | TO REPLACE REAR BUMPER, TOW COVER, BUMPER BRACKET, ETC. | | 1,800.00 | 900.00 |
| | TO SPRAYPAINT & BLEND ON REAR BUMPER, ETC. | | 1,600.00 | 800.00 |
| | TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES. | | 405.00 | 405.00 |
| | | | 3,805.00 | 2,105.00 |
| | GRAND TOTAL | | 4,794.90 | 2,902.94 |
| RECOMMENDED COST OF REPAIRS | | | | 2,902.94 |

Report Ref No. CC4/LPC20004396/R1da3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDZ 1518H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDZ 1518H

RE-INSPECTION

