

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Paul
4p 90010068

3 days

22/06/2020 @ 1410

Resy before paint

SERVICE ESTIMATE

97795 - C00001 SL: SERVICE SALES - PC

Mr Peter Lim Hee Seng

BLK 259B Compassvale Road
#08-613

Singapore 542259

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 23/03/2020

WIP No. : 15424

Veh.In/Out:

*Tel.No. : Mobile: 98381518

Reg.No. : SDZ1518H

Reg.date : 30/07/2018

Mileage : 0

Chassis No: JN18CAV37Z0570092

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Peter Lim Hee Sen

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, TOW COVER, BUMPER BRACKET, ETC	0	1800.00	0	1,800.00	S 900	
800	TO SPRAYPAINT & BLEND ON REAR BUMPER, ETC	0	1600.00	0	1,600.00	S 800	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	405.00	0	405.00	S	

NOTES DO NOT DEL

FACE-RR BUMPER	1.0 EA	839.80	839.80	S 778.50
REAR TOW COVER	1.0 EA	20.90	20.90	S 19.44
BRACKET-BUMPER RR LH	1.0 EA	32.30	32.30	S
BRACKET-BUMPER RR RH	1.0 EA	32.30	32.30	S
BUMPER REAR LH BRACK	1.0 EA	32.30	32.30	S
BUMPER REAR RH BRACK	1.0 EA	32.30	32.30	S

Gross Total. 4,794.90

Labour Total 3,805.00
Parts Total 989.90
Package Total 0.00

Net..... 4,794.90
GST @ 7.0% 335.64
Total..... 5,130.55
Paid..... 0.00
Please Pay.. 5,130.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X