

# PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

*Not Allowed  
d/s \$4300 /  
Hdys.*

15/04/2020

*Alu. Vic*

Date Of Accident : 19-03-2020

OUR REF : SLT 8311C/T/20

*LKK - Marcue*

THAM WING HONG

23 Bristol Road

*Date In/Out: 24-03-20 to 28/3/20*

Singapore 219848

**ESTIMATE BILL ON VEH. NO. : SLT 8311C**

**MODEL : NISSAN QASHQAI**

**CHASSIS NO. : SJNFBA11U2005028**

**NETT ITEM**

Front Bumper Fascia	614.60	<i>D.S</i> <del>1,934.50</del>
Front Bumper Side Retainer - LH		<i>11</i> 35.20 X
Front Bumper Clips	10pcs @ 2.60	<i>10</i> 26.00 /
Front Bumper Parking SensorGarnish - LH		<i>1</i> 86.40 /
Fog Lamp Bracket		<i>1</i> 57.60 X
Front Fender - LH	685.00	<i>1</i> 753.50 /
Front Fender Wheel Arc Garnish	483.00	<i>D.S</i> 654.00 /
Head Lamp Assy - LH	2961.00	<i>1</i> 3,243.00 /
		6,790.20
	Less Discount 10%:	679.02
		6,111.18

**SPECIAL NETT ITEM**

Front Bumper Parking Sensor - LH		<i>1</i> 294.00 X
Fog Lamp - LH		<i>1</i> 323.70 /

**LABOUR CHARGE**

To Check Wiring System.		<i>20</i> 80.00
To Reset Electrical Module System.		<i>11X</i> 200.00

To Respray Affected Areas.

400 600.00

To Check and Adjust Computer Wheel Alignment.

12 X 120.00

To Renew Damaged Parts, Straighten & Repair & Aligned All Parts.

300 550.00

8,278.88

GST 7%:

579.52

AMOUNT DUE :

8,858.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

p- 4858  
107  
p- 4370.4  
S.W- 323.70  
L- 720.00  
54141  
4331