

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2004-0276	Invoice Number	
Quotation Date	21.04.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$845.00	\$700.00
TO REMOVE & REPLACE ABOVE ITEMS AND REPAIR FRONT RHS PORTION	\$350.00	\$150.00
Total Labour	\$1,195.00	\$850.00

supp

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
RESPRAY MIRROR COVER RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,430.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00
Total Other Costs	\$776.00	\$60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		52115470 50	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace
		52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Check
		52127479 07	COVER, FR BUMPER RH	1.00	\$28.10	25.00	\$21.08	Replace	Replace
		52128479 06	COVER, FR BUMPER LH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given
		52114471 90	BRACKET, FR BUMPER	1.00	\$99.80	25.00	\$74.85	Replace	Replace
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace

CRU
BR
SVC
SCR
SVC
CRU
CRU

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 20/04/2020

User ID PohSuan

		NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	✓	MI
	75310470 60	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.33	Replace	Replace	✓	SCR
	53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Check	✗	
	51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Check	✗	3 SVC
	52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	✓	NEC
	52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check	✓	
	52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check	✓	3 SVC
	52103470 10	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given	✗	
	52102470 20	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given	✗	
	81145476 91	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	✓	CRU
	81210470 20	LAMP ASSY, FOG, RH	0.00	\$910.20	0.00	\$0.00	Replace	Check	✗	3 SVC
	52132470 10	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Check	✗	
	52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Check	✗	
	52535500 60	RETAINER, FR BUMPER, LH & RH	0.00	\$8.50	0.00	\$0.00	Replace	Not Given	✗	
	51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Check	✗	
	51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Check	✗	
	51447470 30	COVER, ENGINE UNDER CENTER	0.00	\$94.50	0.00	\$0.00	Replace	Check	✗	
	51443470 20	COVER, ENGINE UNDER SIDE RH	0.00	\$76.90	0.00	\$0.00	Replace	Check	✗	
	51444470 10	COVER, ENGINE UNDER SIDE LH	0.00	\$76.90	0.00	\$0.00	Replace	Check	✗	
	53101470 80	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	Replace	✓	CRU
	53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	25.00	\$699.83	Replace	Replace	✓	DD
	53802471 00	FENDER SUB-ASSY, FR, LH	0.00	\$933.10	0.00	\$0.00	Replace	Not Given	✗	3 SVC
	53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given	✗	
	53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Not Given	✗	
	53301471 10	HOOD SUB-ASSY	1.00	\$938.40	25.00	\$703.80	Replace	Replace	✓	CRU
	53205479 00	SUPPORT S/A UPPER,	0.00	\$364.90	0.00	\$0.00	Replace	Check	✗	SVC
	53202479 01	SUPPORT S/A RH	1.00	\$237.00	100.00	\$0.00	Replace	Repair	✓	
	53203479 01	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given	✗	3 SVC
	53028470 10	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Not Given	✗	
	53213470 50	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Not Given	✗	
	53214470 50	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Not Given	✗	
	53851470 61	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	✗	
	53852470 41	PAD, FR WHEEL LH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	✗	
	53410471 30	HINGE ASSY, HOOD, RH	1.00	\$57.00	25.00	\$42.75	Replace	Replace	✓	BT
	53420471 30	HINGE ASSY, HOOD, LH	1.00	\$57.00	25.00	\$42.75	Replace	Replace	✓	BT
	53807470 20	SEAL SUB-ASSY, RH	0.00	\$50.20	0.00	\$0.00	Replace	Not Given	✗	3 SVC
	53827470 50	PROTECTOR, FR FENDER RH	0.00	\$90.40	0.00	\$0.00	Replace	Check	✗	
	75535470 20	MOULDING RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given	✗	
	67001471 52	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair	✓	
		STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓	NEC
	87910474 50	MIRROR ASSY, OUTER REAR VIEW, RH	0.00	\$1,373.50	0.00	\$0.00	Replace	Not Given	✗	SVC
	87915470 70A1	COVER, OUTER MIRROR, RH	0.00	\$89.50	0.00	\$0.00	Replace	Not Given	✗	SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 03685592
Estimator Telephone Number 88662623
Accident Reporting Number 68662672

Date Generated : 20/04/2020
User ID : PohSuan

42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
Total			\$16,843.04		\$4,765.66		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		5202147110	REINFORCEMENT FRONT UPPER	1.00	\$691.10	25.00	\$518.33	Replace	Replace
		5261147140	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.73	Replace	Replace
		8121047020	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace
		5320547900	SUPPORT S/A UPPER	1.00	\$364.90	25.00	\$273.68	Replace	Replace
		5320247901	SUPPORT S/A RH	1.00	\$237.00	25.00	\$177.75	Replace	Replace
		5321347050	SUPPORT, RADIATOR UPPER RH	1.00	\$76.70	25.00	\$57.53	Replace	Replace
		8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1.00	\$486.40	10.00	\$437.76	Replace	Replace
Total					2,836.60		2,336.96		

3 SVC

BT
CR4
CRA
BT
BT
BT
Short

7102.62 /
+ 850.00 /
+ 860.00 /
8812.62 /

p/p 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____