



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD

1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV No. AC2101310

INV Date 04/03/2021

Reference CC3/QBE20004406/Qpa3q2

Code QBE

PROFESSIONAL SERVICE FEE

Vehicle No. SHF 206Y
Insured Veh. SKJ 6052C
Claim No. VC013594
Policy No. 8-V0017400-MVA-R001
Accident Date 19/03/2020
Inspection Date 23/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC3/QBE20004406/Qpa3q2	
			Date: 04/03/2021	
			Code: QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKJ 6052C	Veh. Inspected	SHF 206Y	
Policy No.	8-V0017400-MVA-R001	Coverage (\$)	0.00	
Claim No.	VC013594	Excess (\$)	0.00	
Assign From		Assign Date	23/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU403576316	Colour	MAROON	
Odometer	213401 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/03/2020	Inspection Date	23/03/2020	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 206Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER, FR BUMPER (DISC 25%)	CRUSHED	495.50	371.63
1	EXTENSION SUB-ASSY, LH	SERVICEABLE	116.30	-
1	SUPPORT, FR BUMPER RH (DISC 25%)	BROKEN	76.90	57.68
1	COVER, FR BUMPER RH	SCRATCHED	28.10	21.08
1	BRACKET, FR BUMPER (DISC 25%)	CRUSHED	99.80	74.85
1	EMBLEM ASSY FRONT (DISC 25%)	SCRATCHED	87.10	65.33
10	CLIPS PIECE, FRT & RR BUMPER @ \$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	GRILLE SUB-ASSY (DISC 25%)	CRUSHED	335.60	251.70
1	FENDER SUB-ASSY, FR, RH (DISC 25%)	DENTED	933.10	699.83
1	HOOD SUB-ASSY (DISC 25%)	CRUSHED	938.40	703.80
1	HINGE ASSY, HOOD, RH (DISC 25%)	BENT	57.00	42.75
1	HINGE ASSY, HOOD, LH (DISC 25%)	BENT	57.00	42.75
1	UNIT, HEADLAMP, RH (DISC 10%)	CRUSHED	2,558.90	2,303.01
1	NUMBER PLATE FRAME (SN)	CRUSHED	25.00	25.00
1	NUMBER PLATE (SN)	MISSING	35.00	35.00
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	SUPPORT, FR BUMPER LH	SERVICEABLE	82.30	-
1	COVER, FR BUMPER LH	SERVICEABLE	28.10	-
1	GRILLE, RADIATOR	SERVICEABLE	165.00	-
1	COVER ASSY, ENGINE	SERVICEABLE	180.10	-
1	REINFORCEMENT FRONT UPPER	SERVICEABLE	691.10	-
1	ABSORBER, FR BUMPER	SERVICEABLE	70.30	-
1	EXTENSION SUB-ASSY, RH	SERVICEABLE	116.30	-
1	LAMP ASSY, FOG, RH	SERVICEABLE	910.20	-
1	REINFORCEMENT FRONT LOWER	SERVICEABLE	238.50	-
1	ABSORBER, FR BUMPER LOWER	SERVICEABLE	117.00	-
1	RETAINER, FR BUMPER, LH & RH	SERVICEABLE	8.50	-
1	COVER ASSY, ENGINE	SERVICEABLE	180.10	-
1	COVER ASSY, ENGINE UNDER CENTER SET	SERVICEABLE	452.80	-
1	COVER, ENGINE UNDER CENTER	SERVICEABLE	94.50	-
1	COVER, ENGINE UNDER SIDE RH	SERVICEABLE	76.90	-

Report Ref No. CC3/QBE20004406/Qpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COVER, ENGINE UNDER SIDE LH	SERVICEABLE	76.90	-
1	FENDER SUB-ASSY, FR, LH	SERVICEABLE	933.10	-
1	LINER, FR FENDER, RH	SERVICEABLE	198.40	-
1	LINER, FR FENDER, LH	SERVICEABLE	194.30	-
1	SUPPORT S/A UPPER,	SERVICEABLE	364.90	-
1	SUPPPORT S/A LH	SERVICEABLE	237.00	-
1	SUPPORT SUB-ASSY LOWER	SERVICEABLE	397.40	-
1	SUPPORT, RADIATOR UPPER RH	SERVICEABLE	76.70	-
1	SUPPORT, RADIATOR UPPER LH	SERVICEABLE	76.70	-
1	PAD, FR WHEEL RH	SERVICEABLE	57.70	-
1	PAD, FR WHEEL LH	SERVICEABLE	57.70	-
1	SEAL SUB-ASSY, RH	SERVICEABLE	50.20	-
1	PROTECTOR, FR FENDER RH	SERVICEABLE	90.40	-
1	MOULDING RH	SERVICEABLE	83.30	-
1	PANEL SUB-ASSY, FRONT DOOR RH	SERVICEABLE	1,249.60	-
1	MIRROR ASSY, OUTER REAR VIEW, RH	SERVICEABLE	1,373.50	-
1	COVER, OUTER MIRROR, RH	SERVICEABLE	89.50	-
1	WHEEL, DISC FRONT	SERVICEABLE	1,555.10	-
1	TYRE	SERVICEABLE	126.74	-
1	SUPPORT S/A RH	TO REPAIR SEE LABOUR	237.00	-
1	REINFORCEMENT FRONT UPPER (DISC 25%) (ADDITIONAL)	BENT	691.10	518.33
1	ABSORBER, FR BUMPER (DISC 25%) (ADDITIONAL)	CRUSHED	70.30	52.73
1	SUPPORT S/A UPPER (DISC 25%) (ADDITIONAL)	BENT	364.90	273.68
1	SUPPORT S/A RH (DISC 25%) (ADDITIONAL)	BENT	237.00	177.75
1	SUPPORT, RADIATOR UPPER RH (DISC 25%) (ADDITIONAL)	BENT	76.70	57.53
1	LAMP ASSY, FOG, RH (DISC 10%) (ADDITIONAL)	CRACKED	910.20	819.18
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1 (DISC 10%) (ADDITIONAL)	SHORTED	486.40	437.76
			19,693.14	7,102.62
	<u>LABOUR</u>			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF SUPPORT S/A RH.		1,195.00	850.00

Report Ref No. CC3/QBE20004406/Qpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT.		2,430.00	800.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX WING MIRROR.	NOT NECESSARY	120.00	-
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TOWING CHARGE.		56.00	40.00
			4,401.00	1,710.00
GRAND TOTAL			24,094.14	8,812.62
RECOMMENDED COST OF REPAIRS				8,812.62

Report Ref No. CC3/QBE20004406/Qpa3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 206Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 206Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

