

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

24th March 2020

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TP China
Vic

GB71079113

Accident date: 23th MARCH 2020

Estimated repair costs for vehicle no: SML4771P HONDA FREED 1.5G 2019

S/n	Qty	Items	U/price	Amount	
1	1	Rear boot lid Distorted.		\$1,350.00	1180
2	2	Rear Boot Lid hinges xle new	\$155.20	\$310.40	x
3	1	Rear boot lid rubber lt		\$205.00	✓
4	1	Rear Boot Lid inner trim Canted.		\$680.00	288
5	1	boot lid inner lock Dented		\$203.10	✓
6	1	rear boot lid shock absorber-RH xle new		\$210.00	x
7	8	Rear boot lid center garnish clips xle new	\$5.50	\$44.00	20
8	1	Rear boot lid centre garnish lt		\$285.10	✓
9	1	Rear boot lid emble logo		\$60.00	✓
10	1	Rear Boot Lid FREED logo		\$40.00	✓
11	1	Rear Boot Lid Hybrid logo		\$48.00	✓
12	1	rear Boot Lid wiper lt		\$112.00	✓
13	1	rear boot Lid wiper motor Dented		\$325.00	✓
14	2	Rear Boot Lid side reflector lt	\$375.00	\$750.00	✓
15	1	REAR Boot Lid Windscreen Shattered		\$1,250.00	1055
16	1	Rear Boot Lid Windscreen Seal		\$138.20	✓
17	1	rear windscreen moulding		\$258.20	✓
18	2	Rear Number Plate lamp	\$58.00	\$116.00	x
19	1	Rear Number Plate		\$50.00	x
20	2	Rear Bumper side reflector	\$83.10	\$166.20	x
21	1	Rear bumper Dented		\$1,358.00	921
22	2	Rear bumper side bracket xle new	\$112.00	\$224.00	x
23	2	rear bumper side retainer xle new	\$105.20	\$210.40	76
24	8	Rear bumper clips	\$5.00	\$40.00	✓
25	1	Rear Bumper Reverse Sensor Dented		\$300.00	200(SN)
26	2	Rear tail lamp LH lt, RH Canted	\$580.00	\$1,160.00	✓
27	1	Rear end panel Dented		\$740.00	528
28	1	Rear end Panel top garnish Dented		\$284.00	✓
29	1	Spare Tyre Panel top cover xle new		\$485.00	x
30	1	Rear spare tyre panel sealant		\$220.00	x
31	2	Rear Fender Inner Trim Board LH Canted	\$386.10	\$772.20	38610
32	10	Rear fender inner trim board clips	\$5.00	\$50.00	30

Subtotal :- \$12,444.80

839770

671816 S.N: 200

Labour charges

Remove / refix rear windscreen

\$120.00 ✓

gum

\$50.00 ✓

remove / refix rear cushion

\$120.00 60

Remove / refix rear reverse sensor

\$100.00 50

Tuff kote

\$120.00 60

To Check Wiring System

\$60.00 30

Panel beating

\$1,000.00 800

Spray painting charges

\$1,000.00 800

\$2,570.00

Total:-

\$15,014.80

total: 8888 16

h/s: 7.11K

07 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: