

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

TP/MSIG

GBC9057M

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department \ THE MOTOR

Estimate No: ES2090322

Date: 01 Apr 2020

Policy No: DMCVSNA00011132004

Veh Reg No: GBC9057M

Make/Model: NISSAN CABSTAR 3.0
5MT

Chassis No: JN1SC2F24Z0855472

Engine No: ZD30334874K

Reg. Date: 07/03/2014

WS Ref: TP-MSIG

Claim Type: Third Party

Accident Date: 19/03/2020

TP Veh Reg No: YN7773L

Estimate Repair Cost to Vehicle No: GBC9057M

Description	U/Price	Quantity	List Price	Amount
Net Price			SS	SS
1 FRONT PANEL	1,580.90	1 PC	1,580.90	—
2 FRONT PANEL EMBLEM 'CABSTAR'	36.10	1 PC	36.10	—
3 FRONT WIPER PANEL	525.30	1 PC	525.30	—
4 FRONT GRILLE	461.90	1 PC	461.90	—
5 FRONT GRILLE LOGO	59.60	1 PC	59.60	—
6 FRONT GRILLE CLIPS	4.50	4 PCS	18.00	—
7 FRONT WINDSCREEN MOULDING	364.30	1 PC	364.30	—
8 FRONT WINDSCREEN INNER SEAL	103.50	1 PC	103.50	3000
9 RH HEADLAMP	684.90	1 PC	684.90	—
			3,834.50	
	Less 10%		383.45	3,451.05
Special Net				
10 FRONT WIPER LINKAGE	151.50	1 PC	151.50	2 X
11 FRONT WINDSCREEN GUM	40.00	1 PC	40.00	—
12 ERP BRACKET	25.00	1 PC	25.00	—
			216.50	216.50
Labour				
13 REMOVE AND REFIX FRONT WINDSCREEN GLASS	120.00	1 LA	120.00	—
14 REMOVE AND REFIX DASHBOARD, METER ASSY, AND CHECK WIRING	200.00	1 LA	200.00	—
15 REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	100.00	1 LA	100.00	—
16 REMOVE AND REFIX FRONT GRILLE, HEADLAMPS, WIPER ASSY. TO CUTTING, WELDING AND RENEW FRONT PANEL, WIPER PANEL AND REALIGN THE SAME	800.00	1 LA	800.00	600
17 PUTTY AND RESPRAY ON FRONT WIPER PANEL, FRONT PANEL, FRONT GRILLE	800.00	1 LA	800.00	580
18 RUSTPROOFING	30.00	1 LA	30.00	—
			2,050.00	2,050.00

Total

SS 5,717.55

Add GST @ 7%

400.23

Total Amount Payable

SS 6,117.78

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

43731N
 373.10
 43357.90
 30 SN
 65 SN
 1630
 45082.90

45082.90