

REC. BY:

REF: C72 / CS / C11 2006 4421 / K+d3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5-6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKW 74006 Yr Regn: 11.15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Wish

c.c.

1798

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

115552

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDGG20W60J003196

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195 / 65 R 15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

21/3/20

D.O.I.

24/3/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/4 1/2 hr @ 4200 email & confirm

u/Time, File Pass to?



: Prel. Report



: Final Report

/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

ort Format :

o Sum / L.B.I: (\$

Not Authorized
 C1 Bump & 4200ch
 Resurvey After Paint

IG KHIM THYE ALLEN
 Ang Mo Kio St 63
 Block B
 Singapore 569116

5 days

Our Ref : TP 2003
 Date : 24/3/2020
 No of Page : 1/2

Registration No : SKW7400G
 Accident Date : 21-Mar-20

Model : Toyota Wish
 Chassis No: JTDGG20W60J003196

/No	Qty	Items	Unit Price	Amount
1	1	Tailgate	\$ 1,230.40	\$ 1,230.40 ✓
2	2	Tailgate Hinge	\$ 60.90	\$ 121.80 X
3	2	Tailgate Absorber	\$ 210.80	\$ 421.60 ✓
4	2	Tailgate Stopper (big)	\$ 9.80	\$ 19.60 X
5	2	Tailgate Stopper (small)	\$ 8.60	\$ 17.20 ✓
7	1	Tailgate Garnish	\$ 280.90	\$ 280.90 X
8	2	Tailgate Garnish side	\$ 320.10	\$ 640.20 X
9	1	Tailgate Garnish Center	\$ 460.70	\$ 460.70 X
10	1	Tailgate Weatherstrip	\$ 279.80	\$ 279.80 508in
11	1	Tailgate Lock	\$ 187.50	\$ 187.50 X
13	1	Tailgate Chrome Moulding	\$ 280.00	\$ 280.00 ✓
14	1	Emblem "Elegance"	\$ 95.30	\$ 95.30 —
15	1	Emblem "Valve Metic"	\$ 90.40	\$ 90.40 —
16	1	Emblem "Toyota" Logo	\$ 90.50	\$ 90.50 —
17	1	Rear Wiper	\$ 43.20	\$ 43.20 X
18	1	Rear Wiper Blade	\$ 76.50	\$ 76.50 X
20	1	Rear Wiper Motor	\$ 481.30	\$ 481.30 ✓
21	1	Rear Wiper Bracket	\$ 53.40	\$ 53.40 X
22	2	Tail Lamp LED (Body)	\$ 363.20	\$ 726.40 ✓
23	2	Tail Lamp LED (Tailgate)	\$ 350.40	\$ 700.80 ✓
24	1	Rear Bumper 584.70	\$ 690.90	\$ 690.90 ✓
26	2	Rear Bumper reflector	\$ 66.70	\$ 133.40 X
27	2	Rear Bumper Retainer	\$ 80.40	\$ 160.80 ✓
28	1	Rear Reinforcement	\$ 430.30	\$ 430.30 X
29	1	Rear End Panel	\$ 528.40	\$ 528.40 ✓
30	1	Rear End Panel Garnish 281.30	\$ 371.80	\$ 371.80 ✓
31	2	Rear Fender Shield	\$ 180.60	\$ 361.20 X
				\$ 8,974.30
				-25% \$ 2,243.58
Total for spare parts				\$ 6,730.73

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ENG KHIM THYE ALLEN
14 Ang Mo Kio St 63
Block B
Singapore 569116

Our Ref : TP 2003
Date : 24/3/2020
No of Page : 2/2

Registration No : SKW7400G
Accident Date : 21-Mar-20

Model : Toyota Wish
Chassis No: JTDGG20W60J003196

S/No	Qty	Items	Unit Price	Amount
Special Nett				
1	16	Tail Gate Garnish Clips	\$ 5.00	\$ 80.00 x
2	6	Tail Gate Chrome Moulding Clips	\$ 8.00	\$ 48.00 ✓
3	1set	Rear Windscreen Sealant	\$ 60.00	\$ 60.00 2000
4	6	Rear End Panel Garnish Clips	\$ 5.00	\$ 30.00 ✓
5	1set	Parking Sensor	\$ 200.00	\$ 200.00 x
6	12	Rear Fender shield clips	\$ 5.00	\$ 60.00 x
Total for SP			\$	478.00
Sub-Total for Parts :			\$	7,208.73

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.		1,200.00 600l
2		To putty and spray paint on all accident damage parts and other accident affected areas		900.00 660l
3		To check wiring system to facilitate repair and refit the same		120.00 20l
4		To remove and transfer windscreen		160.00 120l
5		Water Proofing test		80.00 30l
6		Apply Anti Rust		120.00 60l
7		To remove and refit reverse sensor		120.00 50l

TOTAL AMOUNT : 2,700.00
OVERALL COST : 9,908.73