

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004426/UBA3Q2

Date: 12/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993943

Claimant
Vehicle No : SGD2929D **Insured Vehicle No :** ET3633P

Date of Loss: 20/03/2020 Nature of Claim: TP Claim No: 1179878316SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGD2929D**

Make & Model: NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A) Engine No: HR15371476C

Reg. Date: 28/08/2012 (Man. Year: 2012) Chassis No: JN1BAAG11Z0151106

Colour: Maroon Odometer: 115351 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,129.30	1,035.00	2,094.30	66.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	680.00	1,860.00	73.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,669.30	1,715.00	3,954.30	69.75
Approved Total (Overridden) (S\$)		1,350.00		
Nett Amount (S\$)	5,669.30	1,350.00	4,319.30	76.19
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		1,986.45		
Global Sum Settlement (S\$)		1,900.00		

INSPECTION

Date of Assignment: 24/03/2020

Date Inspected: 24/03/2020 Inspected At:

Zoom Autowerks Pte Ltd (HQ)
130 Bedok Reservoir Road, Eunos
Spring, #08-1339
Singapore 470130

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	985.00 FL	*985.00 FL
2	1		*REAR RH DOOR PROTECTOR	Necessary	215.00 FL	*165.00 FL
3	1		*REAR RH DOOR PROTECTOR CLIPS	Not Necessary	25.00 FL	*- FL
4	1		*REAR RH DOOR WEATHER STRIP	Not Necessary	325.00 FL	*- FL
5	1		*REAR RH DOOR INNER TRIMBOARD	Not Necessary	475.00 FL	*- FL
6	1		*REAR RH DOOR INNER TRIMBOARD CLIPS	Not Necessary	40.00 FL	*- FL
7	1		*REAR RH DOOR TOP HINGE	Not Necessary	86.00 FL	*- FL
8	1		*REAR RH DOOR LOWER HINGE	Not Necessary	86.00 FL	*- FL
9	1		*REAR RH DOOR GLASS OUTER CHANNEL	Not Necessary	295.00 FL	*- FL
10	1		*REAR RH DOOR GLASS REGULATOR ASSY	Not Necessary	525.00 FL	*- FL
11	1		*REAR RH DOOR LOCK ASSY	Not Necessary	420.00 FL	*- FL
12	1		*RIGHT ROCKER PANEL (NPA)	Not Necessary	0.00 FL	*- FL
13	1		*REAR RH FENDER (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,477.00	1,150.00
- List Item Discount on L Items 10.00/10.00% (\$)	347.70	115.00

Total Parts (\$)	3,129.30	1,035.00
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,000.00	200.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	900.00	400.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	40.00	0.00
4	TO RENEW & RECONNECT REAR RH DOOR COMPONENTS	New	200.00	50.00
5	TO CONDUCT WHEEL ALIGNMENT	New	200.00	0.00
6	TO RUST PROOF AFFECTED AREAS	New	200.00	30.00
Gross Labour Cost (\$\$)			2,540.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >