

Lkk: Khanchana.



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunus Spring
#08-1339 Singapore 470130
Tel: 9450 7920
zoomautowerks@gmail.com

Car Number: GBJ8136M

Date: 11/04/2020

Model: TOYOTA DYNA

Damaged Area: (Rear Portion Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Parts / Material :

		Quantity		
1	Rear Tailgate	1465.60	DD/serf	\$ 1,945.20 ✓
2	Rear Tailgate Latch		\$195.00 X 2 pcs	\$ 390.00 X
3	Rear Tailgate Side Member with Rubber	179 N/s bent	\$268.00 X 2 pcs	\$ 536.00 1PC
4	Rear Tailgate Hinges		\$68.00 X 2 pcs	\$ 136.00 X
5	Rear Tailgate Lower Member		serf	\$ 749.40 ✓
6	Taillamps	339.70	N/scm	\$325.00 X 2 pcs \$ 750.00 1PC
7	Taillamps Bracket		N/s bent	\$119.20 X 2 pcs \$ 238.40 1PC
8	Rear Number Plate Bracket		serf	\$ 155.00 ✓
9	Rear Number Plate Lamp		11	\$ 175.00 X
10	Rear Tyre Carrier		17	\$ 385.00 X
			Parts :	\$ 5,460.00
			Less Parts 25% :	\$ 1,365.00
			Total Parts :	\$ 4,095.00

Special Net Items :

Rear Tailgate Sticker (TOYOTA)	ru	\$ 175.00 110
Rear Dyna Sticker	ru	\$ 70.00 45
70 KM/H Sticker	ru	\$ 35.00 10
Rear Side Gate Advertisement Sticker	ru	\$ 650.00 X
Reverse Sensor	short	\$ 280.00 200
Rear Number Plate	serf	\$ 35.00 15
Total S/N Parts :		\$ 1,245.00

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$ 1,200.00 850
To Putty, Spray Paint on Affected Accident Areas	\$ 1,000.00 600
To Check & Re-Connect all electrical wiring	\$ 50.00 20
To Rust Proof Affected Areas	\$ 200.00 50
Total Labour :	\$ 2,450.00

TOTAL PARTS :	\$ 4,095.00
TOTAL SPECIAL NET ITEM :	\$ 1,245.00
TOTAL LABOUR :	\$ 2,450.00
TOTAL REPAIR COST :	\$ 7,790.00

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM:

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT approval from Insurance Company

FINALISED AMOUNT :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Acknowledged by Repairer
Signature:

Not Authorized
date 4/5 = 3300 / 4 days.

P-3007.9
252
P-2255.92
S-2-380.00
L-1520.00
4155.92
3324.