

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33717

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0317/2020/NS
Date : 23-Mar-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

We took 6 days exclude 1 Sunday

jb 8 Jun 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Sandeep Hooda
Address : 4 Simei Rise
#07-10
Singapore 528801
Telephone : HP +65 86616070
Type of Claim : Own Damage Claims
Policy No. : 1900094067
Vehicle No : **SML 216 C**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Apr-19
Engine No : CVK 077057
Chassis No : WAUZZZF42KA040554
Mileage : 7512
Date In : 23-Mar-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Mar-20
Place of Accident : Changi South Avenue 1 Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SML 216 C

S/N	Nature of Jobs		Estimated Charges		Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer Assy and front parking aid.	S/N \$	480.00	\$	480.00
2	To remove and renew aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	\$	1,200.00
3	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror Assy.	S/N	350	\$	300.00
4	To renew rhs wheel suspension Assy with subframe. To inspect for further damages.	S/N \$	2,400.00	\$	2,400.00
5	To dismantle and renew front bumper, bonnet and both headlights. To repair rhs front fender. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	5,250.00	\$	2,750.00
6	To respray front bumper, rhs front fender, bonnet, hinges, rhs front door and rhs sill panel.	\$	4,400.00	\$	2,750.00
7	To carry out pre-wheel alignment and post wheel alignment.	S/N \$	520.00	\$	480.00
7a	Towing and tyre replacement - owner	S/N \$	350.00	\$	350.00
	To carry out diagnostic check.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 15,142.00	\$	10,902.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 216 C

S/N	Parts Description	Damage Parts & Prices		
		S/Nett	Remarks	
1	FRONT BUMPER	\$ 2,068.00	\$	1,654.40
2	FRONT BUMPER FIXING PARTS	\$ 553.00		
3	FRONT BUMPER SECURING STRIP	2 \$ 67.00	\$	52.96
4	FRONT BUMPER GRILLE CENTRE	\$ 185.00	\$	147.60
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 198.00	\$	158.00
6	FRONT BUMPER AIR GUIDE - LH / RH	2 \$ 118.00		
7	RADIATOR GRILLE	\$ 1,254.00	\$	1,003.20
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 254.00		
9	FRONT BUMPER CARRIER	\$ 757.00	\$	605.20
10	FRONT BUMPER FOAM FILLER PIECE	\$ 117.00	\$	93.60
11	FRONT BUMPER COVER	\$ 120.00	\$	96.00
12	CAUTION SIGN STICKER	NEC \$ 13.00	\$	10.24
13	AIRCON STICKER	NEC \$ 7.00		
14	LOCK CARRIER BRACKET	\$ 129.00		
15	FRONT BUMPER SUPPORT - LH / RH	2 \$ 54.00		
16	HORN - LH HIGH TONE	\$ 38.00		
17	HORN - RH LOW TONE	\$ 270.00		
18	SPRING SHACKLE - LH / RH	2 \$ 54.00		
19	FRONT PARKING AID SENSOR - INNER / OUTER	2 TBC		
20	FRONT PARKING AID SEAL RING	4 \$ 14.00		
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,270.00	\$ 3,821.20

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 216 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
			<i>C/F</i> \$ 3,821.20
21	BONNET	\$ 2,634.00	\$ 2,107.20
22	BONNET ATTACHMENT PARTS	\$ 388.00	
23	BONNET LID HINGE - LH / RH	2 \$ 574.00	
24	BONNET IMPACT PROTECTION - CENTRE	\$ 26.00	\$ 20.80
25	BONNET IMPACT PROTECTION - LH / RH	2 \$ 52.00	\$ 41.12
26	BONNET GAS FILLED STRUT	2 \$ 224.00	
27	BONNET STRIKER - LH / RH	2 \$ 94.00	
28	BONNET LID LOCK	2 \$ 403.00	
29	BONNET BOWDEN CABLE - CENTRE	\$ 54.00	
30	BONNET BOWDEN CABLE	\$ 54.00	
31	BONNET RELEASE LEVER	\$ 13.00	
32	BONNET SOUND ABSORBER	\$ 323.00	
33	LED HEADLIGHT - LH / RH	2 \$ 14,642.00	
34	LIFT CYLINDER - LH / RH	2 \$ 396.00	
35	LIFT CYLINDER CORRUGATED PIPE	\$ 88.00	
36	LOCK CARRIER	\$ 956.00	\$ 764.40
37	COLLANT REGULATOR SUPPORT	2 \$ 71.00	
38	AIRCON CONDENSER	\$ 586.00	
39	CHARGE AIR COOLER	\$ 552.00	\$ 441.20
40	CHARGE AIR COOLER PRESSURE HOSE - RH	\$ 336.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 22,466.00	\$ 7,195.92

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 216 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
	<i>C/F</i>		<i>\$ 7,195.92</i>
41	CHARGE AIR COOLER PRESSURE PIPE	\$ 402.00	<i>\$ 612.40</i>
42	RADIATOR	\$ 766.00	<i>\$ 134.72</i>
43	READY MIX COOLANT	\$ 169.00	
44	RADIATOR FAN RING	\$ 240.00	
45	RADIATOR FAN	\$ 1,877.00	
46	RADIATOR AIR GUIDE - LH / RH	2 \$ 54.00	<i>\$ 21.04</i>
47	RADIATOR AIR GUIDE - LH / RH	2 \$ 24.00	
48	RADIATOR AIR GUIDE - UPPER	\$ 15.00	
49	RADIATOR AIR GUIDE - LOWER	\$ 21.00	
50	AIR INTAKE AIR DUCT - RH	\$ 21.00	
51	AIR INTAKE AIR FILTER	\$ 362.00	
52	AIR INTAKE AIR GUIDE	\$ 50.00	
53	AIR INTAKE AIR MASS METRE	\$ 546.00	
54	FRONT BUMPER GUIDE SECTION - RH	\$ 36.00	
55	NOISE INSULATION	\$ 537.00	<i>\$ 429.60</i>
56	FRONT ALUMINIUM RIM - RH	\$ 652.00	<i>\$ 521.20</i>
57	SUPPORT FRAME	\$ 3,096.00	
58	FRONT WISHBONE LINK - RH	\$ 507.00	<i>\$ 405.20</i>
59	FRONT SUSPENSION GUIDE - RH	\$ 887.00	<i>\$ 709.60</i>
60	UPPER CONTROL ARM - RH	\$ 480.00	<i>\$ 384.00</i>
SUB TOTAL SPARE PARTS CHARGES :		\$ 10,742.00	<i>\$ 10,413.68</i>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 216 C

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
	<i>C/F</i>			<i>\$ 10,413.60</i>
61	REAR UPPER CONTROL ARM - RH UPPER	\$	480.00	<i>\$ 384.00</i>
62	WHEEL BEARING HOUSING - RH	\$	912.00	<i>\$ 729.60</i>
63	SWIVEL JOINT	\$	182.00	<i>\$ 145.60</i>
64	WHEEL HUB	\$	460.00	<i>\$ 368.00</i>
65	SUSPENSION FORKS - RH	\$	249.00	
66	COUPLING ROD	2	TBC	
67	DRIVE SHAFT	\$	2,498.00	
68	GAS SHOCK ABSORBER	\$	284.00	
69	TRACK ROD	\$	93.00	
70	STEERING GEAR GREASE	\$	41.00	
71	TIE ROD END	\$	186.00	<i>\$ 148.40</i>
72	DOUBLE ANGLE BALL BEARING	\$	237.00	<i>\$ 189.60</i>
73	REAR NOISE INSULATION	\$	371.00	<i>\$ 296.40</i>
74	CENTRE UNDERBODY TRIM AIR GUIDE - RH		TBC	
75	FRONT UNDERBODY TRIM - LH	\$	40.00	
76	UNDERBODY TRIM	\$	305.00	<i>\$ 243.60</i>
77	REAR UNDERBODY TRIM - RH	\$	125.00	<i>\$ 99.60</i>
78	FUEL TANK TRIM	\$	59.00	<i>\$ 46.56</i>
79	REAR SUSPENSION COVER STONE CHIP GUARD - RH	\$	42.00	<i>\$ 33.20</i>
80	FRONT TYRE - RH		TBC	<i>\$ 150.00</i>
81	FRONT NO PLATE	S/N \$	60.00	<i>\$ 60.00</i>
81A	ADDED PARTS - SEE ATTACHED	\$	69.00	<i>\$ 55.04</i>
82	SUNDRIES	\$	400.00	<i>\$ 105.60</i>
TOTAL SPARE PARTS CHARGES		:	\$ 46,571.00	<i>\$ 13,468.80</i>
TOTAL LABOUR CHARGES		:	\$ 15,142.00	<i>\$ 10,902.00</i>
GRAND TOTAL		:	\$ 61,713.00	<i>\$ 24,370.80</i>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Department Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0317/2020/RT 2-Apr-20 Raymond Ting 1 of 1 SML 216 C Audi A4 Sedan 2.0 TFSI 8W
Quantity	Description	Unit Price	Amount
<u>PARTS</u> 1	Wheel Spoiler RH	\$ 69.00	\$ 55.04
		\$ 69.00	\$ 55.04
	TOTAL	\$ 69.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Department Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0317/2020/RT 4-Jun-20 Glory Tan 1 of 1 SML 216 C Audi A4 Sedan 2.0 TFSI 8W
Quantity	Description	Unit Price	Amount
<u>Labours</u> 1	To tow back the vehicle from accident scene. (including tyre replacement)	S/N \$ 350.00	<i>\$350.00</i>
TOTAL		\$ 350.00	<i>\$ 350.00</i>

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant