

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33717

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0317/2020/NS
Date	:	23-Mar-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Sandeep Hooda
Address	:	4 Simei Rise #07-10 Singapore 528801
Telephone	:	HP +65 86616070
Type of Claim	:	Own Damage Claims
Policy No.	:	1900094067
Vehicle No	:	SML 216 C
Model Code	:	Audi A4 Sedan 2.0 TFSI 8W
Model / Year	:	Apr-19
Engine No	:	CVK 077057
Chassis No	:	WAUZZZF42KA040554
Mileage	:	7512
Date In	:	23-Mar-20
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	20-Mar-20
Place of Accident	:	Changi South Avenue 1 Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SML 216 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To remove and renew aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	✓
3	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N 350.300	✓
4	To renew rhs wheel suspension assy with subframe. To inspect for further damages.	S/N \$ 2,400.00	? ✓
5	To dismantle and renew front bumper, bonnet and both headlights. To repair rhs front fender. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 5,250.00	2750 ✓
6	To respray front bumper, rhs front fender, bonnet, hinges, rhs front door and rhs sill panel.	\$ 4,400.00	2750 ✓
7	To renew rhs front rim and tyre. To carry out pre-wheel alignment and post wheel alignment.	S/N \$ 520.00	✓ 450
	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 14,792.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 216 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Distorted</i>	\$ 2,068.00	✓ 1654.40
2	FRONT BUMPER FIXING PARTS <i>X } Distorted</i>	\$ 553.00	✓ X nn
3	FRONT BUMPER SECURING STRIP <i>✓</i>	2 \$ 67.00	✓ 52.96
4	FRONT BUMPER GRILLE CENTRE <i>crushed</i>	\$ 185.00	✓ 147.60
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>torn</i>	\$ 198.00	✓ 158
6	FRONT BUMPER AIR GUIDE - LH / RH <i>Not nec</i>	2 \$ 118.00	X
7	RADIATOR GRILLE <i>crushed</i>	\$ 1,254.00	✓ 1003.20
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Not nec</i>	2 \$ 254.00	X
9	FRONT BUMPER CARRIER <i>?</i>	BY \$ 757.00	? ✓ 605.20
10	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	DE \$ 117.00	? ✓ 93.60
11	FRONT BUMPER COVER <i>crushed</i>	\$ 120.00	✓ 96
12	CAUTION SIGN STICKER <i>?</i>	NEC \$ 13.00	✓ 10.24
13	AIRCON STICKER <i>✓ Nec</i>	NEC \$ 7.00	✓ X nn
14	LOCK CARRIER BRACKET <i>Not nec</i>	\$ 129.00	X
15	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2 \$ 54.00	? X nn
16	HORN - LH HIGH TONE <i>?</i>	\$ 38.00	X
17	HORN - RH LOW TONE <i>Not nec</i>	\$ 270.00	X
18	SPRING SHACKLE - LH / RH <i>Not nec</i>	2 \$ 54.00	X
19	FRONT PARKING AID SENSOR - INNER / OUTER <i>?</i>	2	TBC X
20	FRONT PARKING AID SEAL RING <i>Not nec</i>	4 \$ 14.00	X
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,270.00

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 216 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	BONNET <i>Dented.</i>	\$ 2,634.00	✓ 2107.70
22	BONNET ATTACHMENT PARTS <i>NP NEC</i>	\$ 388.00	X
23	BONNET LID HINGE - LH / RH <i>NP NEC</i>	2 \$ 574.00	X
24	BONNET IMPACT PROTECTION - CENTRE <i>NP NEC</i>	\$ 26.00	✓ 20.80
25	BONNET IMPACT PROTECTION - LH / RH <i>NP NEC</i>	2 \$ 52.00	✓ 41.12
26	BONNET GAS FILLED STRUT <i>NP NEC</i>	2 \$ 224.00	X
27	BONNET STRIKER - LH / RH <i>NP NEC</i>	2 \$ 94.00	X
28	BONNET LID LOCK	2 \$ 403.00	X
29	BONNET BOWDEN CABLE - CENTRE <i>NP NEC</i>	\$ 54.00	X
30	BONNET BOWDEN CABLE	\$ 54.00	X
31	BONNET RELEASE LEVER <i>NP NEC</i>	\$ 13.00	X
32	BONNET SOUND ABSORBER	\$ 323.00	X
33	LED HEADLIGHT - LH / RH <i>NP NEC</i>	2 \$ 14,642.00	X
34	LIFT CYLINDER - LH / RH <i>NP NEC</i>	2 \$ 396.00	X
35	LIFT CYLINDER CORRUGATED PIPE <i>NP NEC</i>	\$ 88.00	X
36	LOCK CARRIER <i>Cracked.</i>	\$ 956.00	✓ 764.40
37	COLLANT REGULATOR SUPPORT ? <i>CH</i>	1-2 \$ 71.00	? Ann
38	AIRCON CONDENSER ?	\$ 586.00	? Xnn
39	CHARGE AIR COOLER <i>Distorted</i>	\$ 552.00	✓ 441.20
40	CHARGE AIR COOLER PRESSURE HOSE - RH <i>NP NEC</i>	\$ 336.00	X
SUB TOTAL SPARE PARTS CHARGES		: \$ 22,466.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 216 C

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/Nett	Remarks
41	CHARGE AIR COOLER PRESSURE PIPE <i>new</i>	\$	402.00 <i>x</i>
42	RADIATOR ? <i>by</i>	\$	766.00 ? <i>✓ 612.40</i>
43	READY MIX COOLANT <i>new</i>	\$	169.00 <i>✓ 134.72</i>
44	RADIATOR FAN RING ?	\$	240.00 ? <i>x nn</i>
45	RADIATOR FAN ?	\$	1,877.00 ? <i>x nn</i>
46	RADIATOR AIR GUIDE - LH / RH <i>RH torn</i>	2 \$	54.00 <i>27. 21.04</i>
47	RADIATOR AIR GUIDE - LH / RH ?	2 \$	24.00 ? <i>x nn</i>
48	RADIATOR AIR GUIDE - UPPER ?	\$	15.00 ? <i>x nn</i>
49	RADIATOR AIR GUIDE - LOWER ?	\$	21.00 ? <i>x nn</i>
50	AIR INTAKE AIR DUCT - RH	\$	21.00 <i>x</i>
51	AIR INTAKE AIR FILTER	\$	362.00 <i>x</i>
52	AIR INTAKE AIR GUIDE	\$	50.00 <i>x</i>
53	AIR INTAKE AIR MASS METRE	\$	546.00 <i>x</i>
54	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$	36.00 <i>x</i>
55	NOISE INSULATION <i>torn</i>	\$	537.00 <i>✓ 429.60</i>
56	FRONT ALUMINIUM RIM - RH <i>cut</i>	\$	652.00 <i>✓ 521.20</i>
57	SUPPORT FRAME ?	\$	3,096.00 ? <i>x nn</i>
58	FRONT WISHBONE LINK - RH ? <i>BT</i>	\$	507.00 ? <i>405.20 ✓</i>
59	FRONT SUSPENSION GUIDE - RH ? <i>BT</i>	\$	887.00 ? <i>709.60 ✓</i>
60	UPPER CONTROL ARM - RH ? <i>BT</i>	\$	480.00 ? <i>384 ✓</i>

SUB TOTAL SPARE PARTS CHARGES : \$ 10,742.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 216 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
61	REAR UPPER CONTROL ARM - RH UPPER ? <i>bt</i>	\$ 480.00	? 384 ✓
62	WHEEL BEARING HOUSING - RH ? <i>mg</i>	\$ 912.00	? 728.60 ✓
63	SWIVEL JOINT ? <i>bt</i>	\$ 182.00	? 145.60 ✓
64	WHEEL HUB ? <i>mg</i>	\$ 460.00	? 368 ✓
65	SUSPENSION FORKS - RH ?	\$ 249.00	? X nn
66	COUPLING ROD ?	2 TBC	? X nn
67	DRIVE SHAFT <i>ne ne</i>	\$ 2,498.00	X
68	GAS SHOCK ABSORBER ?	\$ 284.00	? X nn
69	TRACK ROD ?	\$ 93.00	? X nn
70	STEERING GEAR GREASE ?	\$ 41.00	? X nn
71	TIE ROD END ? <i>bt</i>	\$ 186.00	? 148.40 ✓
72	DOUBLE ANGLE BALL BEARING ? <i>mg</i>	\$ 237.00	? 189.60 ✓
73	REAR NOISE INSULATION <i>torn</i>	\$ 371.00	✓ 296.40
74	CENTRE UNDERBODY TRIM AIR GUIDE - RH <i>torn</i>	TBC	✓ X nn
75	FRONT UNDERBODY TRIM - LH <i>torn</i> ?	\$ 40.00	✓ ? X nn
76	UNDERBODY TRIM <i>torn</i>	\$ 305.00	✓ 243.60
77	REAR UNDERBODY TRIM - RH <i>torn</i>	\$ 125.00	✓ 99.60
78	FUEL TANK TRIM <i>torn</i>	\$ 59.00	✓ 46.56
79	REAR SUSPENSION COVER STONE CHIP GUARD - RH <i>lt</i>	\$ 42.00	✓ 33.70
80	FRONT TYRE - RH <i>deflated punctured</i>	TBC	✓ 180 X
81	FRONT NO PLATE <i>dented</i>	S/N \$ 60.00	✓
82	SUNDRIES ? <i>nee</i>	\$ 400.00	? 105.60 ✓
TOTAL SPARE PARTS CHARGES		: \$ 46,502.00	
TOTAL LABOUR CHARGES		: \$ 14,792.00	
GRAND TOTAL		: \$ 61,294.00	

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lj

Surveyed Date

: 24/03/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 11 Days inclusive of undercarriage and lock carrier.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0317/2020/RT

2-Apr-20

Raymond Ting

1 of 1

SML 216 C

Audi A4 Sedan 2.0 TFSI 8W

Quantity Description

Unit Price

Amount

PARTS

1 Wheel Spoiler RH

\$ 69.00

740 / 55.04

\$ 69.00

TOTAL

\$ 69.00

For Premium Automobiles Pte Ltd

Authorised Signature

3/4/20
06/04/20