

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO20004434/Qyd3e2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date :	13-05-2020 SMO	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLD 9689R		spected	SHB 514D
	Policy No.		Covera	-	0.00
	Claim No.	CMTD20001261/RUC	Excess	s (\$)	0.00
	Assign From	MELVIN YE	Assign	Date	24/03/2020
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS	c.c		1798
	Engine No.	HIDDEN	Year of	Reg.	2014
	Chassis No.	JTDKN36U705747538	Colour		MAROON
	Odometer	492945	Steerin	g	IN ORDER
	Brakes	IN ORDER	Modific	ation	SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	WEST L		6 mm
	L/H Front Tyre	195/65 R15	WEST LAKE		6 mm
	R/H Rear Tyre	195/65 R15	WEST L		6 mm
	L/H Rear Tyre	195/65 R15	WEST L		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	23/03/2020		tion Date	24/03/2020
	Survey held at SMRT AUTOMOTIVE SERVICES PTE LTD				
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				