

Section A - Accident Details

Registration Number	SHB514D
Case Reference Number	TAX/03/20/2069
Registration Date	13/8/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ALEXANDAR RAJ JOSHUA
Type of Accident	Head To Side
Accident Date and Time	23/3/2020 11:40 AM
Accident Reported Date and Time	23/3/2020 2:00 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	23/3/2020 12:34 PM
Replacement Vehicle issued?	No
Job Card Number	24106289
Special Instruction to ARC, if any	FRONT RIGHT HAND SIDE PORTION DAMAGE
Prepared Date and Time	24/3/2020 8:58 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,095.00	\$550.00
Total Spray Cost	\$2,016.00	\$550.00
Total Spare Part Cost	\$12,873.30	\$1,699.66
Total Other Cost	\$756.00	\$120.00
TOTAL COST	\$16,740.30	\$2,919.66
Lump Sum Total	\$16,750.00	\$2,900.00 (L/S)
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / Sompoo
ARC / Surveyor Sign Off Date	30/03/2020 3:07 PM	28/03/2020 8:35 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP= + 1 day.	Lump Sum Repair, After paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2004-0294	Invoice Number	
Quotation Date	22.04.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$845.00	\$400.00 /
TO REPAIR FRONT SUPPORT PANEL	\$250.00	\$150.00 /
Total Labour	\$1,095.00	\$550.00

Supp

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 /
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 /
TO RESPRAY RIM	\$180.00	\$50.00 /
TO RESPRAY APRON PANEL RH	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
RESPRAY MIRROR COVER RH	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00 /
Total Spray Painting & Panel Beating	\$2,016.00	\$550.00

Supp

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00 /
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$0.00
Total Other Costs	\$756.00	\$120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53111-47040	GRILLE, RADIATOR	0.00	\$31C.60	0.00	\$0.00	Replace	Not Given X
		53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given X
		76851-47020	BUMPER LIP FRT	0.00	\$13C.60	0.00	\$0.00	Replace	Check X
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check X
		51410-12105	UNDER COVER CENTER	0.00	\$44C.30	0.00	\$0.00	Replace	Not Given X
		51444-12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 22/04/2020

User ID PohSuan

51443-12080	UNDER COVER SIDE/RH	0.00	\$46.00	0.00	\$0.00	Replace	Check	X
53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Check	X
53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	X
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	X
53827-47030	FENDER PROTECTOR FRT/RH SIDE	0.00	\$113.90	0.00	\$0.00	Replace	Check	X
53875-47030	FENDER LINER FRT/RH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	X
53851-47040	FENDER LINER PAD. FR WHEEL, RH	1.00	\$49.30	25.00	\$36.98	Replace	Replace	X
53701-47050	FENDER APRON SUB FRT/RH	0.00	\$637.80	0.00	\$0.00	Replace	Check	X
42611-47140	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	X
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
75851-47900	MOULDING BODY, RH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given	X
48510-80574	SHOCK ABSORBER FRT/RH	0.00	\$394.20	0.00	\$0.00	Replace	Check	X
48609-47040	SHOCK ABSORBER MOUNTNG FRT, RH/LH	0.00	\$193.30	0.00	\$0.00	Replace	Check	X
48619-28010	SHOCK ABSORBER BEARING, FRT LH/RH	0.00	\$34.00	0.00	\$0.00	Replace	Check	X
48820-47020	STABILIZER BAR LINK FRT/RH/LH	0.00	\$195.30	0.00	\$0.00	Replace	Check	X
5702712010	MEMBER SUB-ASSY. FR RH	0.00	\$810.70	0.00	\$0.00	Replace	Not Given	X
52255-12010	SIDE CHASSIC BRACE FRT/RH	0.00	\$103.30	0.00	\$0.00	Replace	Not Given	X
48811-47060	STABILIZER BAR FRT	0.00	\$348.30	0.00	\$0.00	Replace	Not Given	X
48820-47020	STABILIZER BAR LINK FRT/RH/LH	0.00	\$195.00	0.00	\$0.00	Replace	Not Given	X
43201-47030	STEERING KNUCKLE RH FRT	0.00	\$580.80	0.00	\$0.00	Replace	Not Given	X
43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given	X
48068-47050	LOWER ARM FRT/RH	0.00	\$625.90	0.00	\$0.00	Replace	Not Given	X
43330-49185	JOINT ASSY, LWR BALL	0.00	\$195.60	0.00	\$0.00	Replace	Not Given	X
45046-49225	TIE ROD END RH	0.00	\$159.30	0.00	\$0.00	Replace	Not Given	X
45510-47070	STEERING RACK ASSY	0.00	\$1,597.50	0.00	\$0.00	Replace	Not Given	X
43410-47030	DRIVE SHAFT RH	0.00	\$1,764.40	0.00	\$0.00	Replace	Not Given	X
87910-47330	MIRROR ASSY, RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given	X
879157-4010	COVER, OUTER MIRROR, RH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X
52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace	X
52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	X
52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	X
52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X
52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check	X
81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	X
52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check	X
57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Not Given	X
	NUMBER PLATE FRAME	1.00	\$12.00	100.00	\$0.00	Replace	Old Damage	X
	NUMBER PLATE	1.00	\$15.00	100.00	\$0.00	Replace	Old Damage	X
53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	X
82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Not Given	X

		81511-47050	LENS & BODY,FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Check	✓
		81521-47050	LENS & BODY,FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	✓
Total					\$20,242.65		\$2,028.80			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52618-47050	BUMPER FRT ABSORBER LOWER	1.00	\$127.70	25.00	\$95.78	Replace	Replace
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	100.00	\$0.00	Replace	Old Damage
		52021-47023	BUMPER REINFORCEMENT FRT	1.00	\$498.40	100.00	\$0.00	Replace	Old Damage
Total					704.90		95.78		

CRU
SVC
SVC

2124.58 ✓

- 207

1699.66 ✓

+ 550.00 ✓
+ 670.00 ✓

2919.66 ✓

L/S \$ 2900/- ✓

4 days