



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



AIG ASIA PACIFIC INSURANCE P/L 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Cocks Nicholas Campbell ADDRESS: TEL: 96369965 <i>Mrs. Stephanie @ 96342151</i>		WIP: 25-Jul EXCESS: DATE: 24-Mar-20	
VEH NO:	SLP5793K	DATE IN:		CONTACT PERSON:	JOBI THOMAS 6331 0682
CHASSIS NO:	WMWXS520102F22501	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MINI COOPER F55	DATE REG.:	9-Jun-17	POLICY NO.:	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	FRONT BUMPER / DD	1	M51.11.7.379.432		\$ 793.52
2	FRONT BUMPER SUPPORT RH	1	M51.11.4.824.422		\$ 70.46
3	FRONT BUMPER LOWER CHROME FRAME / MC	1	M51.11.7.355.238 (photo)		\$ 134.16
4	FRONT FENDER RH / DD	1	M41.00.7.374.522		\$ 527.54
5	FRONT FENDER MOUNT RH / DT	1	M51.64.7.301.600 (photo)		\$ 75.53
6	FRONT BUMPER SPOILER / BR	1	M51.11.7.301.622		\$ 242.32
7	FRONT FENDER WHEEL ARCH RH / CH	1	M51.77.7.300.820		\$ 178.29
8	FRONT FENDER INNER SHIELD RH / BR CR	1	M51.71.7.290.790		\$ 152.94
9	WHEEL ARCH EXPANDING RIVET / MC	8	B07.14.7.201.307		\$ 9.92
10	INNER SHIELD CLIP / MC	6	B07.14.7.169.847		\$ 6.66
11	INNER SHIELD RIVET / MC	2	B07.14.7.136.172		\$ 2.08
12	BONNET / DD	1	M41.00.8.499.868		\$ 1,349.08
13	BONNET ADJUSTER X NN	1	B51.76.7.183.752		\$ 8.26
14	TRIM RING LH / MC	1	M51.13.7.300.631 (photo)		\$ 73.25
15	TRIM RING RH / MC	1	M51.13.7.300.632 (photo)		\$ 73.25
16	MINI EMBLEM / MC	1	M51.14.7.316.703		\$ 79.11
17	INSULATOR CLIP / MC	15	B51.48.9.119.216		\$ 15.60
18	LABEL COOLANT / MC	1	M71.23.6.992.810		\$ 31.85
19	FRONT RIM RH / CH	1	M36.11.6.855.108		\$ 949.79
TOTAL PARTS					\$ 4,773.61
TOTAL PARTS COST					\$ -

Labour Description

1	TO REPLACE FRONT BUMPER, FRONT FENDER RH AND BONNET. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 840	1680	\$ 1,900.00
2	TO RESPRAY FRONT BUMPER, FRONT FENDER RH AND BONNET. 800	2400	\$ 2,600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION. 150		\$ 250.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	NETT	\$ 120.00

5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	\$ 560.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250	\$ 350.00
8	SUNDRIES.	NETT 20	\$ 50.00
		TOTAL LABOUR	\$ - \$ 6,080.00
		TOTAL PARTS	\$ - \$ 4,773.61
		TOTAL	\$ - \$ 10,853.61
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Sten (LKK) w/ AL
6 dys

P/P

By Bul sy

27/3/20, 10.15am

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: