

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004436/T1BA3Q2

Date: 18/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800112859

Claimant
Vehicle No : SLM1710S **Insured Vehicle No :** SME1558X

Date of Loss: 22/03/2020 Nature of Claim: TP Claim No: 0557008191SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM1710S		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5915140
Reg. Date:	22/03/2017 (Man. Year: 2016)	Chassis No:	RU31215129
Colour:	Black	Odometer:	177257 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	APLUS 6 mm	Rear Left Side:	APLUS 6 mm
Front Right Side:	APLUS 6 mm	Rear Right Side:	APLUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,602.32	3,564.32	1,038.00	22.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	2,300.00	1,020.00	30.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,922.32	5,864.32	2,058.00	25.98
Approved Total (Overridden) (S\$)		4,700.00		
(S\$)	7,922.32	4,700.00	3,222.32	40.67
+ GST 7.00/7.00% (S\$)	554.56	329.00	225.56	40.67
Nett Amount (S\$)	8,476.88	5,029.00	3,447.88	40.67
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,485.45		
Global Sum Settlement (S\$)		5,450.00		

INSPECTION

Date of Assignment: 23/03/2020

Date Inspected: 24/03/2020 Inspected At:

Em-1 Auto Pte Ltd (HQ)
Blk 8 Sin Ming Industrial Estate Sector
C, #01-68
Singapore 575643

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent	980.00 FL	*980.00 FL
2	1		*FRONT DOOR OUTER MOULDING LH	Not Necessary	89.00 FL	*- FL
3	1		*FRONT DOOR BLACK STICKER LH	Necessary	49.20 FL	*49.20 FL
4	2		*FRONT DOOR HINGES	Repair	224.00 FL	*- FL
5	1		*FRONT DOOR CHECKER	Repair	62.00 FL	*- FL
6	1		*FRONT DOOR INNER LOCK	Bent	269.20 FL	*269.20 FL
7	1		*FRONT DOOR LOCK CATCH	Not Necessary	46.00 FL	*- FL
8	3		*FRONT DOOR WEATHERSTRIPS	Cut	105.00 FL	*105.00 FL
9	1		*FRONT DOOR REGULATOR MOTOR AND GEAR	Bent	452.80 FL	*452.80 FL
10	1		*FRONT DOOR CHANNEL	Not Necessary	96.50 FL	*- FL
11	1		*FRONT DOOR CHANNEL SEAL	Not Necessary	112.00 FL	*- FL
12	1		*FRONT DOOR INNER TRIM	Cracked	752.00 FL	*560.00 FL
13	1		*FRONT DOOR INNER TRIM CLIPS	Necessary	40.00 FL	*20.00 FL
14	1		*REAR DOOR LH	Bent	960.00 FL	*960.00 FL
15	1		*REAR DOOR OUTER MOULDING	Not Necessary	89.00 FL	*- FL
16	1		*REAR DOOR BLACK STICKER	Necessary	49.20 FL	*49.20 FL
17	1		*REAR DOOR TRANSPARENT STICKER	Necessary	39.00 FL	*39.00 FL
18	1		*REAR DOOR HINGES	Top Not Necessary / BottomBent	112.00 FL	*56.00 FL
19	1		*REAR DOOR CHECKER	Not Necessary	62.00 FL	*- FL
20	6		*REAR DOOR WEATHERSTRIPS	Necessary (3 PCS ONLY)	140.00 FL	*105.00 FL
21	1		*SET DOOR SIDE PROTECTOR	Cut	180.00 FS	*180.00 FS
22	1		*CHASSIS NO STICKER	Necessary	150.00 FS	*100.00 FS
23	1		*SIDE SKIRTS	Distorted	571.50 FL	*430.00 FL
24	1		*SET SIDE SKIRT CLIP	Necessary	40.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **5,670.40** **4,385.40**
- List Item Discount on L Items 20.00/20.00% (\$\$) 1,068.08 821.08

Total Parts (\$\$) **4,602.32** **3,564.32**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,300.00	900.00
2	SPRAY PAINTING	New	1,300.00	1,000.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	120.00	70.00
5	REMOVE AND INSTALL BOTH FRONT AND BOTH REAR DOOR PARTS	New	180.00	120.00
6	REMOVE AND INSTALL CARPET AND SEAT	New	150.00	60.00
7	TO RESET REPROGRAM AND ERASER FAULT CODE	New	220.00	120.00
Gross Labour Cost (\$\$)			3,320.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >