



## 創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

NTUC/MS FC(SHB2138T)

DOA:17/03/2020@2200

MS FIRST CAPITAL INSURANCE PTE LTD

21-03-20

ATTN: THE MOTOR CLAIMS DEPT

### THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SLP 1930 H - TOYOTA WISH 1.8 CVT

CHASSIS NO: JTDGG20W60J007104 (05/2017)

1 pc

Front side mirror assy  
LESS 25%

(glass only) / BR

\$ 854.50

140

\$ 213.63

-25%

\$ 640.87

105

✓

To remove and replace the above.

\$ 80.00

Respray front side mirror cover LH

\$ 50.00

\$ 770.87

ADD 7% GST

\$ 53.96

\$ 824.83

130 ✓

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

\$235 (P/P, before GST)

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

Steve (LKK)

26/3/20, 3:30pm

WM PriL

2 dys

P/P

My Bel sy

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: