



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

NTUC/MS FC(SHB2138T)

DOA:17/03/2020@2200

MS FIRST CAPITAL INSURANCE PTE LTD

21-03-20

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SLP 1930 H - TOYOTA WISH 1.8 CVT

CHASSIS NO: JTDGG20W60J007104 (05/2017)

1 pc	Front side mirror assy	\$	854.50
	LESS 25%	\$	213.63
		\$	640.87
	To remove and replace the above.	\$	80.00
	Respray front side mirror cover LH	\$	50.00
		\$	770.87
	ADD 7% GST	\$	53.96
		\$	824.83

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT