

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 21-Mar-20

INSURANCE: China Teiping

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA1943Y

Description	Qty	List Price	Amount	
Bonnet <i>Dented</i>	1	\$ 2,253.80	\$ 2,253.80	✓
Bonnet Rubber (LH) <i>NH</i>	1	\$ 12.40	\$ 12.40	X
Bonnet Rubber (RH) <i>NH</i>	1	\$ 12.40	\$ 12.40	X
Bonnet Hinge (LH/RH) <i>NH</i>	2	\$ 118.70	\$ 237.40	✓
Bonnet Lock <i>NH</i>	1	\$ 127.30	\$ 127.30	✓
Bonnet Absorber <i>NH</i>	1	\$ 35.70	\$ 35.70	X
Bonnet Insulator <i>NH</i>	1	\$ 230.10	\$ 230.10	✓
Bonnet Seal <i>NH</i>	1	\$ 38.30	\$ 38.30	X
Bonnet Insulator Clips <i>NH</i>	1	\$ 8.40	\$ 8.40	✓
Bonnet Cable <i>SVC</i>	1	\$ 29.90	\$ 29.90	X
Radiator Grille <i>distorted</i>	1	\$ 1,227.50	\$ 1,227.50	✓
Flap Assy Active Air Upper, (LH/RH) <i>distorted</i>	2	\$ 356.00	\$ 712.00	✓
Actuator Active Air(LH/RH) <i>distorted</i>	2	\$ 257.10	\$ 514.20	✓
Unit Assy-SMART CRU (Radar Sensor) <i>broken</i>	1	\$ 2,910.90	\$ 2,910.90	✓
Front Number Plate garnish <i>distorted</i>	1	\$ 137.60	\$ 137.60	✓
Front Bumper Cover <i>distorted</i>	1	\$ 418.30	\$ 418.30	✓
Front Bumper Sponge/Absorber <i>distorted</i>	1	\$ 86.90	\$ 86.90	✓
Front Bumper Reinforcement <i>broken</i>	1	\$ 1,075.10	\$ 1,075.10	✓
Front Bumper reinforcement lower support <i>NH</i>	1	\$ 861.30	\$ 861.30	X
Front Bumper Towing Cover <i>distorted</i>	1	\$ 29.00	\$ 29.00	✓
Front Bumper Moulding Centre Upper <i>distorted</i>	1	\$ 368.50	\$ 368.50	✓
Front Bumper Lower Stiffener <i>distorted</i>	1	\$ 85.10	\$ 85.10	✓
Front Bumper Lip <i>distorted</i>	1	\$ 35.10	\$ 35.10	✓
Front Bumper Bracket Top (LH/RH) <i>NH</i>	2	\$ 35.00	\$ 70.00	X
Front Bumper Bracket (LH/RH) <i>SVC</i>	2	\$ 28.00	\$ 56.00	X
Front Bumper Side Bracket Support <i>NH</i>	2	\$ 12.00	\$ 24.00	X
Front Bumper Clips 10 pcs <i>NH</i>	1	\$ 25.00	\$ 25.00	✓
Day Light ,LH <i>distorted</i>	1	\$ 642.50	\$ 642.50	✓
Day Light , RH <i>distorted</i>	1	\$ 642.50	\$ 642.50	✓
Day Light Wire, LH/RH <i>NH</i>	1	\$ 585.50	\$ 585.50	X
BUZZER ASSY - PIEZO (LH/RH) <i>NH</i>	2	\$ 388.00	\$ 776.00	X
Headlamp Support Panel Assy <i>broken</i>	1	\$ 949.30	\$ 949.30	✓
Headlamp(LH/RH) <i>O/S broken NH distorted / broken</i>	2	\$ 3,987.30	\$ 7,974.60	✓
Headlamp Halogen Bulb (LH/RH) <i>NH</i>	2	\$ 14.40	\$ 28.80	X
Radiator Inverter <i>punctured</i>	1	\$ 884.80	\$ 884.80	✓
Radiator <i>punctured</i>	1	\$ 510.50	\$ 510.50	✓
Radiator Blower Motor <i>Dented / broken</i>	1	\$ 576.00	\$ 576.00	✓
Radiator Fan <i>broken</i>	1	\$ 375.10	\$ 375.10	✓
Radiator Shroud <i>broken</i>	1	\$ 275.50	\$ 275.50	✓
Radiator Hose Upper <i>2 deformed</i>	1	\$ 66.20	\$ 66.20	✓
Radiator Hose Lower <i>broken</i>	1	\$ 66.20	\$ 66.20	✓
Radiator Hose Water <i>2 & turn</i>	1	\$ 29.70	\$ 29.70	✓

Radiator Pipe Water <i>2 1st</i>	1	\$ 61.90	\$ 61.90	<i>✓</i>
Radiator Tank Reservoir <i>crack</i>	1	\$ 110.10	\$ 110.10	<i>✓</i>
Radiator Hose & Tube Assy <i>2 turn</i>	1	\$ 245.70	\$ 245.70	<i>✓</i>
Radiator Air Guard (LH/RH) <i>broken / damaged</i>	2	\$ 26.40	\$ 52.80	<i>✓</i>
Radiator Air Guard, Upr(LH/RH) <i>NH</i>	2	\$ 27.50	\$ 55.00	<i>X</i>
Horn Unit (LH/RH) <i>broken</i>	2	\$ 72.80	\$ 145.60	<i>✓</i>
Front Fender(LH/RH) <i>N/S repn o/s Dashed</i>	2	\$ 490.70	\$ 981.40	<i>✓</i>
Front Fender Apron Panel (LH/RH) <i>NH</i>	2	\$ 756.20	\$ 1,512.40	<i>X</i>
Front Fender Apron Panel Upper(LH/RH) <i>NH</i>	2	\$ 129.60	\$ 259.20	<i>X</i>
Front Chasis Member <i>NH</i>	1	\$ 1,314.80	\$ 1,314.80	<i>X</i>
Front Fender Shield (LH/RH) <i>N/S NH o/s turn / damaged</i>	2	\$ 114.70	\$ 229.40	<i>✓</i>
Front Fender Retainer <i>NH</i>	2	\$ 41.40	\$ 82.80	<i>X</i>
Air Cleaner Assy <i>broken</i>	1	\$ 836.50	\$ 836.50	<i>✓</i>
Air Filter <i>for NH</i>	1	\$ 59.30	\$ 59.30	<i>X</i>
Air Cleaner Cover <i>NH</i>	1	\$ 47.30	\$ 47.30	<i>X</i>
Air Duct <i>broken</i>	1	\$ 96.80	\$ 96.80	<i>✓</i>
Aircon Condenser <i>punctured</i>	1	\$ 663.60	\$ 663.60	<i>✓</i>
Aircon Discharge Hose <i>2 1st</i>	1	\$ 148.50	\$ 148.50	<i>✓</i>
Frt Door(RH) <i>repn</i>	1	\$ 1,797.20	\$ 1,797.20	<i>X</i>
Frt Door Rubber <i>NH</i>	1	\$ 250.00	\$ 250.00	<i>X</i>
Front Door Hinge Upper (RH) <i>NH</i>	1	\$ 65.76	\$ 65.76	<i>X</i>
Front Door Hinge Lower (RH) <i>NH</i>	1	\$ 65.76	\$ 65.76	<i>X</i>
Front Door Check (RH) <i>NH</i>	1	\$ 72.98	\$ 72.98	<i>X</i>
Front Door Mirror ASSY (RH) <i>NH</i>	1	\$ 1,391.70	\$ 1,391.70	<i>X</i>
Front Windscreen Glass <i>crack</i>	1	\$ 1,558.10	\$ 1,558.10	<i>✓</i>
Front Windscreen Moulding <i>NH</i>	1	\$ 57.30	\$ 57.30	<i>✓</i>
Front Windscreen Pillar Outer(RH) <i>Buc</i>	1	\$ 3,764.90	\$ 3,764.90	<i>✓</i>
Front Windscreen Pillar Inner(RH) <i>NH</i>	1	\$ 310.70	\$ 310.70	<i>X</i>
Wiper Danel Top Garnish <i>broken</i>	1	\$ 181.20	\$ 181.20	<i>✓</i>
Wiper Link <i>NH</i>	1	\$ 224.00	\$ 224.00	<i>X</i>
Wiper Container <i>scr</i>	1	\$ 486.30	\$ 486.30	<i>X</i>
Front Wheel Rim (RH) <i>cut</i>	1	\$ 1,124.20	\$ 1,124.20	<i>✓</i>
Front Wheel Hub Cap (RH) <i>NF</i>	1	\$ 346.40	\$ 346.40	<i>X</i>
Front Wheel Bearing <i>2 Dam</i>	1	\$ 454.00	\$ 454.00	<i>✓</i>
Front Shock Absorber(Assy)(RH) <i>2 distrupt</i>	1	\$ 372.50	\$ 372.50	<i>✓</i>
Front Shock Absorber Mounting (RH) <i>NH</i>	1	\$ 206.90	\$ 206.90	<i>X</i>
Front Shock Absorber Fork (RH) <i>NH</i>	1	\$ 206.90	\$ 206.90	<i>X</i>
Front Suspension Upper Arm (RH) <i>NH</i>	1	\$ 244.30	\$ 244.30	<i>X</i>
Front Drive Shaft (RH) <i>distrupt</i>	1	\$ 936.70	\$ 936.70	<i>X</i>
Rack & Pinion Assy <i>NH Dam</i>	1	\$ 887.40	\$ 887.40	<i>✓</i>
STG Tie Rod <i>2 distrupt NH</i>	1	\$ 125.60	\$ 125.60	<i>✓</i>
STG Tie End <i>2 distrupt</i>	1	\$ 94.70	\$ 94.70	<i>✓</i>
Stabilizer Bar <i>NH</i>	1	\$ 246.80	\$ 246.80	<i>X</i>
Stabilizer Bar Bush (RH) <i>NH</i>	1	\$ 22.30	\$ 22.30	<i>X</i>
Stabilizer Bar Link <i>NH</i>	1	\$ 92.10	\$ 92.10	<i>X</i>
Stabilizer Bracket <i>NH</i>	1	\$ 10.50	\$ 10.50	<i>X</i>
Front Suspension Lower Arm (RH) <i>2 distrupt</i>	1	\$ 296.80	\$ 296.80	<i>✓</i>
Knuckle Arm (RH) <i>2 distrupt</i>	1	\$ 363.60	\$ 363.60	<i>✓</i>
Engine Under Cover <i>distrupt</i>	1	\$ 469.40	\$ 469.40	<i>✓</i>
Engine Crossmember <i>NH Dam</i>	1	\$ 1,803.90	\$ 1,803.90	<i>✓</i>
Gearbox Mounting <i>NH</i>	1	\$ 183.70	\$ 183.70	<i>X</i>
Alternator Assy <i>broken NH</i>	1	\$ 1,207.90	\$ 1,207.90	<i>X</i>
Wiring-Engine <i>NH</i>	1	\$ 3,474.00	\$ 3,474.00	<i>X</i>
Wiring-Front <i>2 turn</i>	1	\$ 3,802.10	\$ 3,802.10	<i>✓</i>

} 45
 L
 X
 L
 L
 1200
 900/-
 30/-
 40/-
 44
 NN
 NN
 60/-
 150/-
 44
 50/-
 80/-
 780/-
 80/-
 NN
 244
 320/-

ryan
LKK Auto

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to the approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 8-Apr-20

INSURANCE: China Tqing

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA1943Y

Description	Qty	List Price	Amount
Flap Assy Active wire socket broken	1	\$ 765.30	\$ 765.30
Front bumper top cover torn	1	\$ 476.30	\$ 476.30
Front bumper air duct (LH/RH) destroyed	2	\$ 156.80	\$ 313.60
Front RH drive shaft extension broken	1	\$ 1,125.80	\$ 1,125.80
Aircon Suction & Liquid Hose bt	1	\$ 679.60	\$ 679.60
Aircon Discharge Hose repaired	1	\$ 148.50	\$ 148.50
Wiper Arm bt	1	\$ 133.60	\$ 133.60
Wiper Top Garnish SIDE COVER (RH) destroyed/broken	1	\$ 86.40	\$ 86.40
Engine Mounting Done	1	\$ 786.20	\$ 786.20
Engine mount support broken	1	\$ 286.30	\$ 286.30
Auto Gear Oil MH	1	\$ 163.70	\$ 163.70
electronic clutch pump broken	1	\$ 4,386.50	\$ 4,386.50
Generator Assy, Hybrid Vehicle broken	1	\$ 3,358.10	\$ 3,358.10
wiring - hybrid recharge Done	1	\$ 1,539.50	\$ 1,539.50
Speaker broken	1	\$ 256.10	\$ 256.10
SUB TOTAL			\$ 14,505.50
LESS 20%			\$ 2,901.10
DISCOUNTED TOTAL			\$ 11,604.40
ESTIMATE TOTAL			\$ 11,604.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.


 Tym
 Jkk Auto


08/04/2020.