

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

Not Authorized
24/3/20
Whepht, after repair
3 days!
2/5/20

M/S : LIM SOH KOON
BLK 507 CANBERRA DRIVE #05-20
SINGAPORE 768127

Estimate No: EST1505897
Date: 19 Mar 2020
Policy No: 2100501277
Veh Reg No: SLA4175E
Make/Model: HONDA VEZEL 1.5X
CVT

4/5 \$2150

ATTN: FIRST CAPITAL

Your Ref No: TP 0320-5929
Claim Type: Third Party
Accident Date: 18/03/2020
TP Veh Reg No: SHA 4468 H

Chassis No: RU11107923
Engine No: L15B4027924
Reg. Date: 29/02/2016

Estimate Repair Cost to Vehicle No :SLA4175E

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 REAR BUMPER - CENTRE, BLACK	508.50	1 PC	508.50	✓
2 REAR BUMPER CLIPS	3.90	10 PC	39.00	✓
3 REAR BUMPER SIDE HOLDER - LH	21.50	1 PC	21.50	X
4 REAR BUMPER SIDE HOLDER - RH	21.50	1 PC	21.50	X
5 REAR PANEL	411.90	1 PC	411.90	X
6 REAR PANEL TOP GARNISH	93.20	1 PC	93.20	X
7 REAR BOOT	1,050.90	1 PC	1,050.90	✓
8 REAR BOOT "H" LOGO	27.40	1 PC	27.40	X
9 REAR BOOT "VEZEL" WORDING	43.00	1 PC	43.00	✓
10 REAR BOOT WINDSCREEN MOULDING	131.50	1 SET	131.50	✓
11 REAR BOOT RUBBER	96.80	1 PC	96.80	X
			2,445.20	
		Less 20%	489.04	1,956.16
Special Net				
12 REAR BUMPER SENSOR	220.00	1 SET	220.00	200 S. Net
13 SEALANT Rear windscreen	20.00	2 PC	40.00	✓
14 SPONGE TAPE Rear windscreen	20.00	1 PC	20.00	✓
			280.00	280.00
Labour				
15 TO KNOCK OUT DENTS, REAR BOOT, CUT/WELD, REMOVE, REPLACE ACCIDENT PARTS	600.00	1 JOB	600.00	400
16 TO RESPRAY PAINT ON ACCIDENT PORTIONS	600.00	1 JOB	600.00	400
17 TO CHECK WIRING	20.00	1 JOB	20.00	✓
18 TO REMOVE, REPLACE REAR BUMPER SENSOR	50.00	1 JOB	50.00	✓
19 TO REMOVE, REFIX REAR GLASS	120.00	1 JOB	120.00	✓
20 TO REMOVE, REFIX REAR GARNISH, CARPET, CUSHION, SEAT AND RELATED PARTS	80.00	1 JOB	80.00	60
21 TO TRANSFER REAR BOOT	60.00	1 JOB	60.00	✓
			1,530.00	1,530.00

P-1675
202
1340
2710
2168

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : LIM SOH KOON
BLK 507 CANBERRA DRIVE #05-20
SINGAPORE 768127

ATTN: FIRST CAPITAL

Your Ref No: TP 0320-5929
Claim Type: Third Party
Accident Date: 18/03/2020
TP Veh Reg No: SHA 4468 H


Estimate No: **EST1505897**
Date: 19 Mar 2020
Policy No: 2100501277
Veh Reg No: **SLA4175E**
Make/Model: HONDA VEZEL 1.5X
CVT
Chassis No: RU11107923
Engine No: L15B4027924
Reg. Date: 29/02/2016

Estimate Repair Cost to Vehicle No :SLA4175E

Description	U/Price	Quantity	Price	Amount
			SS	SS
			Total	SS 3,766.16
			Add GST @ 7%	263.63
			Total Amount Payable	SS 4,029.79

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND TWENTY NINE AND CENTS SEVENTY NINE ONLY

For Progressive Car Care Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: