

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : LIM SOH KOON

BLK 507 CANBERRA DRIVE #05-20

SINGAPORE 768127

Estimate No: EST1505897

Date: 19 Mar 2020

Policy No: 2100501277

Veh Reg No: SLA4175E

Make/Model: HONDA VEZEL 1.5X
CVT

ATTN: FIRST CAPITAL

Your Ref No: TP 0320-5929

Claim Type: Third Party

Accident Date: 18/03/2020

TP Veh Reg No: SHA 4468 H

Chassis No: RU11107923

Engine No: L15B4027924

Reg. Date: 29/02/2016

Estimate Repair Cost to Vehicle No :SLA4175E

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 REAR BUMPER - CENTRE, BLACK	508.50	1 PC	508.50	
2 REAR BUMPER CLIPS	3.90	10 PC	39.00	
3 REAR BUMPER SIDE HOLDER - LH	21.50	1 PC	21.50	
4 REAR BUMPER SIDE HOLDER - RH	21.50	1 PC	21.50	
5 REAR PANEL	411.90	1 PC	411.90	
6 REAR PANEL TOP GARNISH	93.20	1 PC	93.20	
7 REAR BOOT	1,050.90	1 PC	1,050.90	
8 REAR BOOT "H" LOGO	27.40	1 PC	27.40	
9 REAR BOOT "VEZEL" WORDING	43.00	1 PC	43.00	
10 REAR BOOT WINDSCREEN MOULDING	131.50	1 SET	131.50	
11 REAR BOOT RUBBER	96.80	1 PC	96.80	
			2,445.20	
		Less 20%	489.04	1,956.16
Special Net				
12 REAR BUMPER SENSOR	220.00	1 SET	220.00	
13 SEALANT	20.00	2 PC	40.00	
14 SPONGE TAPE	20.00	1 PC	20.00	
			280.00	280.00
Labour				
15 TO KNOCK OUT DENTS, REAR BOOT, CUT/WELD, REMOVE, REPLACE ACCIDENT PARTS	600.00	1 JOB	600.00	
16 TO RESPRAY PAINT ON ACCIDENT PORTIONS	600.00	1 JOB	600.00	
17 TO CHECK WIRING	20.00	1 JOB	20.00	
18 TO REMOVE, REPLACE REAR BUMPER SENSOR	50.00	1 JOB	50.00	
19 TO REMOVE, REFIX REAR GLASS	120.00	1 JOB	120.00	
20 TO REMOVE, REFIX REAR GARNISH, CARPET, CUSHION, SEAT AND RELATED PARTS	80.00	1 JOB	80.00	
21 TO TRANSFER REAR BOOT	60.00	1 JOB	60.00	
			1,530.00	1,530.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : LIM SOH KOON
BLK 507 CANBERRA DRIVE #05-20
SINGAPORE 768127

Estimate No: EST1505897
Date: 19 Mar 2020
Policy No: 2100501277
Veh Reg No: SLA4175E
Make/Model: HONDA VEZEL 1.5X
CVT
Chassis No: RU11107923
Engine No: L15B4027924
Reg. Date: 29/02/2016

ATTN: FIRST CAPITAL


Your Ref No: TP 0320-5929
Claim Type: Third Party
Accident Date: 18/03/2020
TP Veh Reg No: SHA 4468 H

Estimate Repair Cost to Vehicle No :SLA4175E

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 3,766.16
			Add GST @ 7%	263.63
			Total Amount Payable	<u>S\$ 4,029.79</u>

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND TWENTY NINE AND CENTS SEVENTY NINE ONLY

For Progressive Car Care Pte Ltd


AUTHORISED SIGNATURE