

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

25-04-20

Accident Date : 25-04-2020
OUR REF : SLL 6554Z/T/20

DONNY SNG WAN JIE
 Blk 40 Sims Drive
 #07-217
 Singapore 380040

*All Lklk Ashw
 Lklk - Marcus
 20/3/20 to 10/4/20*

*Not Authorized
 1/5 @ 18.500
 24/3/20
 18 days.*

ESTIMATE BILL ON VEH. NO. : SLL 6554Z

MODEL : HONDA SHUTTLE

CHASSIS NO : GK81100476

LIST ITEM

Front Bumper Fascia	<i>862.90</i>		<i>DD/pe</i> 1,050.20 /
Front Bumper Side Retainer		2pcs @ 25.40	<i>11</i> 50.80 X
Front Bumper Center Air Grille			<i>7w1</i> 145.20 /
Front Bumper Fog Lamp Cover		2pcs @ 45.20	<i>SU</i> 90.40 X
Front Bumper Reinforcement			<i>Surf</i> 420.80 /
Front Bumper Clips		10pcs @ 3.50	<i>NU</i> 35.00 /
Front Bumper Tow Cover			<i>11</i> 25.40 X
Front Grille			<i>CNA</i> 395.40 /
Front Grille Inner Garnish Bracket			<i>CNA</i> 65.20 /
Front Grille Chrome			<i>CNA</i> 302.40 /
Front Grille Badge			<i>REU</i> 28.40 /
Front Grille Clips		6pcs @ 3.50	<i>11</i> 21.00 X
Front Grille Top Garnish Cover			<i>7111</i> 58.20 /
Head Lamp	<i>2227.70 x 2 = 4455.40</i>	2pcs @ 2250.40	<i>CNA</i> 4,500.80 /
Head Lamp Lower Bracket		2pcs @ 38.20	<i>11</i> 76.40 X
Bonnet			<i>BUC</i> 920.80 /
Bonnet Hinge <i>hinges</i>		2pcs @ 45.80	<i>SU</i> 91.60 X
Bonnet Lock			<i>711</i> 135.40 /

Bonnet Lock Cable		11	75.20 X
Bonnet Inner Rubber Beading		11	27.40 X
Bonnet Inner Rubber Beading Clips	13pcs @ 3.50	11	45.50 X
Bonnet Insulator Clips	4pcs @ 3.50	11	14.00 X
Front Support Panel		sent	785.40 /
Air Cond Condensor		sent/pun	985.40 /
Air Cond Condensor Side Air Grille Garnish	2pcs @ 50.10	de/torn	100.20 /
Radiator Assy		sent/pun	1,350.40 /
Front Fender - LH		R	368.40 X
Tail Gate		Body	1,193.20 /
Tail Gate Hindge	2pcs @ 40.50	11	81.00 X
Tail Gate Stopper	2pcs @ 8.50	11	17.00 X
Tail Gate Lock		DD/JM	256.40 /
Tail Gate Lock Striker		11	34.70 X
Tail Gate Weather Stripe		7m	168.20 /
Tail Gate Absorber	2pcs @ 120.40	11	240.80 X
Tail Gate Chorme Clips	8pcs @ 3.50	11	28.00 X
Tail Gate Outer Garnish with Chorme		sent/cn	363.80 /
Tail Gate Badge		nc	46.50 /
Tail Gate Emblum "Shuttle"		nc	55.40 /
Tail Gate Reflector	2pcs @ 395.40	BRO	790.80 /
Tail Gate Reflector Sealant	2pcs @ 12.90	11	25.80 X
Tail Gate Reflector Clips	4pcs @ 3.50	11	14.00 X
Tail Gate Inner Trim Board		de/torn	320.40 /
Tail Gate Inner Trim Board Clips	8pcs @ 3.50	nc	28.00 /
Tail Gate Outer Keyless Sensor		11	85.40 X
Tail Gate Lock Buzzer		11	80.10 X
Tail Gate Reflector Bulb Socket	2pcs @ 15.20	11	30.40 X

Rear Wiper Motor		JM	390.40	/
Rear Wiper Arm		but	95.50	/
Rear Wiper Arm Cover		ms	8.10	/
Rear Wiper Blade		11	66.50	X
Rear Windscreen Glass		shottch	1,210.40	/
Rear Windscreen Glass Moulding		re	149.20	/
Rear Windscreen Clips	14pcs @ 5.50	11	77.00	X
Rear Windscreen Glass Recorder 'V9'		shottch	39.10	/
Tail Lamp Assy	2pcs @ 520.40	510	1,040.80	/
Tail Lamp Sealant	2pcs @ 21.40	11	42.80	X
Tail Lamp Clips	4pcs @ 3.50	11	14.00	X
Tail Lamp Base Panel	2pcs @ 210.40	1	420.80	X
Tail Lamp Bulb Socket	2pcs @ 15.40	11	30.80	X
Rear Bumper Fascia	936.50	D.S	1,150.40	/
Rear Bumper Side Retainer	2pcs @ 26.50	but/re	53.00	/
Rear Bumper Side Attachement	2pcs @ 41.40	11	82.80	X
Rear Bumper Bracket	2pcs @ 38.70	NS	77.40	X
Rear Bumper Reflector	2pcs @ 45.20	11	90.40	X
Rear Bumper Reflector Garnish	2pcs @ 46.10	twi	92.20	/
Rear Bumper Tow Cover		re	26.50	/
Rear Bumper Sponge - RH & LH	2pcs @ 56.50	To 11	112.00	/
Rear Bumper Clips	10pcs @ 3.50	re	35.00	/
Rear End Panel		body	560.20	/
Rear End Panel Top Trim		cm	155.40	/
Rear End Panel Top Trim Clips	4pcs @ 3.50	11	14.00	X
Rear Fender - LH		body/buc	1,010.90	/
Rear Fender Glass Moulding		re	56.20	/
Rear Fender Inner Seal		re	31.80	/

Rear Fender Clips	6pcs @ 3.50	11	21.00 X
Rear Floor Panel		crumpled/sec	956.20
Rear Floor Panel Under Member		N	255.40 X
Rear Floor Panel Board		waped	655.20
Rear Floor Side Extentional Panel - RH & LH	2pcs @ 255.40	allscrapd	510.80 1/2
Rear Floor Panel Insulator Cloth		NT	291.60 X
Rear Floor Panel Tool Tray		D/S	245.20
Rear Fender Inner Trim Board - RH & LH	2pcs @ 483.20	Delto/n	966.40
Rear Fender Inner Trim Board - Top LH		11	195.20 X
Rear Fender Inner Trim Board Clips	20pcs @ 5.50	11	110.00 X
Rear Floor Panel Tool Tray Cover		D/S	650.40
Rear Sub Chassis Frame Member	2pcs @ 855.40	N	1,710.80 X
Rear Sub Chassis Frame Member Top Panel	2pcs @ 219.20	N	438.40 X
Exhaust Silencer		N	588.20 X
Exhaust Silencer Hook	2pcs @ 29.40	11	58.80 X
Rear Fender Air Vent - RH & LH	2pcs @ 45.20	N/Scrap	90.40 1/2

24046.4
202
19237.12

30,902.80
Less Discount 20%: 6,180.56
24,722.24

SPECIAL NETT ITEM

Front Number Plate		sent	45.00
Front Number Plate Casing			29.00 }40
Rear Windscreen Glass Sealant		neu	60.00 40
Rear Windscreen Glass Solar Film		neu	160.00 1/
Rear Number Plate		sent	45.00
Rear Number Plate Casing			29.00 }40
Reverse Sensor	1 set	shuld	380.00 200
Reverse Camera - (I-road)		shuld	680.00 300
Rear Fender Glass Sealant		neu	60.00 40

LABOUR CHARGE

Towing.	50	120.00
To Check & Reconnect Snap Wiring.	30	180.00
To Reset Electrical Module System.	50	380.00
To Tuff Coat Affected Areas.	150	280.00
To Check & Adjust Chassis Alignment On Car O Liner.	11 X	380.00
To Remove & Refix Rear Fender Glass LH & Rear Windscreen Glass.	220	380.00
To Remove & Refix Radiator & Top Up Coolant.	100 <	180.00
To Remove & Refix Air Cond Condensor & Top Up Gas.		180.00
To Remove & Refix Reverse Sensor.	50	120.00
To Remove & Refix Tail Gate Mechanism.	60	250.00
To Respray Affected Areas.	1800	3,000.00
To Cleaning Interior Upholstery.	11 X	250.00
To Renew Damages Parts, Staraiten & Repair & Aligned All Parts.	2400	2,850.00
To Remove & Refix Exhaust Silencer & Straighten Exhaust Center Pipe.	60	280.00

	35,040.24
GST 7%:	2,452.82
AMOUNT DUE :	37,493.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-19237.12
 S.W-870.00
 L-4970