



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20004459/Kqd3e2

50 RAFFLES PLACE
#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 11-11-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBP 4149X	Veh. Inspected	SJC 2052C
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2000675/THE	Excess (\$)	0.00
Assign From	YE YONG KANG MELVIN	Assign Date	24/03/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NZE1416065565	Colour	METALLIC GREY
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	FALKEN	4 mm
L/H Front Tyre	205/50 R16	FALKEN	4 mm
R/H Rear Tyre	205/50 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/50 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/01/2020	Inspection Date	25/03/2020
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**