

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

P-1822-09

SN-649.4

L-2090

S-1459.52

GOH HANLI JASON
c/o 46 Lenton Plain
Singapore 786548

Not Authorised
11 Rm @ 4650k
Permy After Paint
Today

Date: 23/3/2020

6021-20% = 54416.8

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: HONDA SHUTTLE / SGL 8842 M		
1 pc	front door (right) <u>858.20</u>	1,167.00 ✓
1 pc	front door handle	215.40 X
1 pc	front door handle cover	47.20 X
1 pc	front door lock cylinder	215.00 X
1 pc	front door lock	178.60 X
1 pc	front door lock catch	89.30 X
1 pc	front door window regulator	576.10 X
1 pc	rear door window regulator motor	336.70 X
2 pcs	rear door hinge @ 176.30	352.60 X
1 pc	rear door window regulator <u>478.20</u>	578.50 ✓
1 pc	rear door window regulator motor <u>185.40</u>	336.70 ✓
1 pc	front door weatherstrip	239.10 X
1 pc	rear door weatherstrip	298.80 ✓
1 pc	front wheel bearing	345.10 X
1 pc	front wheel hub	415.30 X
1 pc	front knuckle arm	511.30 X
1 pc	front shock absorber	478.80 X
1 pc	rear wheel bearing <u>384.10</u>	514.30 ✓
1 pc	front door frame sticker (1)	131.30 —
1 pc	front door frame sticker (2)	144.90 —
1 pc	rear door frame sticker	135.80 —
1 pc	"B" pillar outer panel	915.30 X
1 pc	rear bumper	756.50 X
1 pc	rear bumper side retainer	77.60 X
1 pc	side rocker panel skirt	10.70 ✓
sub-total		9,067.90
less 20%		1,813.58
sub-total		7,254.32

2277.60
-20% 455.52

Est 1,822.08

SN 649.40

L 2090.00

SUPP 1,459.52

Page 1 of 2

6021.00

4/8 = 4816.80
4800/-

balance brought forward.

7,254.32

CS

alloy rim

s.nett @

650.00

~~1,300.00~~ ^{500.00}

To remove and replace the parts mentioned above,
panel beat and realign the necessary affected areas.

~~700~~ 1,200.00

To check wiring system.

~~200~~ 50.00

To apply rust proofing on affected areas.

~~600~~ 120.00

To apply waterproof sealant on affected areas.

~~600~~ 120.00 ✓

To apply putty & spray painting on affected areas.

~~1,200.00~~ ^{100.00}

To remove carpet, trimming and seats to enable repair.

~~120.00~~ X

To transfer 2 doors' accessories.

~~120.00~~ ✓

To replace 2 alloy rims & perform wheel balancing.

~~400~~ 80.00

To machine press wheel bearing.

✓ 60.00 ~~300~~

To perform 4 wheels computerised alignment.

~~600~~ 85.00 ✓

Towing charges.

~~500~~ 50.00 X

To benchmount & align frame.

~~400.00~~ X

total 12,159.32

LKS Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No Zingal modifications is allowed
- Supplementary claim(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOWORX HOUSE

C/O 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64520715 FAX: 64529250

ESTIMATE

GOH HANLI JASON
c/o 46 Lenton Plain
Singapore 786548

Date: 16/4/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: SUPPLEMENTARY FOR HONDA SHUTTLE / SGL 8842 M	
1 pc	rear door <u>899.50</u>	By <u>1,217.40</u>
1 pc	front door window regulator	P.T <u>336.70</u>
1 pc	front lower arm	Sm <u>878.10</u>
1 pc	side rocker panel skirt <u>588.20</u>	Qd/Ois <u>910.70</u>
	S=1824 - 20% 1459.52	sub-total 1,217.40
		less 20% 243.48
		sub-total 973.92
	To remove & install front & rear undercarriage parts to enable repair.	<u>260.00</u>
		total 1,233.92

1824.40
- 20% 364.88
1459.52