

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SJS 8231 D

<u>S/N Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1 To tow and recover vehicle from scene of accident.	S/N \$ 280.00	/
2 To carry out first measurement test on car o-liner.	S/N \$ 800.00	? photo
3 To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	/
4 To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	? /
5 To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and knee airbag.	S/N \$ 3,600.00	/
<b>SUB TOTAL LABOUR CHARGES</b>	<b>: <u>\$ 6,240.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SJS 8231 D

<u>S/N Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1 To tow and recover vehicle from scene of accident.	S/N \$ 280.00	/
2 To carry out first measurement test on car o-liner.	S/N \$ 800.00	? photo
3 To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	/
4 To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	? /
5 To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and knee airbag.	S/N \$ 3,600.00	/
<b>SUB TOTAL LABOUR CHARGES</b>	<b>: <u>\$ 6,240.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SJS 8231 D

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	to remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs. Renew accordingly.	S/N \$ 2,800.00	? <i>7/f</i>
7	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew in necessary.	S/N \$ 2,400.00	? <i>photo</i>
8	To renew front windscreen.	S/N \$ 480.00	/
9	To install solar film for front windscreen.	S/N \$ 400.00	/
10	to place vehicle on car o-liner.	S/N \$ 1,800.00	? <i>photo</i>
<b>SUB TOTAL LABOUR CHARGES</b>		<b>: <u>\$ 7,880.00</u></b>	

# Premium Automobiles

20, Kilsyth, Sydney NSW 1505, 994  
 00252211, Fax: 00252181

Telefax

## Estimated Labour Charges for Accident Vehicle S15 8231 D

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
	To renew turbocharge and other engine compartments.	S/N \$ 980.00	X
	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damage.	S/N \$ 280.00	/
	To disassemble rhs front door panel trim. To remove and transfer rhs wing mirror assy.	S/N \$ 350.00	/
	To dismantle and renew front bumper, bonnet, both front fenders, both headlights and rhs front door. (Cut out and reweld rhs fender top support and closing element and (rhs A-lower pillar) weigh both front chassis frames to specification of origin. Renew front lock carrier and align to position. Re-organise front crash management components. reinstall all parts removed.	<sup>0.5 (9.5)</sup> <del>12,600.00</del> S \$ 4750 + 2000 = 6750 (subject to insurance approval)	
	To repair front bumper, both front fenders, bumper hinges, rhs A-pillar, engine compartment, rhs front fender top support and rhs front door. To carry out joint sealer works and steel chip treatment.	(6) <del>7,200.00</del> S \$ 3300 + 1100 = 4400 (subject to insurance approval)	
	To renew rhs front rim. To carry out pre-repair wheel alignment check and post-repair wheel alignment check.	S/N \$ 520.00	/
	To carry out diagnostic check.	S/N \$ 384.00	/
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 36,434.00</b>	

Prep  
 Tel: 00252211

Stic In

bor  
 TF  
 BV4  
 28V

21

23

24

in fa'

25

26

27

# Premium Automobiles

55 Ubi Road I, Singapore 408699  
Tel: 6366 2323 Fax: 6841 3183

Telefax

## Material List for Accident Vehicle Regn No. SJS 8231 D

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	Remarks
1	FRONT BUMPER <i>de</i>	\$ 1,894.00	
2	FRONT BUMPER FIXING PARTS <i>ne</i>	\$ 176.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>ca</i> <sup>nn</sup> <i>1pc</i>	\$ 72.00	<i>2b</i>
4	FRONT BUMPER GRILLE - CENTRE <del>ca</del> <i>X</i> <sup>nn</sup>	\$ 151.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>X ca</i>	\$ 505.00	<i>v</i>
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>ca</i> <sup>nn</sup> <i>1pc</i>	\$ 560.00	<i>270</i>
7	FRONT BUMPER COVER TRIM - LH / RH <i>X</i> <sup>nn</sup> <i>2</i>	\$ 306.00	
8	WHEEL HOUSING LINER ADAPTER - LH / RH <i>ca</i> <sup>nn</sup> <i>1pc</i>	\$ 72.00	<i>2b</i>
9	RADIATOR GRILLE <i>ca</i>	\$ 1,338.00	
10	RADIATOR GRILLE CLOSING ELEMENT <i>ca</i>	\$ 180.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>ca</i> <sup>nn</sup> <i>1pc</i>	\$ 354.00	<i>177</i>
12	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>bt</i>	\$ 681.00	
13	FRONT BUMPER FOAM FILLER PIECE <i>ca</i>	\$ 178.00	
14	FOAM FILLER PIECE COVER <i>cut</i>	\$ 115.00	
15	AIRCON STICKER <i>ne</i>	NEC \$ 7.00	
16	CAUTION SIGN STICKER <i>ne</i>	NEC \$ 13.00	
17	SIGNAL HORN - LH HIGH TONE <i>X</i> <sup>nn</sup>	\$ 188.00	<i>X</i>
18	SIGNAL HORN RH LOW TONE <i>sum</i>	\$ 188.00	
19	FRONT FENDER - LH / RH <i>bt</i>	2 \$ 1,604.00	
20	FRONT FENDER ATTACHMENT PARTS <i>ne</i>	\$ 68.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>: \$ 8,650.00</b>	

# Premium Automobiles

55 Hill Road 1, Singapore 408699  
Tel: 634 2323 Fax: 634 1183

Telefax

## Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
21	FRONT FENDER BRACKET - RH <i>bt</i> ✓	\$	26.00	
22	FRONT FENDER BRACKET - RH <del>bt</del> ✓	\$	36.00	
23	FRONT FENDER BRACE <i>bt</i> ✓	\$	90.00	
24	FRONT FENDER CLOSING ELEMENT - RH <i>na</i> ✓	\$	31.00	
25	FRONT FENDER INSULATION - RH <i>na</i> ✓	\$	40.00	
26	WHEEL HOUSING LINER SEAL - RH <i>na</i> ✓	\$	32.00	
27	WHEEL HOUSING LINER - LH / RH <del>de</del> ✓ <i>1pc</i>	\$	318.00	159
28	WHEEL HOUSING LINER ATTACHMENT PARTS <i>na</i> ✓	\$	84.00	
29	BONNET <i>bt</i> ✓	\$	2,988.00	
30	BONNET ATTACHMENT PARTS <i>na</i> ✓	\$	155.00	
31	BONNET LID HINGE - LH / RH <del>bt</del> ✓	2 \$	116.00	
32	BONNET GAS FILLED STRUT <del>X</del> <i>wn</i>	\$	112.00	
33	BONNET CATCH HOOK <del>bt</del> ✓	\$	84.00	
34	BONNET STRIKER - LH / RH <del>?</del> ✓ <i>1pc</i>	\$	208.00	104
35	BONNET EDGE PROTECTION <i>na</i> ✓	\$	26.00	
36	BONNET COVER - RH <del>de</del> ✓	\$	39.00	
37	WATER BOX SEAL <del>X</del>	\$	56.00	
38	BONNET LID LOCK <i>ca</i> ✓	2 \$	403.00	
39	FLAT CONNECTOR HOUSING <i>?</i>	\$	13.00	?
40	BONNET BOWDEN CABLE - CENTRE <del>X</del> <i>na</i>	\$	54.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>\$ 4,911.00</b>		

Premium  
55 Hill Road  
Tel: 634 2323

# Premium Automobiles

55 Ubi Road 1, Singapore 408609  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
41	BONNET LID LOCK CABLE X	\$	69.00	
42	RELEASE HANDLE BRACKET ?	\$	36.00	
43	ACTUATING LEVER X	\$	47.00	
44	WATER BOX SEAL - LH / RH X	2 \$	26.00	
45	BONNET SOUND ABSORBER X	\$	207.00	
46	PLENUM CHAMBER COVER <del>ca</del> ca ✓	\$	169.00	
47	SIDE MEMBER - RH UPPER bt ✓	\$	384.00	
48	LED HEADLIGHT - LH / RH bro ✓	2 \$	10,386.00	
49	MAIN LIGHTS POWER MODULE ca ✓	\$	714.00	
50	LIGHT CONTROL SYSTEM CONTROL UNIT X cut ✓	\$	524.00 ✓	
51	LED WITH HEAT SINK - RH bt ✓	\$	689.00	
52	HEADLIGHT HOSE - RH X	\$	38.00	
53	LIFT CYLINDER - LH / RH X (RH) bro ✓	1 set \$	268.00	134.
54	LIFT CYLINDER HOSE X	\$	64.00	
55	HEADLIGHT WASHER PUMP X	\$	149.00	
56	WINDSCREEN WASHER SYSTEM PUMP X	\$	120.00	
57	WASH WATER RESERVOIR X	\$	190.00	
58	LOCK CARRIER ca ✓	\$	685.00	
59	AIRCON CONDENSER #9 bt ✓	\$	519.00	
60	REFRIGERANT LINE <del>ca</del> bt cut ✓	\$	613.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>: \$ 15,897.00</b>		

# Premium Automobiles

55 Ubi Road 1, Singapore 408697  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
61	REFRIGERANT LINE <del>re</del> <i>cut</i> ✓	\$	471.00	
62	REFRIGERANT LINE BRACKET <del>re</del> <i>bt</i> ✓	\$	25.00	
63	REFRIGERANT LINE DUAL CLIP <del>re</del> <i>re</i> ✓	\$	29.00	
64	RADIATOR <del>re</del> <i>bt</i> ✓	\$	932.00	✓
65	ADDITIONAL RADIATOR <del>re</del> <i>bt</i> ✓	\$	851.00	✓
66	RADIATOR BRACKET <del>re</del> <i>ca</i> ✓	2 \$	78.00	✓
67	RADIATOR BUSH - LOWER <del>re</del> <i>re</i> ✓	2 \$	19.00	✓
68	READY MIX COOLANT <i>re</i> ✓	\$	169.00	✓
69	RADIATOR FAN <del>re</del> <i>X</i>	\$	1,070.00	<del>X</del>
70	RADIATOR AIR GUIDE - LH / RH <del>re</del> <i>ca</i> ✓	2 \$	46.00	
71	RADIATOR AIR GUIDE - UPPER CENTRE <del>re</del> <i>X</i>	\$	12.00	<del>X</del>
72	EXTERNAL TEMPERATURE SENSOR <del>re</del> <i>X</i>	\$	55.00	<del>X</del>
73	TEMPERATURE SENSOR BRACKET <del>re</del> <i>re</i> ✓	\$	18.00	
74	AIR INTAKE AIR DUCT COVER <del>re</del> <i>X</i>	\$	28.00	<del>X</del>
75	AIR INTAKE AIR GUIDE <del>re</del> <i>X</i>	\$	54.00	<del>X</del>
76	AIR INTAKE AIR GUIDE <del>re</del> <i>X</i>	\$	63.00	<del>X</del>
77	AIR INTAKE SEAL <del>re</del> <i>X</i>	\$	13.00	<del>X</del>
78	AIR INTAKE AIR FILTER <del>re</del> <i>X</i>	\$	256.00	<del>X</del>
79	AIR INTAKE AIR GUIDE <del>re</del> <i>X</i>	\$	19.00	<del>X</del>
80	AIR INTAKE WATER DRAINAGE HOSE <del>re</del> <i>X</i>	\$	32.00	<del>X</del>
<b>SUB TOTAL SPARE PARTS</b>		<b>\$ 4,240.00</b>		

Pre

55 Ubi Rd  
Tel: 6366 2323

ic In

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
81	AIR INTAKE MANIFOLD X	\$	131.00	
82	EXHAUST MANIFOLD X	\$	5,049.00	
83	OIL RETURN TUBE O-RING X	2 \$	46.00	
84	INTAKE PIPE GASKET X	2 \$	27.00	
85	CONVERTER AND PIPE GASKET X	\$	19.00	
86	CONVERTER AND PIPE CLAMP X	\$	48.00	
87	COOLANT HOSE X	\$	232.00	
88	COOLANT HOSE X	\$	115.00	
89	AIRCON COMPRESSOR X	\$	2,123.00	
90	CHARGE AIR COOLER X	\$	686.00	
91	CHARGE AIR COOLER SEAL X	\$	13.00	
92	CHARGE AIR COOLER SEAL X	\$	13.00	
93	INTAKE MANIFOLD X	\$	600.00	
94	INTAKE MANIFOLD SEAL X	\$	13.00	
95	SIDE PANEL - RH ?bt ✓	\$	2,063.00 ✓	
96	WINDSCREEN ca ✓	\$	1,020.00	
97	RAIN SENSOR GEL FOIL re ✓	\$	130.00	
98	INTERIOR MIRROR SPRING CLIP re ✓	\$	20.00	
99	WATER DEFLECTOR STRIP - RH MIS ✓	\$	87.00	
100	FRONT DOOR - RH bt ✓	\$	2,375.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>: \$ 14,810.00</b>		

# Premium Automobiles

11 Selegie Road, Singapore 118699  
Tel: (65) 434 1124 Fax: (65) 434 3183

Telefax

Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
101	FRONT OUTER DOOR SEAL - RH <i>new</i>	NEC	\$ 151.00	
102	BONDING AGENT <i>new</i>	NEC	\$ 46.00	
103	CLEANING SOLUTION <i>new</i>	NEC	\$ 64.00	
104	FRONT DOOR ATTACHMENT PARTS <i>new</i>		\$ 227.00	
105	FRONT DOOR CATCH <i>X</i>		\$ 99.00	<i>X</i>
106	DOOR HINGE HALF-UPPER PART - RH UPPER <i>X</i>		\$ 75.00	<i>X</i>
107	DOOR HINGE HALF-UPPER PART - RH LOWER <i>X</i>		\$ 45.00	<i>X</i>
108	DOOR HINGE HALF-LOWER PART - RH UPPER <i>X</i>		\$ 45.00	<i>X</i>
109	DOOR HINGE HALF-LOWER PART - RH LOWER <i>X</i>		\$ 45.00	<i>X</i>
110	FRONT WINDOW SLOT SEAL - RH <i>sea</i>		\$ 291.00	
111	WINDOW GUIDE TRIM STRIP - RH <i>X</i>		\$ 242.00	<i>X</i>
112	TYRE PRESSURE DATA PLATE <i>new</i>		\$ 27.00	
113	NOISE INSULATION <i>X Cor</i>		\$ 244.00	<i>✓</i>
114	FRONT BUMPER REINFORCEMENT BEAM COVER PLATE <i>bf</i>		\$ 90.00	
115	STEERING WHEEL AIRBAG UNIT <i>act</i>		\$ 3,221.00	
116	DASHBOARD AIRBAG <i>act</i>		\$ 4,330.00	
117	HEAD AIRBAG UNIT - LH / RH <i>act</i>	2	\$ 3,512.00	
118	KNIFE AIRBAG UNIT <i>act</i>		\$ 1,756.00	
119	SEATBELT - LH / RH <i>act</i>	2	\$ 2,080.00	
120	SEATBELT HEIGHT ADJUSTER <i>?</i>	2	\$ 368.00	<i>?</i>
SUB TOTAL SPARE PARTS		:	<u>\$ 16,958.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SIS 8231 D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
121	AIRBAG CONTROL UNIT <i>ACT</i>	\$	1,482.00	
122	AIRBAG CRASH SENSOR <i>ACT</i>	3	TBC	
123	SPORTS STEERING WHEEL ? <i>✓ cut</i>	\$	2,237.00	
124	DASHBOARD <i>crash</i>	\$	4,014.00	
125	LOUDSPEAKER COVER <i>X</i>	\$	88.00	<i>X</i>
<i>126</i>	AIR VENT - CENTRE <i>X</i>	\$	142.00	<i>X</i>
127	STOWAGE COMPARTMENT - RH <i>X</i>	\$	425.00	<i>X</i>
128	MOULDED HEADLINER <i>da</i>	\$	1,666.00	<i>✓</i>
<i>129</i>	A-PILLAR TRIM - LH <i>X</i>	\$	151.00	<i>X</i>
<i>130</i>	A-PILLAR TRIM - RH UPPER <i>X</i>	\$	151.00	<i>X</i>
131	B-PILLAR TRIM - LH / RH <i>X</i>	2 \$	408.00	<i>X</i>
132	C-PILLAR TRIM - LH / RH <i>X</i>	2 \$	284.00	<i>X</i>
133	D-PILLAR TRIM - LH / RH <i>X</i>	2 \$	218.00	<i>X</i>
<i>134</i>	FOLDING GRAB HANDLE - FRONT <i>X</i>	2 \$	266.00	<i>X</i>
<i>135</i>	FOLDING GRAB HANDLE - LH / RH REAR <i>X</i>	2 \$	266.00	<i>X</i>
<i>136</i>	ASSEMBLY CARRIER ? <i>bt</i>	\$	962.00	<i>✓</i>
<i>137</i>	BONDED RUBBER BUSHES SET ? <i>na</i>	\$	93.00	<i>✓</i>
<i>138</i>	TRACK CONTROL ARM ? <i>bt</i>	\$	345.00	<i>✓</i>
139	COMPLETE STABILIZER ? <i>X</i>	\$	380.00	<i>X</i>
<i>140</i>	WHEEL BEARING HOUSING ? <i>bt</i>	\$	555.00	<i>✓</i>
<b>SUB TOTAL SPARE PARTS</b>		<b>: \$ 12,652.00</b>		

# Premium Automobiles

150, Road 1, Singapore 408699  
Tel: 6360 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
141	WHEEL BEARING ? <i>ne</i> ✓	\$	479.00	✓
142	GUIDE JOINT - RH ? <i>ca</i> ✓	\$	119.00	✓
143	COUPLING ROD ? <i>bt</i>	\$	90.00	?
144	GAS SHOCK ABSORBER ? <i>bt</i> ✓	\$	256.00	✓
145	DRIVE SHAFT - RH ? <i>bt</i> ✓	\$	2,190.00	✓
146	TRACK ROD ? <i>bt</i> ✓	\$	88.00	✓
147	TIE ROD END - RH ? <i>X</i>	\$	121.00	X
148	STEERING GEAR ? <i>Jam (fault code)</i>	\$	4,503.00	✓
149	STEERING BOX REPAIR SET ? <i>ne</i> ✓	\$	44.00	✓
150	GEARBOX ASSEMBLY ? <i>X ne (subject to insurance approval)</i>	\$	16,515.00	✓
151	TRANSMISSION FLUID ?	\$	60.00	
152	FRONT ALUMINIUM RIM - RH <i>cut</i> ✓		TBC	
153	FRONT NO PLATE <i>bt</i> ✓	S/N \$	60.00	
154	ACRYLIC SEALANT <i>ne</i> ✓	S/N \$	180.00	
155	CAVITY WAX <i>ne</i> ✓	S/N \$	140.00	
156	STONE CHIP <i>ne</i> ✓	S/N \$	180.00	
157	FRONT WINDSCREEN SEALANT <i>ne</i> ✓	S/N \$	200.00	
158	SUNDRIES ?	\$	1,000.00	
TOTAL SPARE PARTS CHARGES		:	\$ 104,343.00	
TOTAL LABOUR CHARGES		:	\$ 36,434.00	
GRAND TOTAL		:	\$ 140,777.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/00/0306/2020/NS

Date

13-Apr-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SJS 8231 D

Model No

Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

#### Parts

1	Underbody trim rhs front <i>cm</i>	\$ 163.00	
2	Underbody trim cover rhs front <i>cm</i>	\$ 12.00	
3	Gearbox mounting LHS <i>cm</i>	\$ 246.00	

*Subject to insurance approval*

#### Labour

1	To repair chassis member rhs.	\$ <del>700.00</del> <i>500</i>	
2	To respray chassis member rhs.	\$ <del>1,050.00</del> <i>550</i>	

TOTAL

\$ 2,171.00

*For Premium Automobiles Pte Ltd*  
*19/04/2020*

For Premium Automobiles Pte Ltd

Authorized Signature

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0306/2020/NS  
Date 11-Apr-20  
Service Advisor Glory Tan  
Pages 1 of 1  
Regn No SJS 8231 D  
Model No Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
<b>Parts</b>			
1	Battery Console <i>Cre</i>	\$	189.00
2	Shock absorber suspension strut storage <i>Strut</i>	\$	117.00
3	Shock absorber deep groove ball thrust bearing <i>ae</i>	\$	44.00
4	Seat cushion airbag front RHS ?	\$	1,428.00
5	Backrest cover front RHS ?	\$	2,068.00
6	Gearbox selector mechanism <i>noisy (subject to insurance approval)</i>	\$	1,813.00
<b>Labours</b>			
1	To remove and renew rhs front backrest cover.	S/N \$	780.00

**TOTAL** \$ 6,439.00

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
Authorised Signature

*Paul*  
*13/04/2020*  
*all parts subject to insurance approval*

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

### Estimate No.

### Date

### Service Advisor

### Pages

### Regn No

### Model No

PA/OD/0306/2020/NS

13-Apr-20

Glory Tan

1 of 1

SJS 8231 D

Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
<b>Parts</b>			
1	Underbody trim rhs front <i>CR</i>	\$ 163.00	<i>Subject to insurance approval</i>
2	Underbody trim cover rhs front <i>CR</i>	\$ 12.00	
3	Gearbox mounting LHS <i>CR</i>	\$ 246.00	
<b>Labour</b>			
1	To repair chassis member rhs.	\$ <del>700.00</del> <i>500</i>	
2	To respray chassis member rhs.	\$ <del>1,050.00</del> <i>550</i>	

TOTAL

\$ 2,171.00

*Penn*  
*14/04/2020*

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
Authorised Signature