

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 8231 D

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	to remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs. Renew accordingly.	S/N \$ 2,800.00	? ? ✓
7	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew in necessary.	S/N \$ 2,400.00	? photo ✓
8	To renew front windscreen.	S/N \$ 480.00	✓
9	To install solar film for front windscreen.	S/N \$ 400.00	✓
10	to place vehicle on car o-liner.	S/N \$ 1,800.00	? photo ✓
SUB TOTAL LABOUR CHARGES		: <u>\$ 7,880.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 8231 D

<u>S/N Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1 To tow and recover vehicle from scene of accident.	S/N \$ 280.00	✓ X 11
2 To carry out first measurement tect on car o-liner.	S/N \$ 800.00	? photo ✓
3 To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
4 To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	✓
5 To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and knee airbag.	S/N \$ 3,600.00	✓
SUB TOTAL LABOUR CHARGES	: <u>\$ 6,240.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 8231 D

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
11	To renew turbocharge and other engine compartments.	S/N \$ 980.00	X X 117
12	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00	/ /
13	To dismantle rhs front door panel trim. To remove and transfer rhs wing mirror assy.	S/N \$ 350.00	/ /
14	To dismantle and renew front bumper, bonnet, both front fenders, both headlights and rhs front door. Cut out and reweld rhs fender top support and closing element and rhs A-lower pillar. Align both front chassis frames to specification of origin. Renew front lock carrier and align to position. Re-organise front crash management components. reinstall all parts removed.	S/N \$ 12,600.00	4750 5750
15	To respray front bumper, both front fenders, bonnet, hinges, rhs A-pillar, engine compartment, rhs front fender top support and rhs front door. To carry out joint sealer works and stone chip treatment.	S/N \$ 7,200.00	3300 3850
16	To renew rhs front rim. To carry out pre-repair wheel alignment check and post-repair wheel alignment check.	S/N \$ 520.00	/ /
17	To carry out diagnostic check.	S/N \$ 384.00	/ /
TOTAL LABOUR CHARGES		: \$ 36,434.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER <i>de-</i>	\$ 1,894.00	1515.20
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 176.00	140.80
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>cm / 1pc</i>	\$ 72.00	36 28.64
4	FRONT BUMPER GRILLE - CENTRE <i>cm / 1pc</i>	\$ 151.00	120.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>cm / 1pc</i>	\$ 505.00	404.00
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>cm / 1pc</i>	\$ 560.00	280 223.60
7	FRONT BUMPER COVER TRIM - LH / RH <i>2</i>	\$ 306.00	X
8	WHEEL HOUSING LINER ADAPTER - LH / RH <i>cm / 1pc</i>	\$ 72.00	36 28.16
9	RADIATOR GRILLE <i>cm</i>	\$ 1,338.00	1070.40
10	RADIATOR GRILLE CLOSING ELEMENT <i>cm</i>	\$ 180.00	143.60
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>cm / 1pc</i>	\$ 354.00	177 141.20
12	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>bf</i>	\$ 681.00	544.80
13	FRONT BUMPER FOAM FILLER PIECE <i>cm</i>	\$ 178.00	142.40
14	FOAM FILLER PIECE COVER <i>cut</i>	\$ 115.00	91.60
15	AIRCON STICKER <i>ne</i>	NEC \$ 7.00	5.36
16	CAUTION SIGN STICKER <i>ne</i>	NEC \$ 13.00	10.24
17	SIGNAL HORN - LH HIGH TONE <i>X s/c</i>	\$ 188.00	X
18	SIGNAL HORN RH LOW TONE <i>s/c</i>	\$ 188.00	150.00
19	FRONT FENDER - LH / RH <i>bf</i>	2 \$ 1,604.00	1282.40
20	FRONT FENDER ATTACHMENT PARTS <i>ne</i>	\$ 68.00	55.60
SUB TOTAL SPARE PARTS		: \$ 8,650.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	FRONT FENDER BRACKET - RH <i>bt</i> ✓	\$ 26.00	<i>20.56</i>
22	FRONT FENDER BRACKET - RH bt ✓	\$ 36.00	<i>28.80</i>
23	FRONT FENDER BRACE <i>bt</i> ✓	\$ 90.00	<i>71.92</i>
24	FRONT FENDER CLOSING ELEMENT - RH <i>ne</i> ✓	\$ 31.00	<i>24.56</i>
25	FRONT FENDER INSULATION - RH <i>ne</i> ✓	\$ 40.00	<i>31.76</i>
26	WHEEL HOUSING LINER SEAL - RH <i>ne</i> ✓	\$ 32.00	<i>25.44</i>
27	WHEEL HOUSING LINER - LH / RH ^{<i>src</i>} de ✓ <i>1pc</i> ✓	\$ 318.00	<i>159 254.40</i>
28	WHEEL HOUSING LINER ATTACHMENT PARTS <i>ne</i> ✓	\$ 84.00	<i>67.20</i>
29	BONNET <i>bt</i> ✓	\$ 2,988.00	<i>2390.40</i>
30	BONNET ATTACHMENT PARTS <i>ne</i> ✓	\$ 155.00	<i>123.20</i>
31	BONNET LID HINGE - LH / RH bt ✓	2 \$ 116.00	<i>91.84</i>
32	BONNET GAS FILLED STRUT src ✓	\$ 112.00	<i>X</i>
33	BONNET CATCH HOOK bt ✓	\$ 84.00	<i>67.12</i>
34	BONNET STRIKER - LH / RH ^{<i>src</i>} bt <i>? src</i> ✓ <i>1pc</i> ✓	\$ 208.00	<i>104 X</i>
35	BONNET EDGE PROTECTION <i>ne</i> ✓	\$ 26.00	<i>20.80</i>
36	BONNET COVER - RH de ✓	\$ 39.00	<i>30.48</i>
37	WATER BOX SEAL nn ✓	\$ 56.00	<i>X</i>
38	BONNET LID LOCK <i>ca</i> ✓	2 \$ 403.00	<i>322.40</i>
39	FLAT CONNECTOR HOUSING <i>? src</i> ✓	\$ 13.00	<i>X</i>
40	BONNET BOWDEN CABLE - CENTRE src ✓	\$ 54.00	<i>X</i>
SUB TOTAL SPARE PARTS		: \$ 4,911.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
41	BONNET LID LOCK CABLE <i>X suc</i>	\$ 69.00	X
42	RELEASE HANDLE BRACKET <i>? X suc</i>	\$ 36.00	X
43	ACTUATING LEVER <i>X suc</i>	\$ 47.00	X
44	WATER BOX SEAL - LH / RH <i>X m</i>	2 \$ 26.00	
45	BONNET SOUND ABSORBER <i>X suc</i>	\$ 207.00	
46	PLENUM CHAMBER COVER <i>X suc cut</i>	\$ 169.00	135.20
47	SIDE MEMBER - RH UPPER <i>bt</i>	\$ 384.00	307.20
48	LED HEADLIGHT - LH / RH <i>bro</i>	2 \$ 10,386.00	8308.80
49	MAIN LIGHTS POWER MODULE <i>cm</i>	\$ 714.00	571.20
50	LIGHT CONTROL SYSTEM CONTROL UNIT <i>X nw</i>	\$ 524.00	419.20
51	LED WITH HEAT SINK - RH <i>bt</i>	\$ 689.00	550.80
52	HEADLIGHT HOSE - RH <i>X suc</i>	\$ 38.00	X
53	LIFT CYLINDER - LH / RH <i>X suc bro</i>	1 <i>1/2</i> \$ 268.00	134 107.20
54	LIFT CYLINDER HOSE <i>X suc</i>	\$ 64.00	
55	HEADLIGHT WASHER PUMP <i>X suc</i>	\$ 149.00	
56	WINDSCREEN WASHER SYSTEM PUMP <i>X suc</i>	\$ 120.00	
57	WASH WATER RESERVOIR <i>X suc</i>	\$ 190.00	
58	LOCK CARRIER <i>cm</i>	\$ 685.00	547.60
59	AIRCON CONDENSER <i>X bt</i>	\$ 519.00	415.20
60	REFRIGERANT LINE <i>X suc cut</i>	\$ 613.00	490
SUB TOTAL SPARE PARTS		: \$ 15,897.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
61	REFRIGERANT LINE bt cut ✓	\$ 471.00	376.40
62	REFRIGERANT LINE BRACKET bt ✓	\$ 25.00	20
63	REFRIGERANT LINE DUAL CLIP rec ✓	\$ 29.00	22.48
64	RADIATOR bt ✓	\$ 932.00	745.20
65	ADDITIONAL RADIATOR bt ✓	\$ 851.00	680.40
66	RADIATOR BRACKET rec ✓	2 \$ 78.00	62.24
67	RADIATOR BUSH - LOWER rec ✓	2 \$ 19.00	14.56
68	READY MIX COOLANT rec ✓	\$ 169.00	134.72
69	RADIATOR FAN X su	\$ 1,070.00	X
70	RADIATOR AIR GUIDE - LH / RH ca ✓	2 \$ 46.00	36.32
71	RADIATOR AIR GUIDE - UPPER CENTRE X su	\$ 12.00	X
72	EXTERNAL TEMPERATURE SENSOR X nw ✓	\$ 55.00	43.84
73	TEMPERATURE SENSOR BRACKET rec ✓	\$ 18.00	13.76
74	AIR INTAKE AIR DUCT COVER X su	\$ 28.00	X
75	AIR INTAKE AIR GUIDE X su	\$ 54.00	X
76	AIR INTAKE AIR GUIDE X su	\$ 63.00	X
77	AIR INTAKE SEAL X su nw	\$ 13.00	X
78	AIR INTAKE AIR FILTER X su	\$ 256.00	X
79	AIR INTAKE AIR GUIDE X su	\$ 19.00	X
80	AIR INTAKE WATER DRAINAGE HOSE X su	\$ 32.00	X
SUB TOTAL SPARE PARTS		:	<u>\$ 4,240.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
81	AIR INTAKE MANIFOLD <i>X su</i>	\$	131.00	
82	EXHAUST MANIFOLD <i>X su</i>	\$	5,049.00	
83	OIL RETURN TUBE O-RING <i>X nn</i>	2 \$	46.00	
84	INTAKE PIPE GASKET <i>X nn</i>	2 \$	27.00	
85	CONVERTER AND PIPE GASKET <i>X nn</i>	\$	19.00	
86	CONVERTER AND PIPE CLAMP <i>X nn</i>	\$	48.00	
87	COOLANT HOSE <i>X su</i>	\$	232.00	
88	COOLANT HOSE <i>X su</i>	\$	115.00	
89	AIRCON COMPRESSOR <i>X nn</i>	\$	2,123.00	
90	CHARGE AIR COOLER <i>X su</i>	\$	686.00	
91	CHARGE AIR COOLER SEAL <i>X nn</i>	\$	13.00	
92	CHARGE AIR COOLER SEAL <i>X nn</i>	\$	13.00	
93	INTAKE MANIFOLD <i>X su</i>	\$	600.00	
94	INTAKE MANIFOLD SEAL <i>X nn</i>	\$	13.00	
95	SIDE PANEL - RH <i>? bt /</i>	\$	✓ 2,063.00	<i>1650.40</i>
96	WINDSCREEN <i>ca /</i>	\$	1,020.00	<i>816.00</i>
97	RAIN SENSOR GEL FOIL <i>na /</i>	\$	130.00	<i>104.00</i>
98	INTERIOR MIRROR SPRING CLIP <i>na /</i>	\$	20.00	<i>15.92</i>
99	WATER DEFLECTOR STRIP - RH <i>mis /</i>	\$	87.00	<i>69.44</i>
100	FRONT DOOR - RH <i>bt /</i>	\$	2,375.00	<i>1900.00</i>
SUB TOTAL SPARE PARTS		: \$ 14,810.00		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
101	FRONT OUTER DOOR SEAL - RH <i>new</i> ✓	NEC \$	151.00	<i>120.80</i>
102	BONDING AGENT <i>new</i> ✓	NEC \$	46.00	<i>36.72</i>
103	CLEANING SOLUTION <i>new</i> ✓	NEC \$	64.00	<i>51.20</i>
104	FRONT DOOR ATTACHMENT PARTS <i>new</i> ✓	\$	227.00	<i>178.32</i>
105	FRONT DOOR CATCH <i>X s/c</i>	\$	99.00	
106	DOOR HINGE HALF-UPPER PART - RH UPPER <i>X s/c</i>	\$	75.00	
107	DOOR HINGE HALF-UPPER PART - RH LOWER <i>X s/c</i>	\$	45.00	
108	DOOR HINGE HALF-LOWER PART - RH UPPER <i>X s/c</i>	\$	45.00	
109	DOOR HINGE HALF-LOWER PART - RH LOWER <i>X s/c</i>	\$	45.00	
110	FRONT WINDOW SLOT SEAL - RH <i>s/c</i> ✓	\$	291.00	<i>232.40</i>
111	WINDOW GUIDE TRIM STRIP - RH <i>X s/c</i>	\$	242.00	
112	TYRE PRESSURE DATA PLATE <i>new</i> ✓	\$	27.00	<i>21.12</i>
113	NOISE INSULATION <i>X s/c</i>	\$	244.00	<i>195.20</i>
114	FRONT BUMPER REINFORCEMENT BEAM COVER PLATE <i>bt</i> ✓	\$	90.00	<i>72</i>
115	STEERING WHEEL AIRBAG UNIT <i>ACT</i> ✓	\$	3,221.00	<i>2576.80</i>
116	DASHBOARD AIRBAG <i>ACT</i> ✓	\$	4,330.00	<i>3464</i>
117	HEAD AIRBAG UNIT - LH / RH <i>ACT</i> ✓	2 \$	3,512.00	<i>2809.60</i>
118	KNEE AIRBAG UNIT <i>ACT</i> ✓	\$	1,756.00	<i>1404.80</i>
119	SEATBELT - LH / RH <i>ACT</i> ✓	2 \$	2,080.00	<i>1664</i>
120	SEATBELT HEIGHT ADJUSTER <i>? bt</i> ✓	2 \$	<i>✓</i> 368.00	<i>294.40</i>
SUB TOTAL SPARE PARTS		:	<u>\$ 16,958.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
121	AIRBAG CONTROL UNIT <i>ACU ✓</i>	\$ 1,482.00	1185.60
122	AIRBAG CRASH SENSOR <i>ACS ✓</i>	3 TBC	933.60
123	SPORTS STEERING WHEEL <i>? de ✓</i>	\$ ✓2,237.00	1789.60
124	DASHBOARD <i>cr ✓</i>	\$ 4,014.00	3211.20
125	LOUDSPEAKER COVER <i>X su ✓</i>	\$ 88.00	
126	AIR VENT - CENTRE <i>X su ✓</i>	\$ 142.00	
127	STOWAGE COMPARTMENT - RH <i>X su ✓</i>	\$ 426.00	
128	MOULDED HEADLINER <i>de ✓</i>	\$ 1,666.00	1332.80
129	A-PILLAR TRIM - LH <i>de ✓</i>	\$ 151.00	120.80
130	A-PILLAR TRIM - RH UPPER <i>de ✓</i>	\$ 151.00	120.80
131	B-PILLAR TRIM - LH / RH <i>X su ✓</i>	2 \$ 408.00	
132	C-PILLAR TRIM - LH / RH <i>X su ✓</i>	2 \$ 284.00	
133	D-PILLAR TRIM - LH / RH <i>X su ✓</i>	2 \$ 218.00	
134	FOLDING GRAB HANDLE - FRONT <i>Louse ✓</i>	2 \$ 266.00	212.80
135	FOLDING GRAB HANDLE - LH / RH REAR <i>Louse ✓</i>	2 \$ 266.00	212.80
136	ASSEMBLY CARRIER <i>? bt ✓</i>	\$ ✓962.00	789.60
137	BONDED RUBBER BUSHES SET <i>? nr ✓</i>	\$ ✓93.00	74.32
138	TRACK CONTROL ARM <i>? bt ✓</i>	\$ ✓345.00	275.60
139	COMPLETE STABILIZER <i>? su ✓</i>	\$ 380.00	X
140	WHEEL BEARING HOUSING <i>? bt ✓</i>	\$ ✓555.00	443.60
SUB TOTAL SPARE PARTS		: \$ 12,652.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 8231 D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
141	WHEEL BEARING ? <i>new</i>	\$	479.00	383.20
142	GUIDE JOINT - RH ? <i>com</i>	\$	119.00	95.20
143	COUPLING ROD ? <i>bt</i>	\$	90.00	71.36
144	GAS SHOCK ABSORBER ? <i>bt</i>	\$	256.00	204.80
145	DRIVE SHAFT - RH ? <i>bt</i>	\$	2,190.00	1752
146	TRACK ROD ? <i>bt</i>	\$	88.00	70
147	TIE ROD END - RH ? <i>bt</i>	\$	121.00	96.40
148	STEERING GEAR ? <i>bt</i>	\$	4,503.00	3602.40
149	STEERING BOX REPAIR SET ? <i>new</i>	\$	44.00	34.72
150	GEARBOX ASSEMBLY ? <i>new</i>	\$	✓16,515.00	13212
151	TRANSMISSION FLUID ? <i>xan</i>	\$	60.00	X
152	FRONT ALUMINIUM RIM - RH <i>cut</i>		TBC	666
153	FRONT NO PLATE <i>bt</i>	S/N \$	60.00	60
154	ACRYLIC SEALANT <i>new</i>	S/N \$	180.00	180
155	CAVITY WAX <i>new</i>	S/N \$	140.00	140
156	STONE CHIP <i>new</i>	S/N \$	180.00	180
157	FRONT WINDSCREEN SEALANT <i>new xan</i>	S/N \$	200.00	X
158	SUNDRIES ? <i>new</i>	\$	1,000.00	515.04
TOTAL SPARE PARTS CHARGES		:	\$ 104,343.00	105799
TOTAL LABOUR CHARGES		:	\$ 36,434.00	36434
GRAND TOTAL		:	\$ 140,777.00	142,233

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: RASUL - Hp 90010068
: 24/03/2020 @ 1730
: 18 days
: EXCESS: TBA
: REVERT
: Resurvey before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0306/2020/NS
Date 12-Jun-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SJS 8231 D
Model No Audi A3 Sedan 1.0 TFSI BV

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Wheel bearing front LHS <i>bf ✓</i>	\$ 479.00	<i>383.20</i>
TOTAL		\$ 479.00	

For Premium Automobiles Pte Ltd

Rose

*Subject to
insurance approval
15/06/2020*

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0306/2020/NS
Date 8-Jun-20
Service Advisor Raymond Ting
Pages 1 of 1
Regn No SJS 8231 D
Model No Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Tyre Front RH <i>cut ✓</i>	TBC	<i>335</i>
TOTAL		\$	-

For Premium Automobiles Pte Ltd

Rasul
08/06/2020

Authorised Signature

*Subject to
insurance approval*

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0306/2020/NS
Date 21-May-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SJS 8231 D
Model No Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Coolant pipe with inner heat exchanger <i>bt/</i>	\$ 471.00	<i>376.40</i>
TOTAL		\$ 471.00	

For Premium Automobiles Pte Ltd

Authorised Signature

R Alan
21/05/2020

*Subject to
insurance approval*

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0306/2020/NS
Date 17-Apr-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SJS 8231 D
Model No Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Chassis data tag on lower A-pillar	\$ 436.00	436.00 348.40
TOTAL		\$ 436.00	



For Premium Automobiles Pte Ltd

Authorised Signature

Subject to
insurance
approval

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Mr. Adrian Ling - Motor Claims Dept
 Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0306/2020/NS
Date 11-Apr-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SJS 8231 D
Model No Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
Parts			
1	Battery Console <i>Cre</i>	\$ 189.00	150.80
2	Shock absorber suspension strut storage <i>Hand</i>	\$ 117.00	93.20
3	Shock absorber deep groove ball thrust bearing <i>Hand</i>	\$ 44.00	34.72
4	Seat cushion airbag front RHS ?	\$ 1,428.00	1142.40
5	Backrest cover front RHS ?	\$ 2,068.00	1654.40
6	Gearbox selector mechanism <i>noisy (subject to insurance approval)</i>	\$ 1,813.00	X
Labours			
1	To remove and renew rhs front backrest cover.	S/N \$ 780.00	780

TOTAL \$ 6,439.00

For Premium Automobiles Pte Ltd

 Authorised Signature

Paul
 13/04/2020
 all parts subject to insurance approval

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0306/2020/NS
Date 13-Apr-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SJS 8231 D
Model No Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	Underbody trim rhs front <i>ca</i>	<i>130.40</i> \$	163.00
2	Underbody trim cover rhs front <i>ca</i>	<i>8.96</i> \$	12.00
3	Gearbox mounting LHS <i>ca</i>	<i>196.80</i> \$	246.00

Subject to insurance approval

Labour

1	To repair chassis member rhs.	\$ 700.00	<i>500</i> ✓
2	To respray chassis member rhs.	\$ 1,050.00	<i>550</i> ✓

TOTAL

\$ 2,171.00

Pessul
14/04/2020

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0306/2020/NS 31-Dec-20 Glory Tan 1 of 1 SJS 8231 D Audi A3 Sedan 1.0 TFSI 8V
Quantity	Description	Unit Price	Amount
LABOURS 1	TO RENEW GEARBOX ASSY AND CARRY OUT ADAPTATION. <i>new /</i>	S/N \$ 1,800.00	\$ 1,800.00 (A)
TOTAL		\$ 1,800.00	\$1,800.00

For Premium Automobiles Pte Ltd

Authorised Signature