

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SJS 8231 D

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
11	to renew turbocharge and other engine compartments.	S/N \$ 980.00	X
12	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00	/
13	To dismantle rhs front door panel trim. To remove and transfer rhs wing mirror assy.	S/N \$ 350.00	/
14	To dismantle and renew front bumper, bonnet, both front fenders, both headlights and rhs front door. Cut out and reweld rhs fender top support and closing element and rhs A-lower pillar. Align both front chassis frames to specification of origin. Renew front lock carrier and align to position. Re-organise front crash management components. reinstall all parts removed.	S \$ 12,600.00	(9.5) 4750
15	To respray front bumper, both front fenders, bonnet, hinges, rhs A-pillar, engine compartment, rhs front fender top support and rhs front door. To carry out joint sealer works and stone chip treatment.	S \$ 7,200.00	(6) 3300
16	To renew rhs front rim. To carry out pre-repair wheel alignment check and post-repair wheel alignment check.	S/N \$ 520.00	/
17	To carry out diagnostic check.	S/N \$ 384.00	/
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 36,434.00</b>	