

ASS. REC. BY: Sun Pin

REF:

NTUC NS/INC 20004470 / Qvf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

FZ 9255P

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SG 6128PYr Regn: 05/04/2019Type: M.Car / M.Cycle Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAN A95 E46c.c 10518

Colour:

Multicolour

A/C: Insured / Std / NI / NA

Sp. Reading

39732

T/Radio: Insured / Std / NI / NA

Eng/No:

-

C/No:

WMAA95229KF009002

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F: 275/70 R225R: 275/70 R225

BSY DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/03/2020D.O.I. 20/03/2020

Survey held at

SMRT.Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SG 6128P-x</u>
	<u>FZ 9255P-x</u>
<u>13/4/20</u>	<u>Sun Pin confirmed \$2150.19 (Red 1452.91, 405)</u>

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

13/4 - typist

Report Format:

TP

Lump Sum / L.B.I. /

2150.19Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Phone

Others

TOTAL



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/04/2020

User ID : CatherineLee

Section A - Accident Details

Registration Number	SG6128P
Case Reference Number	BUS/03/20/7017
Registration Date	5/4/2019
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95 EU6
Name of Driver	Nga Yook Lian
Type of Accident	Side Swipe
Accident Date and Time	18/3/2020 6:24 PM
Accident Reported Date and Time	19/3/2020 9:28 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24106254
Special Instruction to ARC, if any	SG6128P-RIGHT REAR PORTION FZ9255P (TP) INSURED WITH
Prepared Date and Time	19/3/2020 2:06 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$324.00	\$262.00
Total Spare Part Cost	\$1,358.19	\$1,358.19
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,477.19	\$2,150.19
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Kok Khoon Goh	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	19/03/2020 2:14 PM	20/03/2020 2:51 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/04/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS		\$795.00				\$530.00			
Total Labour		\$795.00				\$530.00			
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$324.00				\$262.00			
Total Spray Painting & Panel Beating		\$324.00				\$262.00			
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012636	VE		REVERSE LAMP BULB (A95 MAN)	1.00	\$235.00	10.00	\$211.50	Replace	Replace CRG
6010299			SIGNAL LAMP LED	1.00	\$1,274.10	10.00	\$1,146.69	Replace	Replace CRG
6013482	Body	124-2-2-009-012	O/S FRP REAR LAMP	1.00	\$975.00	100.00	\$0.00	Repair	Repair SVC
Total					\$2,484.10		\$1,358.19		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									