

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 31103

Vehicle Insured : SHC 733 H
Accident Date : 23-Mar-2020

Date : 24-Mar-2020

Our Ref : 020156 (FIRST) / QUEK

Not Notified

PAGE : 1

CDS CAR RENTAL PTE LTD
Singapore

*11 May 87
Paying After Repair 7 days*

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE MANUAL (2982cc)(2010) GBB7364U
=====

1 pc rear bumper	CM	415.00	✓
1 pc n/s rear bumper side retainer	N/A	30.00	✓
8 pcs rear bumper clips	@ S\$ 5.00	40.00	✓
2 pcs rear bumper lower bracket	@ S\$ 30.00	60.00	✓
1 pc n/s taillamp	CM	300.80	✓
1 pc n/s taillamp panel		248.00	?
1 pc n/s taillamp lower apron garnish	CM	100.00	✓
1 pc tailgate	B	2,150.00	✓
1 pc tailgate lock	N	275.00	X
1 pc tailgate weatherstrip	N	395.00	X
1 pc tailgate logo	N	55.00	✓
1 pc rear end panel - outer	B	331.70	✓
		4,400.50	
	Less 25% :	-1,100.13	

3,300.37

- 1 pc reverse sensor assy
- 1 pc tailgate glass sealant
- 1 pc tailgate '70km/h' sticker
- 1 pc tailgate '6pax' sticker
- 1 pc tailgate glass damping seal

<i>Red</i>	220.00	sn	✓
<i>N</i>	40.00	sn	✓
<i>N</i>	15.00	sn	✓
<i>N</i>	15.00	sn	✓
<i>N</i>	20.00	sn	✓

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

1,000.00 *Red*

To remove and renew rear windscreen
glass and conduct water leak test.

120.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental survey will be resurveyed and is subject to the insurance company

Acknowledged: _____
Signature: _____
Date: _____

Con't Page 2 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHC 733 H
Our Ref : 020156

Page : 2
No. : 31103

To transfer tailgate's fittings	80.00	601
To remove and refit reverse sensor assy.	60.00	501
To putty and respray on affected portions.	800.00	6801
To focus taillamps. To check rear wiring and lighting operation.	30.00	201
Total :	S\$ 5,700.37	

Singapore Dollars Five Thousand Seven Hundred
and Cents Thirty Seven Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.