

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Mar 2020 Sendback Est	24 Mar 2020 16:53 \$0.00	25 Mar 2020 13:38 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: TAN CHYE HOCK GERARD GARY , ID: SXXXX343H, Tel: +6581389648, Email: GARYTAN@RAMCE.COM.SG									
Vehicle Reg. No.: SME7635S		Date of Loss: 21/03/2020 18:00 - :59 [49 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM20D201476/SME7635S/BEN		Policy/Cover Note No.: DMPCSNW00007372000 (Comprehensive)							
		Excess: S\$4,500.00							
Repairer: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/04/2020]									
Driver/Custodian: TAN KHENG SOON DARYL (25 / Male) , NRIC: SXXXX310F, Tel: +6594506279 Email: DARYLMATTHIASTAN@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA_TAIPING (07/04/2020): Alert - Adj Mandate Approved (\$0.00) - SME7635S - Claim Handler: Ben Tang									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SME7635S (SNM20D201476/SME7635S/BEN)

OD

Mar 21 2020 6:00PM

[TAN CHYE HOCK GERARD GARY]

Jin Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports

1 per page

No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	24/03/20 16:53	Repairer Estimates		Load HTM	

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/03/20 10:42	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/03/20 09:36	General View		Load JPG	☒
2	26/03/20 09:36	General View		Load JPG	☒
3	26/03/20 09:36	General View		Load JPG	☒
4	26/03/20 09:36	General View		Load JPG	☒
5	26/03/20 09:36	General View		Load JPG	☒
6	26/03/20 09:36	General View		Load JPG	☒
7	26/03/20 09:36	General View		Load JPG	☒
8	26/03/20 09:36	General View		Load JPG	☒
9	26/03/20 09:36	General View		Load JPG	☒
10	26/03/20 09:36	General View		Load JPG	☒
11	26/03/20 09:36	General View		Load JPG	☒
12	26/03/20 09:36	General View		Load JPG	☒
13	26/03/20 09:36	General View		Load JPG	☒
14	26/03/20 09:36	General View		Load JPG	☒
15	26/03/20 09:36	General View		Load JPG	☒
16	26/03/20 09:36	General View		Load JPG	☒
17	26/03/20 09:36	General View		Load JPG	☒
18	26/03/20 09:36	General View		Load JPG	☒
19	26/03/20 09:36	General View		Load JPG	☒

Documentation

1 per page

No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	24/03/20 16:53	E-filed GIA report		Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/03/20 10:39	SME 7635S GIA.pdf		Load PDF	
2	08/04/20 09:10	TOTAL LOSS LETTER		Load PDF	
3	08/04/20 09:12	LTA REBATE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST
[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20004487/GSF3S2**Date:** 08/04/2020**REFERENCE**

Insured/Claimant:	TAN CHYE HOCK GERARD GARY	Policy No:	DMPCSNW00007372000		
Date of Loss:	21/03/2020	Nature of Claim:	OD	Claim No:	SNM20D201476/SME7635S/BEN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME7635S		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20Y158227
Reg. Date:	23/01/2016 (Man. Year: 2015)	Chassis No:	JF1SJ5KC5FG062447
Colour:	Silver	Odometer:	0 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	4,500.00	-4,500.00	
Nett Amount (S\$)	0.00	-4,500.00	4,500.00	

INSPECTION

Date of Assignment:	25/03/2020	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	25/03/2020	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	0.0 days		

Adjuster: XING GUO QIANG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$ 60,000.00
OMV :	\$ 14,573.00
PARF Rebate (1) :	\$ 10,929.00
Quota Premium Paid :	\$ 60,001.00
COE Rebate (2) :	\$ 34,952.00
Total Rebate (1) + (2) = :	\$ 45,881.00

The total amount incurred will be Market Value \$ 60,000.00 minus Total Rebate \$ 45,881.00 = \$14,119.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Apr 2020)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME7635S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >