LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ben Tang Date: 27 Mar 2020

Preliminary Advice

Vehicle No : SME7635S Accident Date : 21/03/2020

Make : SUBARU FORESTER Policy No. : DMPCSNW00007372000

Assignment Date : 25/03/2020 Excess : \$\$4,500.00

Date of Inspection : 25/03/2020 Est. Duration of Repair :-

Inspection At : Jin Auto Services Pte Ltd (Defu)

Blk 14 Defu Lane 10, #01-410/412

Singapore 539195

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ TOTAL LOSS
Revised Amount :S\$ TOTAL LOSS
Check Items (Estimated) :S\$ TOTAL LOSS
Total :S\$ TOTAL LOSS

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$
 60,000.00

 COE / PARF Rebate
 :S\$
 45,881.00

Salvage Value :S\$

Margin for Repair :S\$ 14,119.00

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
X)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments :