



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 31 Aug 2018 / 10:36:46

Receipt Date/Time : 31 Aug 2018 / 10:36:46

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180831-000566

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result: of Insurance Enquiry - SLB62T As at 31 Aug 2018/09:05:00 Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SLB62T Enquiry Fee 20180831103610190031	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
		xxxxxxxxxxxx2392	Credit Card: Visa/MasterCard	7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

TWINCAR RENTAL

Business Registration Number : 53092815M

Blk 2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 68420051 Fax : 67410510 email: sales@n51.com.sg

Invoice To :

CHUA CHUAN HENG
BLK 813 JURONG WEST ST 81
#04-176
SINGAPORE 640813

INVOICE

Invoice No. 13-2342

Date 11/9/2018

		Hirer's Car No.	VHA No.	Terms
		SLD932Y	71804	CASH
No. of Day	Description	Per Day	Amount (S\$)	
12	Car Rental from the period of 31/08/2018 to 11/09/2018. Vehicle no. SKT6805U Singapore Dollars One Thousand Four Hundred and Forty Only	120.00	1,440.00	
		Total	\$1,440.00	

TWINCAR RENTAL



Authorised Signature



TWINCAR RENTAL

Kaki Bukit Autohub @ 2 Kaki Bukit Ave. 2 #01-18
Singapore 417921 Tel: 6744 0510 / 6842 0051

VHA No: 71804 (6)

SID 9323

ROE NO. 53092815M

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR


Name: (as in I/C) CHUA CHUAN HENG
NRIC/PASSPORT No: S 0217731
Address (Res): BLK 813 JURONG WEST ST 91
04-176 S (640813)
Name & Address of Employer:
Occupation: Driving Exp:
Driving Licence No: S0217731 D/L Type: Local / International
Pass Date: 21/04/1997 Date of Birth: 20/02/1954
Tel: (O) (R) HP 9456 4945

ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C)
NRIC/PASSPORT No:
Address (Res):
Driving Licence No: D/L Type: Local / International
Pass Date: Date of Birth:
Occupation: Driving Exp:

VEHICLE CHECKLIST

INDICATE:
D - DENTS
S - SCRATCHES
A - ACCIDENTS



ACCESSORIES CHECK

☐ Ashtray ☐ Cig Lighter ☐ S/Tyre
☐ STD Tools ☐ Jack ☐ Hub Caps
☐ Radio / Cass ☐ CD ☐ Cartridges

Vehicle No: SKT 6805 V Replace Veh No:
Mileage Out: Mileage Out:
Make & Model: Toyota Auto/Manual
Group:
OUT: Date 31/08/18 Time: 1030 HRS
HIRE/PERIOD EXPIRY
NON-WAIVER EXCESS: \$

CHARGES

Daily	@ \$ 120	per day 12	1440	00
Weekly	@ \$	per week		
Monthly	@ \$	per month		
Hours	@ \$	per hour		
Others	@ \$			
CDW	@ \$	per day/month		
PAI	@ \$	per day/month		
Delivery Service				

SUB-TOTAL \$

PETROL LEVEL

Out	E	1/4	1/2	3/4	F	
In	E	1/4	1/2	3/4	F	

EXTENSION

Collection Service
Misc.

TOTAL CHARGE \$ 1440 00

Rented out by:

Hirer's Signature

Addition Driver's Signature

I have read and agree to the terms & condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given TWINCAR RENTAL in connection with this Agreement is true.

* IMPORTANT

- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY. AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY TWINCAR RENTAL.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO TWINCAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
11/09/2018	16:40 HRS				



Reg No : 196700C86Z
ST Reg No: MR-8500000-9

TAX INVOICE

n Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd
Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1189

Account Detail	Account No	Customer Detail
Bodyshop Retail Cash Sales Pandan TCBC Toyota	c0110038/PBPREG	Mr Chua Chuan Heng
Bodyshop Retail Cash Sales	Document No	813 Jurong West Street 81
Pandan TCBC Toyota	38016847	#04-176
	Document Date	Singapore 640813
	16/05/2017	Mobile: 94564945

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
6	GEXGKZ	S3	ZRE171R 02/06/2016	SLD0932Y	29492	25296	69CASH/SLD0932Y-PSF

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
RO53REH104549329	12RY279135	00	Raymond Seah L M	16/05/2017 14.27	16/05/2017 14.28	

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1 *	PSEINE-SEL PSEINE LABOUR FOR PLATINUM SHINE GLASS COATING RECOMMENDED MAINTENANCE AT \$40/SESSION UP TO 4 SESSIONS WITHIN 3 YEARS				568.22
1 *	PSEINE MAT PLATINUM SHINE SET				
2 X	TRADEIN-SF1 TRADE-IN OF TOYOTA SHINEPLUS PACKAGE (COMPLETE) FOR PLATINUM SHINE (PRO) PACKAGE LESS \$300 AFTER GST				-280.37
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.					

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 0.00	287.85
		Labour -280.37	GST 7.00% 20.15
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 568.22	Amount Due 309.00

PLEASE TEAR ALONG PERFORATED LINE

3400166

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

CHUA CHUAN HENG

BLK 813 JURONG WEST ST 81 #04-176

SINGAPORE 640813

Contact : 94564945

TAX INVOICE

Date : 05/10/2019

Date in : 31/03/2018

Vehicle Num. : SLD932Y

Make/Model : TOYOTA COROLLA ALTIS 1.6 CVT-2016

Chassis/Eng# : MR053REH104549329/1ZRY279135

Accident Date : 31/03/2018

Claim No : CLM14202

Reference : AUG-30/2018

Policy No. : VPA/P2120798 (01/06/2019)

LUMPSUM REPAIR BILL

AS PER SURVEYOR REPORT

REF : 0462-19-TCA DATED 30/09/2019

BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$

28,400.00

E. & O.E. Sub S\$: 28,400.00

Add GST (7%) S\$: 1,988.00

Total Amount S\$: 30,388.00



for TWINCAR AUTOMOTIVE PTE LTD

PAR Automotive Consultancy

Regn. No. 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0462-19-TCA

30 September 2019

Chua Chuan Heng
Blk 813 Jurong West St 81 #04-176
Singapore 640183

INVOICE No. **0462-19-TCA**


Vehicle No. **SLD932Y**

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$1,521.00
Total amount payable		\$1,521.00

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



Report No: 0462-19-TCA

30 September 2019

ACCIDENT VEHICLE SURVEY REPORT

Chua Chuan Heng
Blk 813 Jurong West St 81 #04-176
Singapore 640183

VEHICLE INFORMATION:

Vehicle Reg No.:	SLD932Y	Odometer:	64732km
Make & Model:	Toyota Corolla Altis 1.6 CVT	Colour:	Black
Chassis number:	MR053REH104549329	Date of accident:	31/08/2018
Year of Regn.:	02/06/2016	Date inspected:	31/08/2018
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	11/09/2018

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Michelin	5mm/Michelin	215/45ZR19
Rear:	5mm/Michelin	5mm/Michelin	215/45ZR19

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
AIRCON CONDENSER	1	bent	2,173.20	2,173.20
FRONT BONNET	1	buckled	1,140.40	1,140.40
FRONT BONNET HINGES L/R	2	bent	264.50	264.50
FRONT BONNET INNER RUBBER SEAL	1	deformed	62.70	62.70
FRONT BONNET INSULATOR	1	deformed	435.10	435.10
FRONT BONNET MECHANISM LOCK	1	bent	271.85	271.85
FRONT BRACE PANEL	1	bent	182.10	182.10
FRONT BUMPER	1	squashed	581.45	581.45
FRONT BUMPER FOGLAMP GARNISH L/R	2	necessary	382.70	382.70
FRONT BUMPER FOGLAMP L/R	2	fractured	579.80	579.80
FRONT BUMPER LOWER GRILLE	1	fractured	191.40	191.40
FRONT BUMPER REINFORCEMENT	1	bent	374.45	374.45
FRONT BUMPER SIDE RETAINER L/R	2	necessary	264.20	264.20
FRONT BUMPER SPONGE	1	deformed	186.10	186.10
FRONT BUMPER UNDER COVER	1	fractured	277.25	277.25
FRONT FENDER 'VVTI' EMBLEM L/R	2	necessary	90.20	90.20
FRONT GRILLE	1	fractured	595.90	595.90
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	65.45	65.45
FRONT GRILLE TOP GARNISH	1	reuse	92.00	0.00
FRONT GRILLE TOP RUBBER SEAL	1	deformed	81.90	81.90
FRONT HEADLAMP (L.E.D) L/R	2	fractured	5,886.00	5,886.00
FRONT HEADLAMP LOWER BRACKET L/R	2	bent	264.20	264.20
FRONT HEADLAMP MOULDING L/R	2	necessary	283.00	283.00
FRONT HORN HI & LOW	2	distortion	464.00	464.00
FRONT LH FENDER	1	repair	656.00	0.00
FRONT LH FENDER INNER SHIELD	1	reuse	161.30	0.00
FRONT SUPPORT PANEL	1	bent	2,121.40	2,121.40
RADIATOR (AUTO)	1	bent	2,142.30	2,142.30
RADIATOR CENTER TOP BRACKET	1	bent	155.30	155.30
RADIATOR FAN BLADE	1	warped	191.10	191.10
RADIATOR FAN COWLING	1	distorted	244.50	244.50
RADIATOR FAN MOTOR	1	shorted	394.40	394.40
RADIATOR TOP BRACKET L/R	2	bent	106.20	106.20
RADIATOR TOP MOUNTING L/R	2	distorted	151.40	151.40
REAR BOOTLID	1	buckled	781.10	781.10
REAR BOOTLID 'ALTIS' EMBLEM	1	necessary	54.10	54.10
REAR BOOTLID 'COROLLA' EMBLEM	1	necessary	50.20	50.20
REAR BOOTLID 'LOGO' EMBLEM	1	necessary	58.50	58.50
REAR BOOTLID HINGES L/R	2	bent	159.20	159.20
REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R	4	deformed	68.00	68.00
REAR BOOTLID INNER TRIM COVER	1	deformed	181.85	181.85
REAR BOOTLID LOCK STRIKER	1	bent	85.00	85.00

REAR BOOTLID MECHANISM LOCK	1	bent	379.20	379.20
REAR BOOTLID NUMBER PLATE LAMP L/R	2	fractured	46.00	46.00
REAR BOOTLID OUTER CHROME HANDLE	1	fractured	253.70	253.70
REAR BOOTLID OUTER LOCK SWITCH	1	shorted	65.20	65.20
RR BOOTLID REFLECTOR INNER BLACK RUBBER GASKET L/R	2	necessary	86.20	86.20
REAR BOOTLID REFLECTOR L/R	2	fractured	748.90	748.90
REAR BOOTLID WEATHERSTRIP	1	deformed	271.45	271.45
REAR BUMPER	1	squashed	581.90	581.90
REAR BUMPER REFLECTOR L/R	2	fractured	282.90	282.90
REAR BUMPER REINFORCEMENT	1	bent	398.70	398.70
REAR BUMPER REINFORCEMENT BRACKET L/R	2	bent	330.00	330.00
REAR BUMPER REVERSE SENSOR HOLDER	2	necessary	86.00	86.00
REAR BUMPER REVERSE SENSOR L/R	2	shorted	792.00	792.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS	1	reuse	715.20	0.00
REAR BUMPER SIDE RETAINER L/R	2	necessary	214.40	214.40
REAR END PANEL	1	buckled	781.90	781.90
REAR END PANEL ANTENNA SENSOR	1	shorted	175.00	175.00
REAR END PANEL INNER TOP GARNISH	1	fractured	391.60	391.60
REAR EXHAUST GASKET	1	necessary	63.20	63.20
REAR EXHAUST RUBBER MOUNTING	2	distorted	127.80	127.80
REAR EXHAUST SILENCER BOX	1	bent	1,255.00	1,255.00
REAR FENDER INNER TRIM L/R	2	deformed	676.00	676.00
REAR FLOOR PANEL	1	buckled	974.45	974.45
REAR FLOOR PANEL TOP BOARD COVER	1	deformed	485.10	485.10
REAR FLOOR SIDE PANEL LH	1	repair	348.90	0.00
REAR LH BODY SUB FRAME	1	repair	384.30	0.00
REAR LH DOOR	1	repair	958.70	0.00
REAR LH DOOR BLACK FRAME STICKER	1	reuse	142.50	0.00
REAR LH DOOR INNER SEAL COVER	1	reuse	78.00	0.00
REAR LH DOOR INNER TRIM BOARD	1	reuse	763.20	0.00
REAR LH DOOR MECHANISM LOCK	1	bent	431.60	431.60
REAR LH DOOR WEATHERSTRIP	1	deformed	168.40	168.40
REAR LH FENDER	1	repair	987.40	0.00
REAR LH FENDER AIR VENT	1	reuse	117.33	0.00
REAR LH FENDER INNER SHEILD	1	reuse	231.35	0.00
REAR LH FENDER PETROL LID RIVET	2	reuse	25.80	0.00
REAR SPARE TYRE SCREW LOCK	1	bent	79.60	79.60
REAR TAILLAMP INNER BLACK RUBBER GASKET L/R	2	necessary	51.00	51.00
REAR TAILLAMP INNER PANEL L/R	2	repair	748.90	0.00
REAR TAILLAMP L/R	2	fractured	783.80	783.80
REAR TAILLAMP LOWER BRACKET L/R	2	necessary	177.40	177.40
REAR WINDSCREEN SEAL	1	reuse	138.00	0.00

Subtotal before discount S\$ 39,749.68 S\$ 33,200.80

Percentage discount 25% and 25% S\$ 9,937.42 S\$ 8,300.20

Sub-total 1 S\$ 29,812.26 S\$ 24,900.60

FRONT BONNET INSULATOR CLIPS - SET	1	necessary	60.00	60.00
FRONT BUMPER CLIPS - SET	1	necessary	80.00	80.00
FRONT BUMPER NUMBER PLATE	1	bent	25.00	25.00
FRONT BUMPER NUMBER PLATE HOLDER	1	bent	50.00	50.00
FRONT BUMPER UNDER COVER CLIPS - SET	1	necessary	40.00	40.00
FRONT GRILLE TOP GARNISH CLIPS - SET	1	necessary	40.00	40.00
FRONT LH FENDER INNER SHIELD CLIPS - SET	1	necessary	50.00	50.00
RADIATOR COOLANT	1	necessary	60.00	60.00
REAR BOOTLID CAMERA	1	shorted	800.00	800.00
REAR BOOTLID INNER TRIM COVER CLIPS - SET	1	necessary	50.00	50.00
REAR BOOTLID NUMBER PLATE	1	bent	25.00	25.00
REAR BOOTLID NUMBER PLATE HOLDER	1	bent	50.00	50.00
REAR BOOTLID OUTER CHROME HANDLE CLIPS - SET	1	necessary	40.00	40.00
REAR BUMPER CLIPS - SET	1	necessary	80.00	80.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	30.00	30.00
REAR FENDER INNER SHIELD CLIPS L/R - SET	2	necessary	60.00	60.00
REAR FENDER INNER TRIM CLIPS L/R - SET	2	necessary	100.00	100.00
REAR FLOOR PANEL INSULATOR MAT	1	necessary	300.00	300.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET	1	necessary	50.00	50.00
REAR TAILLAMP CLIPS L/R - SET	2	necessary	40.00	40.00
REAR WINDSCREEN SEALANT	1	reuse	80.00	0.00

Subtotal before discount S\$ 2,110.00 S\$ 2,030.00

Sub-total 2 S\$ 2,110.00 S\$ 2,030.00

Parts-total S\$ 31,922.26 S\$ 26,930.60

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	150.00	120.00
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	100.00	80.00
To remove, reinstall windscreen (REAR)	150.00	0.00
To remove, reinstall petrol tank. (to FR)	80.00	0.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	60.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel, rear bumper, rear doors (L/R), and roof top panel.	2,100.00	1,540.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	1,300.00	1,100.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	120.00	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	3,800.00	3,000.00
To mount vehicle on to Car 'O' Liner.	300.00	300.00
To apply anti-rust chemical on repaired and replaced panel.	150.00	150.00
To transfer rear bootlid mechanism lock outer handle reflector and other attachment parts.	50.00	50.00

Labour Total S\$ 8,440.00 S\$ 6,500.00

Parts & Labour Total S\$ 40,362.26 S\$ 33,430.60

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

**Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 28,400.00
and the recommended number of working days for the repairs is within 13 day(s).**



B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-176400

Date of Request: 14/11/2018

Your Ref No: AKN-INS-T140-107889-18-AT

VISION LAW LLC
133 New Bridge Road #18-01/02
Chinatown Point
Singapore 059413

Dear Sir/Madam,

Date of Accident: 31/08/2018
Vehicle No: SLD932Y
Place of Accident: PIE TOWARDS CHANGI AFTER 6 TOA PAYOH
Involving Vehicle No: SLB62T

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLB62T	PIE TOWARDS CHANGI AFTER 6 TOA PAYOH	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque