

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33391

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0308/2020/NS
Date	:	20-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

11 days exclude 1 Sunday

jb 9 Jul 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mrs Lee Bee Ling
Address	:	73 Anchorvale Crescent #01-06 Singapore 544661
Telephone	:	HP +65 92326679
Type of Claim	:	Own Damage Claim
Policy No.	:	2100491866-03
Vehicle No	:	SLJ 927 G
Model Code	:	Audi Q5 2.0 TFSI qu
Model / Year	:	Nov-16
Engine No	:	CNC 174517
Chassis No	:	WAUZZZ8R7HA028904
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Mar-20
Place of Accident	:	Along KPE Towards City

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLJ 927 G

S/N	Nature of Jobs		Estimated Charges	Surveyor's commendations
1	To remove and transfer rear parking aid. Check function.	S/N \$	280.00	\$ 280.00
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$	480.00	\$ 480.00
3	To renew rear windscreen.	S/N \$	480.00	\$ 480.00
4	To install solar film for rear windscreen.	S/N \$	400.00	\$ 400.00
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. Inspect for damages and renew where necessary.	S/N \$	480.00	
SUB TOTAL LABOUR CHARGES		:	\$ 2,120.00	\$ 1,640.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLJ 927 G

S/N	Nature of Jobs		Estimated Charges	Surveyor's recommendations
				\$ 1,640.00
6	To dismantle and renew rear bumper and rear lid. To cut out and welded end panelling. Re-organise rear crash management components. Reinstall all parts removed.	C/F \$	4,800.00	\$ 1,500.00
7	To respray rear bumper, rear lower spoiler, rear lid, hinges, rear end panelling and spare wheel housing.	\$	5,000.00	\$ 1,950.00
8	To renew both rear exhaust silencer and centre silencer. To align to position.	S/N \$	480.00	\$ 480.00
9	Added labour - see attached	\$	3,080.00	\$ 3,080.00
10	Added labour - see attached	\$	240.00	\$ 240.00
11	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES			: \$ 15,912.00	\$ 9,082.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 927 G

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER	\$ 1,560.00	\$ 1,248.00
2	REAR BUMPER FIXING PARTS	\$ 156.00	
3	REAR BUMPER GUIDE SECTION - LH	\$ 51.00	\$ 40.48
4	REAR BUMPER SPOILER	\$ 815.00	\$ 651.60
5	REAR BUMPER TAIL LIGHT - LH	\$ 282.00	\$ 225.20
6	TAIL LIGHT - LH	\$ 1,371.00	
7	TAIL LIGHT COVER - LH	\$ 46.00	
8	REAR BUMPER CARRIER	\$ 617.00	\$ 493.20
9	REAR BUMPER BRACKET HOLDER - LH / RH	2 \$ 404.00	
10	REAR PARKING AID SENSOR - INNER / OUTER	2 TBC	
11	REAR BUMPER WIRING SET	\$ 544.00	
12	REAR LID	\$ 4,046.00	\$ 3,236.80
13	REAR LID ATTACHMENT PARTS	\$ 117.00	
14	REAR LID HINGE - LH / RH	2 \$ 432.00	\$ 172.40
15	REAR LID GAS FILLED STRUT	2 \$ 224.00	
16	REAR LID FLAP GASKET	\$ 193.00	
17	REAR LID LOCK	\$ 167.00	
18	LID LOCK PUSH BUTTON	\$ 170.00	
19	REAR LID STRIKER PLATE	\$ 834.00	
20	REAR LID DRIVE UNIT - LH	\$ 1,885.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 13,914.00	\$ 6,067.68

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 927 G

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>		\$ 6,067.68
21	REAR LID DECORATIVE TRIM		\$ 410.00	\$ 328.00
22	SPOILER FIXING PARTS		\$ 156.00	
23	PACKING ADHESIVE		\$ 18.00	\$ 14.24
24	AUDI EMBLEM		\$ 117.00	\$ 93.20
25	Q5 INSCRIPTION		\$ 90.00	\$ 71.76
26	TFSI INSCRIPTION		\$ 90.00	\$ 71.76
27	QUATTRO INSCRIPTION		\$ 90.00	\$ 71.76
28	REAR WINDSCREEN		\$ 1,066.00	\$ 852.80
29	PRIMER		\$ 19.00	\$ 14.80
30	REAR CROSS PANEL		\$ 480.00	
31	LOCK CARRIER REINFORCEMENT		\$ 1,048.00	
32	CORNER REINFORCEMENT - LH		\$ 68.00	
33	REAR CROSS PANEL TRIM		\$ 323.00	
34	REAR SILENCER - LH		\$ 928.00	\$ 742.40
35	REAR SILENCER DUAL CLIP		\$ 53.00	\$ 41.92
36	REAR SILENCER BRACKET - LH / RH	2	\$ 108.00	\$ 42.80
37	REAR SILENCER - RH		\$ 928.00	
38	REAR SILENCER DUAL CLIP		\$ 53.00	
39	REAR SILENCER BRACKET - LH / RH	2	\$ 108.00	
40	CENTRE SILENCER		\$ 920.00	\$ 736.00
SUB TOTAL SPARE PARTS CHARGES			\$ 7,073.00	\$ 9,149.12

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 927 G

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/Nett	Remarks
				\$ 9,149.12
41	CENTRE SILENCER DUAL CLIP		\$ 57.00	\$ 44.96
42	CENTRE SILENCER DUAL CLIP	2	\$ 105.00	
43	CENTRE SILENCER BRACKET - LH / RH FRONT	2	\$ 84.00	\$ 33.28
44	REAR SILENCER HEAT SHIELD - LH / RH	2	\$ 292.00	
45	CENTRE SILENCER HEAT SHIELD		\$ 222.00	
46	WHEEL HOUSING LINER - LH REAR		\$ 248.00	\$ 198.40
47	REAR NO PLATE	S/N	\$ 60.00	
48	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
49	ACRYLIC SEALANT	S/N	\$ 180.00	
50	CAVITY WAX	S/N	\$ 140.00	
51	STONE SHIP	S/N	\$ 180.00	
52	Added parts - see attached		\$ 3,096.00	\$ 2,476.80
54	SUNDRIES		\$ 400.00	\$ 88.32
TOTAL SPARE PARTS CHARGES			: \$ 26,251.00	\$ 12,190.88
TOTAL LABOUR CHARGES			: \$ 15,912.00	\$ 9,082.00
GRAND TOTAL			: \$ 42,163.00	\$ 21,272.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0308/2020/NS 09-Jun-20 Glory Tan 1 of 1 SLJ 927 G Audi Q5 2.0 TFSI qu
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Rear subframe	\$ 3,096.00	\$ 2,476.80
<u>Labours</u>			
1	To remove and reinstall s/n exhaust system and rear suspension assembly, including rear axle and propellor shaft. Renew accordingly.	2800	\$ 2,800.00
2	To dislodge rear roof panel trim s/n to facilitate rear lid renewal.	\$ 280.00	\$ 280.00
TOTAL		\$ 6,176.00	\$ 5,556.80

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0308/2020/NS 16-Jun-20 Glory Tan 1 of 1 SLJ 927 G Audi Q5 2.0 TFSI qu
Quantity	Description	Unit Price	Amount
<u>Labours</u> 1	To carry out wheel alignment.	\$ 240.00	\$ 240.00
TOTAL		\$ 240.00	\$ 240.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant