

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33704

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0319/2020/NS
Date : 24-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Sim Hua Soon Shen Huashun
Address : Blk 51 New Upper Changi Road
#12-1514
Singapore 461051
Telephone : +65 97590416
Type of Claim : Own Damage Claims
Policy No. : 2070036793
Vehicle No : **SGU 2230 X**
Model Code : Audi A3 Sportsback 1.0 TF
Model / Year : Mar-20
Engine No : CHZ C38104
Chassis No : WAUZZZ8V3LA034964
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Mar-20
Place of Accident : PIE Towards CTE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGU 2230 X

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00 ✓	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	2,450.00 1250. ✓	✓
3	To respray front bumper and rhs front fender.	\$	2,000.00 1100 ✓	✓
4	To carry out pre-diagnostic check and post-diagnostic check.	S/N \$	384.00 192 ✓	192 ✓
TOTAL LABOUR CHARGES		:	<u>\$ 5,194.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 2230 X

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Regr</i>	\$ 1,756.00	X
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 176.00	X
3	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 36.00	X
4	FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	\$ 280.00	X
5	FRONT FENDER - RH <i>Buckled.</i>	\$ 802.00	641.20
6	FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$ 68.00	X
7	LED HEADLIGHT - RH <i>cracked.</i>	\$ 5,193.00	4154.40
8	LED WITH HEAT SINK - RH ?	\$ 689.00	? X nn
9	MAIN LIGHT ELECTRONICS POWER MODULE - RH ?	\$ 714.00	? X nn
10	LIGHT CONTROL SYSTEM CONTROL UNIT ?	\$ 524.00	? X nn
11	HEADLIGHT HOSE - RH ? <i>new</i>	\$ 38.00	X X nn
12	LIFT CYLINDER - RH <i>new</i>	\$ 134.00	X X nn
13	SUNDRIES ?	\$ <i>nee</i> 200.00	? 25.60
TOTAL SPARE PARTS CHARGES		\$ 10,610.00	
TOTAL LABOUR CHARGES		\$ 5,194.00	
GRAND TOTAL		\$ 15,804.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adria Lij
Surveyed Date : 25/03/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant