



新福德車廠私人有限公司 - AIG - LKK - ATRELAX

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

24-03-2020

01-43

Singapore 417883

TPAIG.

Khanchana.

FEB21EA20959

Accident date: 23/03/2020

Estimated repair cost for vehicle no: YP4550Y MITSUBISHI CANTER FEB21ER4SDEB

CHASSIS: FEB21EA20959

3.0 M '16

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Corner Panel <i>cutted</i>		\$506.00 ✓
2	1	Front R/H Head Lamp <i>cutted</i>		\$501.00 ✓
3	1	Front R/H Signal Lamp <i>cutted</i>		\$266.00 ✓
4	1	Front R/H Side Lamp <i>cutted</i>		\$251.00 ✓
5	1	Front Bumper <i>new</i>		\$1,060.00 ✗
6	1	Front R/H Bumper Side Cover <i>cut</i>		\$341.00 ✓
7	1	Front R/H Door <i>Painted</i>		\$2,070.00 ✓
8	1	Front R/H Step Panel <i>new</i>		\$613.00 ✗

3935

2951.25

Subtotal :- \$5,608.00

Labour charges

To remove & refit front R/H door and door components	\$280.00 <i>80</i>
To check wiring	\$100.00 <i>30</i>
Tuff kote	\$100.00 ✗ <i>810</i>
Panel beating	\$800.00 <i>350</i>
Spray painting	\$1,000.00 <i>350</i>

Total: 3761.25

4/5 3K

048up

3K

Subtotal :- \$2,280.00

Total:- \$7,888.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: