

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

SERVICE ESTIMATE

- C00001
Mr Chua Yew Gee Roland
Blk 10 Tao Ching Road
#19-23

Singapore 618725

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Chua Yew Gee Rola

GST Reg.No: M28920628X

Inv.No. . : B&P 0 Page 1
Inv.date. : 24/03/2020
WIP No. . : 15236
Veh.In/Out:
*Tel.No. . : Mobile: 98456431
Reg.No. . : SKZ1923M
Reg.date . : 30/09/2019
Mileage .. : 0
Chassis No: VF1RFA00862895230

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER, ETC.	0		1600.00	0		1,600.00 S	450
800	TO PUTTY AND SPRAY PAINT ON FRONT BUMPER, ETC.	0		1400.00	0		1,400.00 S	400
0031	TO REPLACE LHF RIM	0		50.00	0		50.00 S	
419	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	0		280.00	0		280.00 S	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0		375.00	0		375.00 S	X nn
	BUMPER FRT GS4 repair	1.0	EA	1182.60			1,182.60 S	
	FOG LAMP MOULDING OU	1.0	EA	192.70			192.70 S	
	FOG LAMP COVER CHORM	1.0	EA	192.70			192.70 S	
	BUMPER LOWER FRT GS4	1.0	EA	395.90			395.90 S	
	BUMPER BRACKET FRT L	1.0	EA	113.90			113.90 S	
	BUMPER BRACKET FRT R	1.0	EA	113.90			113.90 S	
	ALLOY RIM 20" INCH GS	1.0	EA	1068.60			1,068.60 S	990.63
	TYRE PRESSURE SENSOR	1.0	EA	117.30			117.30 S	108.81

Gross Total. 7,082.60

Labour Total 3,705.00
Parts Total 3,377.60
Package Total 0.00

Net..... 7,082.60
GST @ 7.0% 495.78
Total..... 7,578.40
Paid..... 0.00
Please Pay.. 7,578.40

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Passer
Up 9001068
3 days
21/07/2020 @ 1000
Rery after repair