

Repair Estimate

Date : 21/03/2020

Reference: SMC 1660T
Make: ~~Opel~~
~~Astra~~

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SMC 1660T
CHASSIS NO. JM6BN22A8J0215041
ENGINE NO.: P520504716

TP All
Khanhha

Name of insured : Alpine Car Rental Pte Ltd
Date of accident.: 18/03/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER <i>red</i>	710.00 ✓
2	1	FRT BUMPER SIDE RETAINER RH, Guide <i>Def</i>	70.00 ✓
3	1	FRT BUMPER CLIP SET - Rivet <i>ac</i>	30.00 ✓
4	1	RH HEADLAMP <i>at</i>	790.00 ✓
5	1	FRT FENDER RH <i>Detel</i>	390.00 ✓
6	1	FRT RH FOG LAMP <i>for</i>	320.00 +
7	1	FRT RH FOG LAMP COVER <i>for</i>	70.00 +
Parts Total:			2,380.00
Less 20%:			238.00
Total :			2,142.00

1930
1592

Labour No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	800.00 <i>400</i>
2	Carry out spray painting on accident affected area. (Frt bumper, RHF Fender)	7000.00 <i>400</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	40.00 <i>30</i>
4	To conduct 4 wheel alignment	50.00 <i>x</i>
Labour Total :		7,890.00

Admin Lj
P/P 24/03/20
04 hrs.

total: 2422 ✓
(P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: