

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates	GBE 2665 T	Not Nothanh Returns After Par
Parts (a) Cost / List Price Items Plus/Less Total of Cost / List (b) Nett Price Items Less Total of Nett Item (c) Special Nett Items Total Parts Cost Labour Total The above total will be subjected to items	\$ 650.00 \$ 650.00	LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
Name of Surveyor		Kenneth
Company	L T.	CKIC

Company : \(\frac{\lambda \lambda \la



GBE 2665 T

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Carmen Lim

Submit By

Labour

Vehicle No.

Make	& Model : NISSAN NV350 Year of Manufacture	:	2014
S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (FRONT BUMPER)	\$300.00	
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (FRONT BUMPER)	\$300.00	2001
3	To check wiring, focus headlamp	\$50.00	10/

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.