

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
 TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

Not Authorized

Resurvey B4 paint

1-B-1

4-5 days

CYCLOPS CARS PTE LTD
 c/o 46 Lentor Plain
 Singapore 786548

Date: 24/3/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA NOAH / SMP 3165 A		
1 pc	Rear tail door	<i>B1</i> 1,983.90 ✓
1 pc	Rear tail door lock	<i>n</i> 242.50 X
1 pc	Rear tail door lock catch	<i>n</i> 86.50 X
1 pc	Rear tail door windscreen glass moulding	<i>net</i> 242.20 ✓
1 pc	Rear tail door emblem "HYBRID SYNERGY DRIVE"	<i>net</i> 78.40 ✓
1 pc	Rear tail door inner trim	<i>sn</i> 364.50 X
1 pc	Rear tail door lock sensor	274.30 ?
1 pc	Rear bumper	<i>net</i> 1,065.30 ✓
1/2 pcs	Rear bumper park sensor	@ 275.40 <i>net</i> 550.80 ✓
1 pc	Rear bumper reflector	<i>sn</i> 153.30 X
1 pc	Rear bumper impact sponge	364.70 ?
1 pc	Rear bumper reinforcement beam	374.40 ?
1 pc	Rear bumper side retainer	<i>sn</i> 68.60 X
1 pc	Rear end panel - outer	564.30 ?
1 pc	Rear end panel - inner	<i>n</i> 658.20 X
1 pc	Rear end panel top trim	263.20 ?
1 pc	Rear end panel weatherstrip	311.40 ?
	sub-total	7,646.50
	less 25%	1911.63
	sub-total	5734.88
2 pcs	windscreen glass sealant	nett @ 120.00 <i>net</i> 240.00 <i>4032</i>
	sub-total	5974.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	balance brought forward	5,974.88
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	1200.00 7
	To check wiring system.	60.00 201
	To apply rust proofing on affected areas.	120.00 7
	To apply waterproof sealant on affected areas.	120.00 7
	To remove rear windscreen glass(es) to enable repair.	150.00 1202
	To install reverse sensors & reverse camera.	80.00 501
	To remove carpet, trimming to enable repair.	120.00 601
	To apply putty and spray painting on affected areas.	770.00 6001
	Total	8,594.88