

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
 TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

Not Notified

Resurvey B4 paint

~~1st~~

4-5 days

CYCLOPS CARS PTE LTD
 c/o 46 Lentor Plain
 Singapore 786548

L/sum \$3,850.00

Date: 24/3/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA NOAH / SMP 3165 A		
1 pc	Rear tail door \$1,561.90	Rt 1,983.90 ✓
1 pc	Rear tail door lock	R 242.50 X
1 pc	Rear tail door lock catch	R 86.50 X
1 pc	Rear tail door windscreen glass moulding	Ru 242.20 ✓
1 pc	Rear tail door emblem "HYBRID SYNERGY DRIVE"	Ru 78.40 ✓
1 pc	Rear tail door inner trim	Ru 364.50 X
1 pc	Rear tail door lock sensor	Dd 274.30 ✓
1 pc	Rear bumper \$730.95	Ru 1,065.30 ✓
2 pcs	Rear bumper park sensor @ 275.40	Ru 550.80 ✓
1 pc	Rear bumper reflector	Ru 153.30 X
1 pc	Rear bumper impact sponge	NSP 364.70 X
1 pc	Rear bumper reinforcement beam	NSP 374.40 X
1 pc	Rear bumper side retainer	Ru 68.60 X
1 pc	Rear end panel - outer	Bt 564.30 ✓
1 pc	Rear end panel - inner	R 658.20 X
1 pc	Rear end panel top trim	Buc 263.20 ✓
1 pc	Rear end panel weatherstrip	Dd/ Dis 311.40 ✓
	sub-total	7,646.50
	less 25%	1911.63
	sub-total	5734.88
2 pcs	windscreen glass sealant	nett @ 120.00 Ru 240.00 ✓
	sub-total	5974.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

	balance brought forward		5,974.88	
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.		1200.00	7600
	To check wiring system.		60.00	201
	To apply rust proofing on affected areas.		120.00	760
	To apply waterproof sealant on affected areas.		120.00	730
	To remove rear windscreen glass(es) to enable repair.		150.00	1202
	To install reverse sensors & reverse camera.		80.00	501
	To remove carpet, trimming to enable repair.		120.00	601
	To apply putty and spray painting on affected areas.		770.00	6001
		Total	8,594.88	