



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2003909
INV Date 14/05/2020
Reference CS/AGI20004539/Atd3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SLG 6630M

Insured Veh. SLR 5165M

Claim No. C10006041

Policy No.

Accident Date 25/03/2020

Inspection Date 26/03/2020

| Description | Total |
|---------------------|---------------|
| Survey Inspection | 350.00 |
| Resurvey Inspection | |
| Digital Photographs | |
| Transportation | |
| Subtotal | 350.00 |
| GST (7%) | 24.50 |
| Grand Total | 374.50 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20004539/Atd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 14-05-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|-------------|-----------------------|------------|
| Insured Veh. | SLR 5165M | Veh. Inspected | SLG 6630M |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | C10006041 | Excess (\$) | 0.00 |
| Assign From | IVY RATILLA | Assign Date | 26/03/2020 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|------------|
| Make & Model | TOYOTA ALTIS | c.c | 1598 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | MR053REH104558556 | Colour | SILVER |
| Odometer | 194785 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | | | |
|-----------------------|-------------|-------------|----------------|
| | Size | Make | Balance |
| R/H Front Tyre | 205/55 R16 | HABILEAD | 6 mm |
| L/H Front Tyre | 205/55 R16 | HABILEAD | 6 mm |
| R/H Rear Tyre | 205/55 R16 | HABILEAD | 6 mm |
| L/H Rear Tyre | 205/55 R16 | HABILEAD | 6 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|-----------------------|---|------------------------|------------|
| Accident Date | 25/03/2020 | Inspection Date | 26/03/2020 |
| Survey held at | N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 7 Working Days |
|-------------------------------------|-----------------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 6630M

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FRONT RH DOOR | DISTORTED | 1,135.00 | 1,135.00 |
| 1 | FRONT RH DOOR BLACK FRAME TAPE | NECESSARY | 63.00 | 63.00 |
| 1 | FRONT RH DOOR GLASS CHANNEL BRACKET | NOT NECESSARY | 97.00 | - |
| 1 | FRONT RH DOOR GLASS CHANNEL WEATHER STRIP | NOT NECESSARY | 97.00 | - |
| 2 | FRONT RH DOOR INNER RUBBER GUIDE STOPPER @ \$25.00 | NOT NECESSARY | 50.00 | - |
| 1 | FRONT RH DOOR MECHANISM LOCK | DAMAGED | 427.00 | 427.00 |
| 1 | FRONT RH DOOR OUTER CHROME MOULDING | NOT NECESSARY | 97.00 | - |
| 1 | FRONT RH DOOR OUTER FRAME GARNISH (VERTICAL) | NECESSARY | 99.00 | 99.00 |
| 1 | FRONT RH DOOR OUTER HANDLE | NOT NECESSARY | 153.00 | - |
| 1 | FRONT RH DOOR OUTER HANDLE INNER BRACKET | NOT NECESSARY | 147.00 | - |
| 1 | FRONT RH DOOR OUTER HANDLE INNER RUBBER GASKET SEAL | NOT NECESSARY | 35.00 | - |
| 1 | FRONT RH DOOR OUTER HANDLE KNOB COVER | NOT NECESSARY | 35.00 | - |
| 1 | FRONT RH DOOR OUTER HANDLE KNOB COVER INNER RUBBER GASKET SEAL | NOT NECESSARY | 35.00 | - |
| 1 | FRONT RH DOOR REGULATOR | DAMAGED | 213.00 | 213.00 |
| 1 | FRONT RH DOOR WEATHER STRIP | CUT | 183.00 | 183.00 |
| 1 | REAR RH ARCH PANEL | TO REPAIR SEE LABOUR | 917.00 | - |
| 1 | REAR RH DOOR | DENTED | 1,175.00 | 1,175.00 |
| 1 | REAR RH DOOR BLACK FRAME TAPE | NECESSARY | 63.00 | 63.00 |
| 1 | REAR RH DOOR CHECKER | NOT NECESSARY | 127.00 | - |
| 1 | REAR RH DOOR GLASS CHANNEL BRACKET | NOT NECESSARY | 97.00 | - |
| 1 | REAR RH DOOR GLASS CHANNEL WEATHER STRIP | NOT NECESSARY | 97.00 | - |
| 1 | REAR RH DOOR GLASS REGULATOR | DAMAGED | 217.00 | 217.00 |
| 1 | REAR RH DOOR GLASS REGULATOR MOTOR | NOT NECESSARY | 547.00 | - |
| 2 | REAR RH DOOR HINGES (TOP & LOWER) @ \$67.00 | BENT | 134.00 | 134.00 |
| 2 | REAR RH DOOR INNER RUBBER GUIDE STOPPER @ \$25.00 | NOT NECESSARY | 50.00 | - |
| 1 | REAR RH DOOR INNER TRIM BOARD | CRACKED | 975.00 | 698.00 |
| 1 | REAR RH DOOR MECHANISM LOCK | NOT NECESSARY | 563.00 | - |

Report Ref No. CS/AGI20004539/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
| 1 | REAR RH DOOR OUTER CHROME MOULDING | NOT NECESSARY | 121.00 | - |
| 1 | REAR RH DOOR OUTER FRAME GARNISH (VERTICAL) | NECESSARY | 97.00 | 97.00 |
| 1 | REAR RH DOOR WEATHER STRIP | CUT | 183.00 | 183.00 |
| 1 | ROCKER PANEL RH | DENTED | 508.00 | 508.00 |
| 1 | ROCKER PANEL RH MOULDING | DEFORMED | 268.70 | 268.70 |
| | LESS 25% DISCOUNT | | -2,251.43 | -1,365.93 |
| | | | 6,754.27 | 4,097.77 |
| 1 | REAR RH SPORT RIM (SN) | CUT | 2,010.70 | 850.00 |
| | LESS 25% DISCOUNT | | -502.68 | - |
| | | | 1,508.02 | 850.00 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SET FRONT RH DOOR INNER TRIM BOARD CLIPS (SN) | NOT NECESSARY | 50.00 | - |
| 1 | SET REAR RH DOOR INNER TRIM BOARD CLIPS (SN) | NECESSARY | 50.00 | 30.00 |
| | | | 100.00 | 30.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR). | | 140.00 | 60.00 |
| | TO TRANSFER DOOR GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL TRIM BOARD,MECHANISM LOCK AND HANDLE. | | 200.00 | 160.00 |
| | TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT. | | 1,200.00 | 1,000.00 |
| | TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR RH ARCH PANEL. | | 1,600.00 | 1,000.00 |
| | TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL. | | 100.00 | 60.00 |
| | | | 3,240.00 | 2,280.00 |
| | GRAND TOTAL | | 11,602.29 | 7,257.77 |

Report Ref No. CS/AGI20004539/Atd3n2



| | | | |
|---|--|--|-----------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 5,800.00 |
|---|--|--|-----------------|

Report Ref No. CS/AGI20004539/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLG 6630M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLG 6630M

RE-INSPECTION

