

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

TP Budget Direct.
Denise.

Contact : 66550005-GRAB 90686405

ESTIMATE

Repair Code : CLM16162

Date in : 25/03/2020

Vehicle Num. : SLG6630M

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104558556/1ZRY334249

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Dented.</i>	1	1135.00	✓ 1,135.00
FRONT RH DOOR BLACK FRAME TAPE <i>neu</i>	1	63.00	✓ 63.00
FRONT RH DOOR GLASS CHANNEL BRACKET <i>neu</i>	1	97.00	+ 97.00
FRONT RH DOOR GLASS CHANNEL WEATHER STRIP <i>neu</i>	1	97.00	+ 97.00
FRONT RH DOOR INNER RUBBER GUIDE STOPPER <i>neu</i>	2	25.00	+ 50.00
FRONT RH DOOR MECHANISM LOCK <i>Dented</i>	1	427.00	✓ 427.00
FRONT RH DOOR OUTER CHROME MOULDING <i>neu</i>	1	97.00	+ 97.00
FRONT RH DOOR OUTER FRAME GARNISH (VERTICAL) <i>neu</i>	1	99.00	✓ 99.00
FRONT RH DOOR OUTER HANDLE <i>neu</i>	1	153.00	+ 153.00
FRONT RH DOOR OUTER HANDLE INNER BRACKET <i>neu</i>	1	147.00	+ 147.00
FRONT RH DOOR OUTER HANDLE INNER RUBBER GASKET SEAL <i>neu</i>	1	35.00	+ 35.00
FRONT RH DOOR OUTER HANDLE KNOB COVER <i>neu</i>	1	35.00	+ 35.00
FRONT RH DOOR OUTER HANDLE KNOB COVER INNER RUBBER GASKET SEAL <i>neu</i>	1	35.00	+ 35.00
FRONT RH DOOR REGULATOR <i>Dented.</i>	1	213.00	✓ 213.00
FRONT RH DOOR WEATHER STRIP <i>LT</i>	1	183.00	✓ 183.00
REAR RH ARCH PANEL <i>R, is</i>	1	917.00	+ 917.00
REAR RH DOOR <i>Dented.</i>	1	1175.00	✓ 1,175.00
REAR RH DOOR BLACK FRAME TAPE <i>neu</i>	1	63.00	✓ 63.00

51 AUTOMOTIVE PTE LTD

Bukit AutoHub
 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 90686405

ESTIMATE

Repair Code : CLM16162

Date in : 25/03/2020

Vehicle Num. : SLG6630M

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104558556/1ZRY334249

REAR RH DOOR CHECKER <i>neu</i>	1	127.00	X	X 127.00
REAR RH DOOR GLASS CHANNEL BRACKET <i>neu</i>	1	97.00	+	97.00
REAR RH DOOR GLASS CHANNEL WEATHER STRIP <i>neu</i>	1	97.00	+	97.00
REAR RH DOOR GLASS REGULATOR <i>Dand</i>	1	217.00	✓	217.00
REAR RH DOOR GLASS REGULATOR MOTOR <i>neu</i>	1	547.00	+	547.00
REAR RH DOOR HINGES (TOP & LOWER) <i>Best</i>	2	67.00	✓	134.00
REAR RH DOOR INNER RUBBER GUIDE STOPPER <i>neu</i>	2	25.00	+	50.00
REAR RH DOOR INNER TRIM BOARD <i>anld</i>	1	975.00	698	975.00
REAR RH DOOR MECHANISM LOCK <i>neu</i>	1	563.00	+	563.00
REAR RH DOOR OUTER CHROME MOULDING <i>neu</i>	1	121.00	+	121.00
REAR RH DOOR OUTER FRAME GARNISH (VERTICAL) <i>neu</i>	1	97.00	✓	97.00
REAR RH DOOR WEATHER STRIP <i>ut.</i>	1	183.00	✓	183.00
REAR RH SPORT RIM <i>lt.</i>	1	2010.70	850 (sw)	2010.70
ROCKER PANEL RH <i>Dented</i>	1	508.00	✓	508.00
ROCKER PANEL RH MOULDING <i>delnd</i>	1	268.70	✓	268.70

*** This is a computer-generated document which requires no signature.***

page 2

546370

S.N: 850

409777

51 AUTOMOTIVE PTE LTD

Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 90686405

ESTIMATE

Repair Code : CLM16162

Date in : 25/03/2020

Vehicle Num. : SLG6630M

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104558556/1ZRY334249

				Subtotal before discount	11,016.40
				Percentage discount 25%	2,754.10
				Sub-total 1	8,262.30
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00			50.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00			50.00
				Subtotal before discount	100.00
				Percentage discount 0%	0.00
				Sub-total 2	100.00
				Parts-total	8,362.30

LABOUR

- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

60 140.00
160 200.00
1000 1,200.00
1000 1,600.00
60 100.00

2280

Labour Total

3,240.00

Parts & Labour Total

11,602.30

total 7257.77
h/s 5.8k

Adrian G
h/s 26/03/20.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature. ***

Acknowledged by Repairer

Signature:

Date:

5.8k

07 Days.