

AB AUTO SERVICES PTE LTD
 100, KADUT ST 1 SINGAPORE 729346
 TEL NO. 6287 6666 FAX NO. 6366 8862
 GST REG NO. 201019626G
 HC 5375A - AIG

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC 5
 VF1AB
 RENA
 LATITU
 18.12.
 AIG

0 * C
 759 * 25 +
 0 * =
 759 * 25 *

759 * 25 x
 90 * %
 683 * 325 *

0 * C

200 * +

20 * +

220 * =

440 * *

PART

1	1	BUMPER COVER FRT
2	1	BUMPER BEAM FRT
3	1	BUMPER ABSORBER FRT
4	1	BUMPER RETAINER FRT RH
5	1	BUMPER SUPPORT FRT RH
6	1	BUMPER SPOILER FRT
7	1	HEADLAMP RH
8	1	FENDER PANEL FRT RH
9	1	FENDER WHEELARCH FRT RH
10	1	WIPER RESERVOIR
11	1	WIPER RESERVOIR MOTOR

\$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$

81/2 \$ 1,123 * 33 *

739.25

502.46 x

89.44 x

144.67 x

76.48 x

TOTAL	\$	3,447.45
10%	\$	344.75
	\$	3,102.71

Specical Nett

1	1SET	FRONT BUMPER CLIP
2	1SET	WHEELARCH CLIP (Necessary)LH
3	1SET	WHEELARCH CLIP (Necessary)RH

\$
 \$
 \$

66.00 x
 66.00 x
 66.00 x

TOTAL	\$	198.00
-------	----	--------

TOTAL PARTS	\$	3,300.71
-------------	----	----------

Panel beating, knocking and straightening
 the necessary portion, remove and
 renewal of parts, adjust and realign the
 same

\$

840.00 20

To Check Electrical Lighting Concerned.

\$

170.00 20