

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Mohd Yusaini Bin Hamid

Accident Date : 23-Mar-20

Vehicle No : FBC110B

Vehicle Model : YAMAHA
YBR125

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Bearing cone	\$ 45.00 ✓
1	Front fork assy (1 set) Local Repair	\$ 180.00 ✓
1	Fork under bracket	\$ 100.00 X
1	Head lamp assy	\$ 65.00 ✓
1	Front signal - L/H	\$ 18.00 ✓
1	Handle bar	\$ 30.00 ✓
1	Mirror - L/H	\$ 25.00 ✓
1	Clutch lever	\$ 15.00 ✓
1	Front fairing	\$ 55.00 ✓
1	Wind screen	\$ 22.00 X
1	Front fender	\$ 35.00 ✓
1	Balancer - L/H	\$ 12.00 ✓
1	Front brake disc	\$ 55.00 X
1	Rider foot rest bracket	\$ 75.00 ✓
1	Rider foot rest rubber	\$ 10.00 ✓
1	Gear pedal	\$ 35.00 X
1	Pillion foot rest - L/H	\$ 18.00 X
1	Pillion foot rest bracket - L/H	\$ 45.00 X
1	Rear box	\$ 250.00 / 250.00 ✓
1	Front rim	\$ 190.00 X
1	Front rim shaft	\$ 30.00 X
		\$ 1,310.00
	Less 10%	\$ 131.00
		\$ 1,179.00

S/No.	Labour
1	To provide towing service
2	To provide labour

\$ 55.00 35
\$ 380.00 250
\$ 435.00

\$ 1,614.00

Dollars: One Thousand Six Hundred and Fourteen only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey (and/or repair) the vehicle
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1- 385
102
346.50
901.50
171