

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBB1219X200319

Estimate**Customer**

Name: MS First Capital Insurance Limited

Address: Motor Claims Department

36 Robinson Road #16-01

City House

Singapore 068877

Date: 24-03-20

Vehicle No: GBB1219X

Model/Make: Toyota Hiace

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate	\$ 1,850.00	
2	Tailgate Rubber	\$ 387.90	X
3	Tailgate Lock	\$ 359.00	X
4	Number Plate Outer Garnish	\$ 346.50	X
5	Tailgate Inner Trim Board	\$ 165.30	X
6	Tailgate Inner Trim Board Clips 1 set	\$ 50.00	X
7	Tailgate "Toyota Logo" Motif	\$ 70.50	
8	Tailgate "70 KM/H" Sticker	\$ 15.00	SN 105.~
9	Number Plate (Metal Plate)	\$ 35.00	SN X
10	Tail Lamp Rh	\$ 365.10	
11	Corner Panel Rh	\$ 165.80	X
12	Corner Panel Garnish Bracket	\$ 31.50	X
13	Tailgate Windscreen Moulding	\$ 285.90	X
14	Tailgate Windscreen Sealant	\$ 45.00	405.~
15	Bumper	\$ 496.50	
16	Bumper Clips 1 set	\$ 48.00	
17	Bumper Bracket	\$ 404.00	
18	Bumper Reverse Sensor	\$ 220.00	SN 2005.~
19	End Panel Inner	\$ 936.20	
20	End Panel Outer	\$ 566.10	
21	End Panel Sealant	\$ 50.00	SN X
22	Spare Tyre Carrier	\$ 250.60	
23	Exhaust Pipe	\$ 971.10	X
24	Exhaust Pipe Mounting 02 pcs (@ S\$42.50)	\$ 85.00	X
25	"Company Advertisement" Sticker	\$ 350.00	SN 1505.~
	Remove and refix rear Bumper distance sensor	\$ 90.00	50
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	60
	To check all wiring & electrical component for proper function	\$ 80.00	20
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 200.00	nix
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,000.00	800
	To putty & spray painting & including touch up paint on accident affect	\$ 800.00	700
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 100.00	60
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 11,020.00

Total amount in Lump Sum Basis for repaired vehicle

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
after
meas
2/s 4700
5 days.



M/s Liu's Brother Auto Engrg Wks

P-4951
252
3713-25
5928-25
4738