

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 34182

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0335/2020/NS
Date : 26-Mar-20

Guide.
\$ 1992.40

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : **SKC 8415 M**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tham Leong James (Tan Liang)
Address : 81 Pasir Ris Grove
 #10-45
 Singapore 518210
Telephone : (HP) +65 96914753
Type of Claim : Third Party Claims
Policy No. : 1900148114
Vehicle No : **SMN 7880 C**
Model Code : Audi Q2 1.0 TFSI S Tronic
Model / Year : 28/8/2019
Engine No : CHZ C32348
Chassis No : WAUZZZGA2KA079147
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Mar-20
Place of Accident : 9 Mohd Sultan Road

Premium Automobiles

55 Libi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMN 7880 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00 500	
3	To respray rear bumper.	\$ 1,000.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,672.00</u>	

Carv 16/04/13

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 5366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7880 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Regis</i>	\$ 1,108.00	X
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 73.00	+
3	REAR BUMPER SPOILER <i>del</i>	\$ 268.00	✓ 214.40
4	REAR LIGHT REFLECTOR - RH <i>new</i>	\$ 28.00	+
5	REAR BUMPER CARRIER <i>new</i>	\$ 517.00	+
6	REAR BUMPER HOLDING STRAP - LH / RH <i>new</i> 2	\$ 24.00	+
7	REAR PARKING AID SENSOR - OUTER 2	TBC	+
8	REAR PARKING AID SEAL RING <i>new</i> 4	\$ 14.00	+
9	REAR WHEEL COVER - LH / RH <i>new</i> 2	\$ 320.00	✓ 256.00
10	SUNDRIES <i>new</i>	\$ 200.00	✓
TOTAL SPARE PARTS CHARGES		: \$ 2,552.00	
TOTAL LABOUR CHARGES		: \$ 2,672.00	
GRAND TOTAL		: \$ 5,224.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan
Surveyed Date : 26/03/20.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant